
AVRO LANCASTER



1941 onwards (all marks)

Owners' Workshop Manual



An insight into owning, restoring, servicing and flying Britain's legendary World War II bomber

AVRO LANCASTER



1941 onwards (all marks)

© Haynes Publishing 2008

Jarrod Cotter and Paul Blackah have asserted their right to be identified as the authors of this work

All rights reserved. No part of this publication may be reproduced or stored in a retrieval system or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without prior permission in writing from Haynes Publishing

Published in April 2008

A catalogue record for this book is available from the British Library

ISBN 978 1 84425 463 7

Library of Congress control no. 2007943094

Published by Haynes Publishing, Sparkford, Yeovil, Somerset BA22 7JJ, UK Tel: 01963 442030 Fax: 01963 440001

Int. tel: +44 1963 442030 Int. fax: +44 1963 440001

E-mail: sales@haynes.co.uk Website: www.haynes.co.uk

Haynes North America Inc. 861 Lawrence Drive, Newbury Park, California 91320, USA

Printed and bound in Great Britain by J. H. Haynes & Co. Ltd, Sparkford

WARNING

While every attempt has been made throughout this book to emphasise the safety aspects of working on, restoring and flying a Lancaster, the authors and publishers accept no liability whatsoever for any damage, injury or loss resulting from the use of this book.

Acknowledgements

Gathering the material for this manual would have been impossible without the enthusiastic support of so many within the world of active Lancaster preservation:

Battle of Britain Memorial Flight – OC BBMF Squadron Leader Al Pinner MBE, Flight Lieutenant Ed Straw, BBMF 'Bomber Leader' Squadron Leader Stuart Reid, BBMF 'Navigation Leader' Squadron Leader Jeff Hesketh, Flight Engineer Squadron Leader Ian Morton, Flight Lieutenant Jack Hawkins, Warrant Officer Dick Harmer, Public Relations Officer Jeanette O'Connell, Jim Stewart and Di Holland.

RAF Museum London – Development Manager Rebecca Dalley for her valued assistance in supplying photographs and posters from the museum's collection.

Aeroplane Monthly for kind permission to reproduce the cutaway drawing of the Lancaster that appears on the cover and on pp38-9.

Lincolnshire Aviation Heritage Centre – Fred Panton MBE, Harold Panton, Ian Hickling, Andrew Panton and Mark Fletcher.

Canadian Warplane Heritage Museum – Don Schofield; Mark Watt and Doug Fisher of Warbird Depot (www. warbirddepot.com) for kindly supplying pictures of the Canadian Lancaster.

Haynes Publishing – Jonathan Falconer, Steve Rendle and James Robertson for their patience with the authors throughout the production process of this book – it is important to remember that without them what you see before you would not exist!

Also much appreciation goes to Bruce Irvine of Classic Aircraft Maintenance for words and pictures appertaining to PA474's latest major overhaul, and to Dale and Andrea Featherby for the beautiful air-to-air photograph of it in its current *Phantom of the Ruhr* paint scheme.

And last, but by no means least, Louise Blackah, who worked tirelessly to assist with the preparation of the technical content and made sure Paul kept on track with this project when he wasn't 'fixing' the Lancaster; and Clare Cotter, who typed up manuscripts when her husband was away looking at aeroplanes.

To all of these contributors, the authors sincerely offer their grateful thanks.


COVER CUTAWAY: Avro Lancaster BI by J. H. Clark ARAeS (courtesy of Aeroplane Monthly/www.aeroplanemonthly.com)

AVRO LANCASTER




1941 onwards (all marks)

Owners' Workshop Manual



An insight into owning, restoring, servicing and flying Britain's legendary World War II bomber

Jarrod Cotter and Paul Blackah







80 The o	wner's view	
Purchasing an a is hardly likely!	irworthy Lancaster	82
The Canadian viewpoint		86
Insurance and ru	unning costs	89





Pre-flight checks	92
Introduction	93
Start-up	93
Take-off	98
Display flying a Lancaster	98
PA474 flight test schedule	112
Emergency equipment and controls	115
Navigating the Lancaster	119
The flight engineer's duties	126

Introduction	131
Servicing a Lancaster	134 141
Heroes without wings	
From Mickey to the Phantom	143

Appendix 1 – Part numbers	153
Dimensions and weights	153
PA474 avionics	153
PA474 general limitations	154
	5000

	PA474 engine limitations	154
Appendix 2 -	Surviving Lancasters	155
Appendix 3 -	Glossary and abbreviations	156
Appendix 4 -	Useful addresses	157





Introduction

Over the years the Lancaster has won the hearts and souls of so many. From the Bomber Command aircrew that it brought home from dangerous operations over occupied enemy territory, to the airshowgoer who avidly gazes up as its unmistakable black shape flies gracefully across the peaceful skies that it helped secure.

That the Lancaster was born to wreak havoc on a distant enemy might be a disturbing thought to younger generations who, perhaps, see it as just a beautiful old aeroplane, 'harmless' even. But there is no mistaking that the 'Lanc' was in the thick of the fight during World War Two, playing a significant part in winning the freedom that we enjoy today.




RIGHT The Lancaster's shape is unmistakable. and as PA474 travels to and from scheduled appearances each year it is seen by millions the length and breadth of the United Kingdom. (Jarrod Cotter)

OPPOSITE Night was the natural environment of the wartime Lancaster, so the rare sight of one in darkness nowadays always evokes a feeling of pre-'ops' tension. as though a crew were about to board for a sortie to some distant target, perhaps never to return, (Chris Elcock) Crown Copyright)

f asked to name a Royal Air Force bomber from World War Two, most people in the UK would immediately answer 'Lancaster'. Avro's mighty four-engined workhorse gained its iconic status for numerous reasons. It was able to carry out its intended job efficiently, it was reliable, and it offered many advantages over its predecessors in Bomber Command. All of this combined to give Lancaster aircrews a better chance of making it home.





years they have been able to enjoy looking at it as the beautiful aeroplane that it is - thanks to the fact that it got them back from the severe

of the United Kingdom admire and know of the Lancaster, as we are lucky enough to be living where one of only two airworthy examples in



The Battle of Britain Memorial Flight Lancaster: why PA474 was used as the main source of material for this book

type in the world. As well as being restored to authentic wartime configuration (with the exception of its dual controls), the fact that occupied Europe, and flies all over our island each summer providing millions of people with the chance to experience its

operated and maintained in accordance with military regulations and procedures – which makes it the ideal principal source of material for this manual. While there is no question that the other superbly maintained exhibits, the prospect of taking one of them to pieces for a book such as this is utterly beyond practicality. parts. Many of these photographs were especially taken to provide readers with a wonderful and unprecedented insight into how a

ABOVE RIGHT PA474 wears the 550 Squadron BQ-B code to starboard, representing the unit with which Phantom of the Ruhr went on to become a 'Centurion'. completing a total of 121 operations. (Crown Copyright)

OPPOSITE Dedicated to the more than 55,000 Bomber Command personnel who never made it home to see the next morning's sunrise... (Jarrod Cotter)


the world takes to the skies on a regular basis between April and September, courtesy of the Battle of Britain Memorial Flight based at RAF Coningsby in Lincolnshire. During World War Two Lincolnshire was known as 'Bomber County' on account of the number of bomber bases there. Lancaster Mark I PA474 pays a 'living' tribute

to the more than 55,000 Bomber Command personnel who didn't make it home, and to their comrades who survived the war but have had to live with their memories for the rest of their lives. Thus, each time PA474 arrives back in Lincolnshire - whether after a display, or after carrying out a flypast at a village fete or a high-profile State occasion - it symbolises all those lost souls finally making it home. May this continue for many years to come.

There is also a Lancaster maintained in airworthy condition in Canada, a country which has very strong connections with the type. Not only did many Canadians serve with Bomber Command during World War Two, but Lancs were also built in Canada before being flown to England. After the war Lancasters were operated by the Royal Canadian Air Force in various roles too, so it is wholly appropriate that Mark X FM213 still graces the skies of Canada.

PA474's role in the BBMF

he BBMF was originally known as the Historic Aircraft Flight and was a direct result of the efforts of Wing Commander (later Group Captain) Peter Thompson DFC, then Station Commander at Biggin Hill, Kent. After gaining his wings in the summer of 1940, Peter flew Hurricanes during the Battle of Britain.





After the war the powers-that-be determined that Battle of Britain Day should be on 15 September, as in 1940 that date had marked the height of the aerial conflict. And so it was that in 1945 thousands gathered in London to watch masses of RAF fighters carry

flypast over the capital. In the years immediately following World War Two it became traditional for a Hurricane and a Spitfire to lead the flypast.

With the passing of time, aircraft that were

with the passing or time, arcraft that were once the mainstay of RAF fighter operations decreased in numbers and gradually the jet age took over. The familiar and much-loved pistonengined types were rapidly withdrawn from frontline service.

By the mid-1950s Hurricane II LF383 was the only airworthy representative of its type with the RAF, and at that time was based at Bliggin Hill. When the Spittire was finally phased out of RAF service in 1957 the only three remaining airworthy examples were those being flown by the civilian-operated THJM (Temperature and Humidty) Flight at Woodvale, Lancs.

There was a strong belief among some in the RAF that the service's greatest Battle Honour (Battle of Britain) should continue to be commemorated in a fitting fashion — and the best way to do that was to keep these lagendary fighters in the air. Wing Commander Thompson was are enthusiastic advocate of this notion and with L7936 already at Biggin. he had the basis for a grander plan, Peter gained the



authority to form a commemorative unit, but no public funding for maintenance or fuel would be forthcoming and all manpower would have to be on a voluntary basis.

With their useful operational curears over, the three Spatitie PR XXS of the THUM Flight – PM631, PS835 and PS815 – were allocated to the unit. They were scheduled to be delivered to Loudord, Cambridgeshire, on 12 June 1957, but PS915 proved unserviceable and PS858 ended up on its nose during take-off. Nevertheless, over the next few weeks all three arrived and awared their PRF clicks.

From Duxford, a three-Spit formation eventually flew to Biggin on 11 July, ploted by legendary wartine ace Group Captain J.E. Johnnie' Johnson in PS853, Group Captain James Rankin in PM631 and Wing Commander Peter Thompson in PS915.

What was then known as the Historic Aircraft Flight (or HAP) was formed at Biggin Hill on 11 July 1987. However, while the concept had come to fullion there was a consensus among warrine pilots that it was not right to form a tribute flight to the Battie of Britain using a varient of the Spliffer that was not designed to fire guns. The solution came in the form of three Minr XVII (1823). T474 and SL574, recently brought out of storage for a ground display at the 1987 Poul Tournament. The Senior Technical Officer at Biggin, Squadron Leader E.H. Sowden, recommended that priority be given to bringing these up to flying condition. This was partly because they were fighters, but also because spares were more readily available than for the PR XVs.

Peter Thompson air-tested TE330 at Biggin early in September 1957, It performed faultlessly and was taxied across to the Station Flight hangar where it joined up with LF363. On 15 September, HAF carried out its first commemorative flight over Westminster Abbey for Battle of Britain Day, using LF363 and TE330. By that time the Flight had already lost one of its PR XIXs, PS915 had not been in the best of health when it arrived at Biggin Hill on 11 July, so it was retired from flying fairly promptly. Peter flew it to West Malling on 8 August, where it became a gate guardian. Two months later, on 10 December 1957, TE476 was successfully air-tested

In February 1958 Peter was posted to the USA and promoted to Group Captain. He had always referred to the HAF as the 'BoB Flight' and on 21 February it was officially renamed as the Battle of Britain Flight. Work continued steadtly and on the 23rd SL574 took to the skies. However, in the same month it was announced that Bigain was to close and the OPPOSITE TOP On 7 November 1967, PA474 starts up at Waddington ready for its first air test after restoration to flying condition. It was to join the BBMF six years later. (Crown Copyright)

OPPOSITE BOTTOM
Group Captain Arthur
Griffiths Are, Station
Commander at
Waddington, carrying
out a pre-flight walkaround check of PA474
at Waddington in 1967.
He was responsible for
its return to the air on
a regular basis.
(Crown Copyright)

BELOW Two classic RAF bombers from Avro – Lancaster I PA474 and Vulcan B2 XL317. (Crown Copyright)





ABOVE Bearing the name and arms of the City of Lincoln, it's always a special sight to see PA474 flying over Lincoln cathedral – which during the war would have been a welcome landmark to many returning Bomber Command crews.

(Crown Copyright)

Flight was informed it would move to North Weald in Essex by March 1958.

That April the BoB Flight tost a second PFIXX, as PSBS was allocated to West Raynham, Norfolk, where it was placed on display at the gate, in the following month it was dealt yet another blow, and one that must have been externely intesting—despite the existence of many non-airworthy Sptiffes around the UK. The Flight's principle tyer, TESQ) was taken away on 14 May to be prepared for presentation to the USAF Academy at Colonado Springe.

Things were going from bad to worse. In May 1958 North Weald closed, so that after a very brief stay there the BoB Flight was again in need of a new home. It moved to Martlesham Heath in Suffolk shortly afterwards, where it remained for three years.

It was here, during 1959, that the Flight lost its remaining Spitfire XVIs due to a series of accidents and reliability problems. On 28 May SL574 suffered a flying incident at Martlesham and was sent for repair to 71 Maintenance Unit at Biseste, Oxfordshire, returning on 1 July. Then on 10 September TE476 had a wheels-up landing, As a result, the "Top Brass' docread that 20 September 1959 would be the last time the 15th September 1959 would be the last time the 15th September 1959 would be the last time the 15th September 1959 would be the 15th September 10 participate in the Battle of Britain Pipast Over London. This declaion was perhaps windcated when SL574 suffered a complete engine failure during that very sortie over the capital and crashlanded on an orderic ground at Borning.

In November 1961 the BoB Flight undertook another move, to Horsham St Faith in Norfolk. By this time it comprised just LF363 and PR XIX PM631, and this is how things would remain until 1964.

Continuing what could almost have been seen as a jinx, it transpired that Horsham in turn had been earmarked for closure, and on 1 April 1963 the Flight made its way to nearby Cottishall. After all these knock-backs, surely the BoB Flight was due some better luck?

Coltishall offered just such a chance and things began to improve significantly, PS853

was made serviceable again and out on charge of the Central Fighter Establishment on 31 October 1962. In April 1964 it was returned to the Flight. Then in September 1965 another Snitfire inited the ranks when Vickers-Armstrona narted with Mark VR AR910. This brought the Flight's inventory back up to four and with the fleet and its popularity growing things were put on a more formal footing at Coltishall, resulting in the appointment of a team of full-time engineers.

Another significant acquisition occurred after filming for the 1969 classic movie Battle of Britain ended, when the Flight was presented with Spitfire IIA P7350 - the world's oldest airworthy example and a genuine combat veteran of the Battle of Britain.

Having popularly become known as the Battle of Britain Memorial Flight, the unit officially took this name on 1 June 1969.

Another major milestone came in March 1972 when Hurricane IIC PZ865 was presented to the BBMF after being refurbished by Hawker Siddeley. This aircraft had been the very last off the production line and hence carried the legend The Last of the Many! on its sides.

November 1973 saw the arrival of a new and significant wartime aircraft, which would

widen the tribute paid by the BBMF to include Bomber Command as well as Fighter Command. On the 20th Lancaster I PA474 was officially transferred from Waddington, Lincs, where it had been refurbished and looked after by station personnel. It had been making a growing number of annearances around and about, and station resources were strucialing to keep page with the demand. The best option, it was realised, was to place PA474 under the care of the BBME which was better equipped with the necessary expertise and infrastructure to maintain it. However, the name of the BBMF remained unchanged and continued to reflect its dedication to the RAE's

most famous Battle Honour Less than two years after the Lancaster arrived at Coltishall it was announced that the BBMF was moving to Coningsby in Lincolnshire, in order to free up its hangar space, and on 1 March 1976 the Flight began to ferry its aircraft to their new home. Though the BBMF had arrived at 'Colt' with just two wartime-era aircraft, it left with seven - including what was then the world's only airworthy Lancaster. Their arrival at Coningsby delighted the folk of Lincolnshire - often nicknamed 'Bomber County' - as they'd always had a

BELOW PA474 with a BBMF fighter escort of two Spitfires and a Hurricane. (Crown Copyright)









soft snot for their beloved Lancaster and had campaigned tirelessly to get it back.

The Flight's aircrew continues to comprise volunteers, who these days perform their primary duties working on front-line types such as the Eurofighter Typhoon and Boeing E-3D Sentry. The only exception is the BBMF's Officer Commanding, which is a full-time appointment owing to the additional demands of overseeing operations, administration and engineering.

For many years after its formation the Flight carried out relatively low-key operations, generally performing around 50 to 60 displays. a year until the mid-1960s. Thereafter this figure gradually increased as the BBMF's popularity grew, and nowadays it's considered 'the norm' for between 700 and 800 individual appearances to be planned on the ops board. The BBMF has grown to become a major link between the RAF and the British public. and every year its aircraft are seen by around six million people. Since 1986 the Flight has even been made available to the public during weekdays - an amazing gesture of goodwill by the BAE. The BBMF Visitors' Centre features. displays and a well-stocked shop, and for a nominal fee people can even go on a guided tour of the hangar.

As for the brave individuals who paid the ultimate price flying such aircraft to preserve our freedom, their sacrifice is honoured by the BBMF's motto... 'Lest We Forget'.

ABOVE Something which makes the BBMF even more of a priceless national asset is that it is not hidden away from the public, Each weekday visitors can pay a nominal fee to go on a guided tour of the Flight's hangar. In the winter they get to see the aircraft undergoing servicing such as this. while in the summer they may be lucky enough for their visit to coincide with aircraft starting up for a sortie.

LEFT For the Flight's 50th anniversary. PA474 led all seven BBMF fighters for one, possibly never-to-be-repeated flypast at Duxford on 5 May 2007. (Jarrod Cotter)

(Jarrod Cotter)

Restoring PA474

A474 was built as a BI by Vickers-Amstrong at Hewardsen, North Welse, in 1945. Initially it was earmarked for "Tiger Force" operations and, consequently, service in the Far East, soil twas manufactured to FE standardss. However, the war with Japan ended before it could take part in hostifiles, Instead at went into storage at 38 Maintenance Unit, Llandow, South Welse, on 18 August 1945. It was next moved to 32 Maintenance Unit at St Athan, also in South Welse, on 26 November 1940.

After this period in storage PA474 was converted to PR1 configuration by Armstrong Whitworth, with work beginning on 28 June 1947. The conversion included the removal of the Lancaster's turrets. The former bomber was ferried back to Llandow on 11 August and temporarily loadend back into Storage.

On 23 September 1948, PA474 at last entered service with the RAF when it was assigned to 'B' Flight of No 82 Squadron for photographic reconnaissance duties in East and South Africa. After joining the squadron at Berson, Oxfordshie, it was given the identification letter "M", and spent the next four years carrying out survey work. This saw PA474 taken on many detachments to emall airfields with relatively primitive facilities before it finally returned to Benson on 18 February 1952 to await a fairly uncertain future.

The borne's long-term fate became even more doubtful when, from 26 May 1962, it was loaned to Fight Refueling Ltd at Tarrarth Rushton, Dorset, with the intention of converting it not a picless drom. Much design work followed while PA474 languished somewhat forgotten at Tarrart Rushton. However, before the proposed work began the Ar Ministry decided to use an Arvo Lincoh instead.

So on 7 March 1954 PA474 was transferred to the College of Aeronautics at Cranfield, Bedfordshire, where it was to be used for trials with several experimental aerofol sections. This new career effectively saved an airvorthy Lancaster for the nation. The trial wing sections were mounted vertically on the upper rear



BELOW PA474 in

College of Aeronautics

while on laminar wing

flow tests, (College of

service with the





ABOVE PA474 minus propellers, parked outside Hangar 4 at Waddington on 9 June 1971. (Crown Copyright)

LEFT A happy scene at Waddington on 7 November 1967 after PA474's first postrestoration test flight.

restoration test fli (Crown Copyright) fuselage of the aircraft, which at the time was still wearing its No 82 Squadron badges and individual 'M' code.

PA474 was employed in this role until 1984, by which time the College of Aeronautics had completed the conversion of Linchol B2 G-39-3 the former FF542(1) oraplace it. During October 1963 the FAF had talked to the College about taking PA474 back with a view could be conversed to the college of the conversion of Museum, and on 22 April 1964 it was ferried to 15 Meintenance with at Wesupton, Wilshire, and placed into storage. The first steps towards PA747 becoming a permanent flying memorial to Bornber Command had successfully hear taken.

The aircraft was adopted by the Air Historical

Branch with the intention of it being included

in the new museum. It was soon painted in

more fitting wartime camouflage, though

without any squadron markings, and on

BELOW PA474 on 6 November 1974, partway through a Major overhaul at Kemble. Henlow, Bedfordshire, to be prepared for the RAF Museum.

The first unit to be equipped with Lancasters had been Not 48 (Phodesial Squadnon, and in 1968 Wing Commander MA. D'Arcy, the Commanding Officer of No. 41 (by their flying Avir Wilcares from RAF Waddington in Liconohinity out in a request to the Ministry of Deliroo that PALTA be transferred to his squadnon's care. Approval being eventually obtained, a party of ground crew left for Henicky on 12 Mey 1963.

On close inspection PAZT4 appeared to be alworthy, so a further request was ant to the MoD asking that it be flown to Waddington. After due consideration this request to was granted, and on 26 July a team of experienced technicians from Waddington state to was granted, and on 26 July a team of experienced technicians from Waddington states to was a "recovery servicing". This included undercarriage or "recovery servicing", This included undercarriage swing, shing control checks, electrical and institutional variety of the control of the cont



checks. Despite having stood out in the open for 12 months, the only servicing required on the Merlins was the clearing out of birds' nests from the cowlings, spark plug cleaning, and fuel and oil checks! The engines started easily.


After PA474 was declared fully serviceable the aircrew arrived on 18 August for what was supposed to be its last flight, to Waddington. At 10:30am the crew climbed aboard and the preflight checks were carried out.

One by one the Merlins burst into life, chocks were drawn away, and PA474 taxied across the rough grass field to the take-off point. A fair-sized crowd had gathered to watch the proceedings, and they were rewarded by the evocative sight of the Lancaster slowly gathering speed and rising off the ground. Its departure caused much surprise around Henlow, where it had been regarded as a mere museum relic, and never expected to fly. so there was hardly a door or window on the



LEFT A major milestone in PA474's restoration to authentic wartime configuration was the fitting of a mid-upper turret, seen here being lowered into position during 1976 under the guidance of Pete 'Gerbs' Jeffery and Engineering Officer Flight Lieutenant Terry Lees. (Crown Copyright)

BELOW RAF engineers hard at work about to remove the nose section of PA474 at Abingdon, circa





ABOVE Again seen at Abingdon in 1983, the Lancaster's rear fuselage has been separated from the centre section. Note that at the time it was wearing the AJ-G markings of Wing Commander Guy Gibson's ED932 from the famous 'Dam Busters' raid. (Crown Copyright)

PA474 flew over! It made for Waddington in the company of a Varsity that had been provided for the press and television crews.

At Lincoln the Lancaster made several runs past the Cathedras on that the photographers could first a with that landmark in the background. The Varsity then flew on to land at Waddington first so that the photographers could position themselves to film the Lancaster's arrival. Meanwhile, it made two low, feat runs down Scampton's main runway before landmar at Waddington at 1's 30cm.

After being put into storage in one of Waddington's language it was decided to repaint the Lancaster in the markings of Squadron Leader J.D. Nettletton's KM-B, in which he seared his Viction Cross whitst carrying out the famous low-level daylight raid on the MM factory at Augsburg on 17 April 1942. The markings were those of No 44 Squadron Lancaster IRSSO.

A restoration programme then began that would continue for many years. By 1966 work was progressing well and both the front and mer turrets were in place. However, the Lancaster was intelligh intended to be only a static exhibit, as its return to the air would require overcoming many difficulties. Instead it abod on display outside the Officers' Mess – until Group Captain Arthur Griffiths avc, Waddingtion'S Station Commander since April 1967, saw it and asked why it wasn't being from. Group Captain Griffiths was a true flyer who simply loved aeroplanes, and he just couldn't bear to see PAP47 looking forforn and unwanted. He decided to attempt making the Lancaster airworthy again, and to get the necessary permission to fly it. The project was supported by HO I Group,

but foundered initially with the McD from whom financial approval was allow in coming. What finally carried the day was the forthcoming 50th arriversary of Waddington in November 1967. The celebrations were to culminate with a quest right in the Offices' Mess, to which Christ of Defence Staff MRAF Sir Charles or Christ of Defence Staff MRAF Sir Charles of the disciplinate of purchased to the professional control of the other destinguished quests had been initiated. The plan was to get the Lancaster airborne before this date.

On 6 November permission for one air test finally arrived. After an hour's circuit work in a borrowed Hastings on 7 November to refamiliarise himself with such neculiarities as propellers, flaps and tailwheels. Waddington's Station Commander went to the Lancaster. started up the 'four lovely Merlins' and taxied out. He pushed the throttles open and away they went, with no problems at all. The aircraft flew beautifully and was obviously delighted to

be back in the air after so many years. The flight was well received in higher headquarters and the Lancaster was subsequently allowed to fly on further occasional test flights. Nevertheless, there were still to be difficulties from time to time. Propeller oil leaks were a problem until some appropriate seals were obtained from Hong Kong. Feathering motors appeared unobtainable until MoD Harrogate bought a couple from a local scrap dealer. On one occasion, a double plug failure caused such vibration that the Lancaster's No 4 engine had to be shut down, necessitating the pilot's first three-pistonengined landing for 20 years! But by and large PA474 continued to fly beautifully, and the only real problem lay in gaining financial authority to fly it regularly. Gradually, as the aircraft continued to give little trouble and gained in popularity, opposition decreased and the Waddington Lancaster was invited increasingly to air shows throughout England, where it was

always the star attraction. Restoration work to bring the bomber up to the desired condition to accurately represent a wartime Lanc went on. PA474 joined the BBMF in November 1973 and in 1975 it was adopted by the City of Lincoln, the name and coat of arms of which it still proudly wears more than 30 years later. When the BBMF moved to its current home at RAF Coningsby, Lincolnshire, in 1976 restoration work was still going on, and a mid-upper turret that had been discovered in Argentina, of all places, was finally fitted the same year. Even today work continues to get PA474 into an even more authentic wartime condition, the latest items being considered for addition being flame dampers over the exhaust shrouds.

The only Lancaster to be re-sparred

relatively short, so there had been no need to consider that one might even need replacement wing agains. AAT4, By the end might even need replacement wing agains.

A tetague mater had been fitted on board PA74, By the other had been greater than the bomber had declocked up 3,060 hours, leaving 1,340 hours or about 13 years remaining, based on its usage of that time. In 1949 British Aerospace (BA4), determined the fatigue index to be 70.7, where an index of 100 inclustes no fatigue life remaining. A decision that the sper booms would eventually need to be replaced was made in 1990, and EAA was tasked to define the repair.

The intention of the repair deeping was to replicate as much be the historic converged of the Lancaster as possible. This included the use of a unique method of the lower to the them.

use of a unique method of attaching the skins to the boom on the cutter wings, known as plug inveling. However, the major could not in any way compromise modern-day design practices and fatigue enhancement measures.

The new booms were to be manufactured from extrusions surplus. On the re-sparing programmer of the RATS Any Stackletons. They were to be made without defiling any holes so that the defiling pattern could be object from the existing borne, in addition the repairs were required to include new webs and fasteness and new shackles. A decision was made to keep Pad-74 fing for as long surplus sufficient fatigue life remained available on the original spars, satisfactor fatigue life remained available on the original spars.

sunicein largue the tretained available of the Orginal spars, which had been calculated to expire in 1996. Flying restrictions were imposed to avoid any heavy manoeuvres, and fatigue meter readings were regularly sent to BAn for analysis.

As the booms were the critical components they were wisely

1950 bet forming accepted the contract to carry Oil the re-sporing. After its arrival at St Athan in 1959 PAT4* was separated into its component parts and prepared for transportation. Various sections arrived at Bate in November and were placed in purpose-built holding fixtures to support them during the work. Around 5:000 production hours were spent on the aircraft by both military and civilian engineers, who often worked from 07:300 until 2000, before completed sections were ready to be sent back to St Athan during early February 1961.





Chapter One

The Lancaster Story

The origins of the Lancaster can be traced back to 1936 when the RAF was looking to re-equip with up-to-date monoplane bombers. Air Ministry Specification P.13/36 for a so-called 'medium bomber' formed the basis of the design for Avro's twin-engine Manchester.

However, the genesis of the Lancaster lay in the failure of the Manchester's twin Rolls-Royce Vulture engines. Four Merlins were married to the Manchester airframe and the resulting aircraft was called the Manchester III

- later renamed the Lancaster.

LIEFT Lancaster I R6689 W-N of No 50 Squadron. On the right of 18 september 1982 this aircraft took off from Swinderby, Lincolnshire, on a 'Gardening' sortie to an undisclosed area. It was bady hit and attempted to return, but crash-landed some miles south of its base at Thurby, Lincolnshire, when both port engines failed as the crew prepared for landing. (RPAF Museum)



Lancaster: The story of a bomber

ne of the most revolutionary departures from previous aircraft design practice was the proposed increase in wing loading. This would allow a heavier type of aircraft to be operated from airfields that would most likely have grass or even sandy surfaces. Up to that time the normal wing loadings were in the region of 20lb/ft sq. but the Avro Manchester design called for double that. This caused numerous headaches for the design team, as the engine loading could not be reduced to compensate for the effect of the higher wing loading on the take-off run, and the rate of climb once off the ground, though a degree of compensation was offered by the constant speed variable pitch propeller which was being developed.

After many trials and tribulations with the design, A.V. Roe & Company Limited first flew the Avro 679 Manchester twin-engined medium bomber on 25 July 1939 from Ringway. Manchester. The Manchester was the brainchild of Avro's chief designer Roy Chadwick, and was powered by a pair of Rolls-Royce Vulture engines. By the end of January 1940 some 1.200 Manchesters had been ordered, but only 200 were delivered due to reliability problems with the Vulture and the Manchester's performance. For example, its 'comfortable' operating altitude was between 10,000ft and 15.000ft, leaving it vulnerable to flak which was becoming more and more of a danger. However, one feature of the Manchester which was an indisputable success was its bomb bay.

With the Rolls-Royce Merlin proving to be an excellent engine, and with more powerful marks being planned, it was decided not to waste any time in trying to improve the Vulture. This cancellation left Avro with a superb airframe in need of a reliable power plant.

In February 1940 discussions had taken place regarding a proposed Manchester III powered by four Merlins. There was some initial reluctance about this, as at the time Merlins were desperately needed for Hurricanes and Spitfres. However, in July 1940 there was a change of heart and the Air Ministry informed Avro of their wish that the development of the four-engined Manchester should go ahead.

The Auro 683 was to have the minimum the Auro 683 was to have the minimum of the Auro 684 was to the Auro 684 was the Auro 68

After a number of setibacks Avro got the approval to produce two prototypes by July 1941. The first of these, BT308, was rolled out for engine runs on 28 December 1940. By 4 January 1941 the four-engined Avro 683 was cleared to fly from Woodford. However, due to poor weather – low cloud, drizzle and fog – it was temporarily orounded.

By 9 January the weather had improved sufficiently for BT308 to take to the skies – and the Lancaster legend was born! While the aircraft was still widely known as the Manchester III it was annotated as a "Lancaster" on Its Air Ministry Form 1187 Design Certificate for Flight Trials.

BT308 intitally featured the triple in design of the Manchester. However, following early handing trials it was suggested that the aircraft be fitted with larger twin firs and the central fin be removed. It was fest flown in this form on 21 February 1941, and such was the improvement that on its second test flight BT308 was flown with both port engines shut down – proving that the larger rudders could keep the bomber fifting straight.

The second prototype, DGS95, carried out its maiden fight or 13 May 1941, and it quickly received authorisation to go for service trials. Though there were delays. Roy Chedwick used the time visely and set about improving a number of areas he had already identified as needing attention, as well as inflating a complete review of the aircraft and its systems. With Mainchester production now cased, the Lancaster was approved and the balance of orders was changed to the new four-engined bomber. The first production machine, L7827, few on 31 Otobor 1941.

L7527 differed from the prototypes in that it had four 1,280hp Merlin XXs rather than 1,145hp Merlin Xs. The aircraft's performance

OPPOSITE TOP
The Lancaster was
developed from
the twin-engined
Manchester, which
was basically a good
airframe in need of
better engines than
the Vultures with
which it was equipped.
This is L7247, seen in
June 1941. (Art Ministry)

OPPOSITE MIDDLE BT308 was the first Lancaster prototype and represents the legendary bomber in its earliest form, with small outer tail fins and a centre fin. (Rolls-Royce)

OPPOSITE BOTTOM DG595, the second prototype Lancaster. (Air Ministry)



ABOVE A staggering 500,000 manufacturing processes were involved in building a Lancaster, which was made up of some 55,000 separate parts – even when you count engines and turrets as one item and exclude all the rivets, nuts and

bolts! (RAF Museum)

was simply outstanding; large-scale production soon began at several factories and plans were put in place to get the Lancaster built in Canada too.

The first RAF unit to receive the Lancaster was 44 (Rhodesia) Squadron at Waddington, Lincolnshire. On Christmas Eve 1941 the squadron took delivery of three examples of the type.

Into service

It was not until 3 March 1942 that the Lancaster entered operational service, when four aircraft from No 44 Squadron set off for Heligoland Bight in the North Sea at the mouth of the River Eibe, on a mine-laying sortie. They took off from Waddington at 18:15 and all returned safely around five hours later.

The first night bombing operation with Lancasters took place a week later on 10/11 March, when two 44 Squadron Lancs took part in a raid on Essen. Each of them carried 5,000to of incendiaries and they joined a force of 126 bombers which included Handley Page Hampdens, Manchesters, Short Stirings and Vickers Wellingtons. Lancasters were certainly well received by their crews, and they quickly settled into squadron service, proving themselves to be sound and reliable workhorses.

Many raids by Lancasters would go on to make headline news, the fest of three being the daylight operation by 44 and 67 Squadrons to bornot the MAN Dissell factory at Algaburg in southern Germany on 17 April 1942. Squadron Lader J.D. Nettleron vod 44 Squadron led the 12-aircraft op, for which he became the first of ten Lancaster aircrew to be awarded the Victoria Orios for hier exploits.

Lancasters were in service in time to participate in the first "Thousand Bomber' raid on the night of 30/31 May 1942, codenamed Operation Millennium. Out of a total of 1,047 aircraft that were despatched to Cologne, 868 reached the primary target.

On the clear moonlit night of 16/17 May 1943 the newly formed 617 Squadron successfully carried out what became the most famous single operation in the history of aerial warfare. No 617 Squadron, commanded by Wing Commander Guy Gibson, set out from Scampton in Lincolnshire to breach key dams

OPPOSITE As the light fades a formation of Lancasters sets out for occupied Europe. A few hours later they were probably avoiding flak in the night skies over a heavily defended target. (RAF Museum)

in the industrial heartland of Germany. For the sortie the squadron used a special weapon (codenamed 'Upkeep' and actually termed a mine, but more commonly referred to as the 'bouncing bomb') that had been designed by the famous and highly respected aviation designer Sr. Barnes Wallis.

The Lancasters used for the raid vere BIII (Specials), modified to be able to carry ore mine sach in a specially designed caliper device that could retate it at the 500pm required for it to work successfully. Furthermore, the bomb would need to be dropped from just 60ft, at might, and at a specified speed and exact distance from the dams. To compound things turther, the crews had just seven versels to train for the precision stack as it had to take place within a period inneference.

Nineteen aircraft set out, with sixteen reaching their targets. Operation Chastise was carried out successfully, with the Mohne and Eder Dams both being breached and the Sorpe damaged. Of the sixteen Lancs that reached their targets eight were lost, and only three of their 56 crew members survived to become prisoners of two.

It was for this famous operation that Guy Gibson was awarded the VC, with a total of 34 decorations being awarded for aircrew who participated in Chastise. The post-raid publicity was massive, and proved to be a tremendous PR boost for the RAF.

Stalking the Tirpitz

Another very famous achievement using Lancasters came as a result of the three operations mounted to eink the mighty German battlehip Trpits. Along with 617 Squadron, as the very progressed 9 Squadron also came to specialise in deopring large borths. in particular the 12,000th Tallboy*, on strategic targets—and the ops aimed at destroying the Trpits are a further good example of the Lanc's operational versatility.

In January 1942 Prime Minister Winston Churchill put out a document to the Chiefs of Staff staffing that no other sea target was comparable to the *Tirpitz* – the entire worldwide naval situation would be altered if it could be destrowed, or even crisoled. Although a



number of attempts by various units were made to sink the vessel, it remained serviceable. Consequently and 617 Squadrons were tasked to bomb the *Tripitz* during September 1944 in Operation Paravane. Armed with Tallboys', they were to fly to Vegochis in the Soviet Union so that they would be within range of the German battleship.

A number of aircraft from both squadrons were lost en route to Yagodrik, but the remaining force set out from the Russian artifact on 15 September to bomb the Tripitz in its Norwegan hidring place at Rasilgord. The crucial element of surprise was lost when a German ground unit gave prior notice of the bomber force's direction, and a smoke screen was set up over the ship. Attempts were nevertheless made to bomb the Tripitz, but many of the post-flight reports state that the target was obscured by smoke that made the results difficill it to reference.

Later it was discovered that the Tripitz had indeed been hit by one Tallboy' that had gone through the forward deck and emerged below the waterine on the starboard side before exploding, while a second near miss had caused further damage. These bombs are thought to have been dropped by 9 Squadron's Flight Leutenard J.D. Medon and 617 Squadron's Wing Commander J.B. Talt sign 'pre'". The attack had, however, rendered Tripit, unit to ou to say.

The damage having been patched up by mid-October, the huge vessel was then moved to the port of Tromse, around 200 miles south of its previous location. This new berth potentially put the battleship within range of RAF bases in north-east Scotland, including Lossiemouth.

In order to carry out attacks, however, the Lancasters would have to be heavily modified and fitted with the more powerful Merlin 24s





RELOW While most

stories obviously relate

to the aircrew, they in

turn all testify that the

contribution of their

ground crews was

– but the only ones exaliable were already fitted to their Lancasters scattered throughout. 5 Group. A frantic search located at the Merin 24s and these were then exchanged with the engines fitted to the "fallboy" arrant. Other modifications included removing the mid-uptic. Turnets, pinks amour, gruns and ammunition from the front turnets, and as morting the mid-uptic and interest, pinks amount of ammunition carried in the rear turnet. Extra fuel tanks were then fitted to give the aircraft sufficient range.

More than 120 engines were exchanged over a three-day period – this and all the other modifications had to be carried out on top of routine maintenance and repairs, thus confirming 9 Squadron's unofficial motto: There's always bloody something!

A combined force of 40 Lancasters (20 from 9 Squadron, 19 from 617 Squadron, and PD329 from No 463 Squadron on 'special photographic duties') left their bases for

Scotland on 28 October, and the following day set off for Tromso on Operation Obviate. Heavily laden with extra fuel and weighty 'Tallboys', the aircraft took off at +18 boost rather than the normal +14.

On approach to the target area an unexpected weather fort caused conditions to rapidly deteriorate and bombing was made difficult as the target quickly became obscured by cloud. Some aircraft dropped bombs by targeting the gun flashes they could glimpse through the cloud, but as the force turned for home the crews knew that the Tirptz was still adoat. It was later reported that but the happened just half an hour serier conditions would have been prefect.

would neve been peried.

A third attempt by 9 and 617 Squadrons to bomb the *Tirpitz* was initiated during November. At 03:00 on 12 November 1944 the first of the Lancasters set off from Scotland on Operation Catechism. This time they had perfect weather

BELOW Last RAF sortie by a Lancaster, as MR3 RF325 carries out a flypast at St Mawgan in Cornwall on 15 October 1956. (MOD/Crown Copyright)



conditions all the way to the target, with the clear sky offering excellent visibility.

As the Lancasters neared the battleship they were greated by fish. Dut with their armament delpleted to save weight there was a more service site that the Lancasters might become very easy prey to the Tirpitz's fighter cover. Indeed, ground troops reported the bomber force to be heading towards the vessel and its Captain ordered that the fighters be scrambled, knowing they could be overhead in an mnutes. However, the 18 Focker-Will Fiv190s that got acts test of in the wrong direction – they had apparently not been informed of the battleship's change of anchorage!

Everything was at last in favour of a successful attack. The "Tallboys' rained down on the Tirpitz and after a number of drect hits and near misses the battleship rolled over to port and lay on its side. Huge clouds of black smoke rose into the gin-clear sky. The Lancaster crews' determination to finish off this significant threat had finally paid off.

Final throes of war

An er the "fallboy' came the 22,000b 'Grand Slam', sometimes called the Earthquake bomb'. To carry this the Lancaster had to again be modified, with the huge bombs being slung externally in a doorless bomb bay. The first use of the 'Grand Slam' came on 14 Merch 1945, when the Beilderld Viduct in northern Germany was attacked. The Lancasters capable of carrying 'Grand Slam' became known as 'Capper' aircraft by their crews, because after releasing their heavy payloads the aircraft went like the clappers'!

in the war was the daylight raid to bornb Hiller's Englie's Nest reheat at Benchlespoin. This op to the Barwise Alps was carried out on 25 April 1945, and though Hiller was not in residence at the time it was still considered a success. The same day saw Lancasters take off for the last raid by the type, a right op against an oil target at Tonsberg in Norway on 25/28 April. Lancasters not my made a vial and husely

Lancasters not only made a vital and hugely significant contribution to Bomber Command's night offensive, but they also helped to turn the tide in the major land battles of 1944 by bombing the German army in the field and flying tactical sorties aimed at precision targets. During the war Lancasters carried out around 156,000 sorties and dropped 608,612 tons of bombs.

Before the German surmofer Lancasters were heavy involved in Operation Manna, with saw them supplying much-needed food to staining Dutch people. These sorties were objectively heavened as a large areas of the country were still under German control – though with the war's ent in sight a truce was negotiated and the Lancas were allowed to carry out their vital aid ratel singly, uninicidend. Some 6.684 tons of food were dropped during 2.855 sorties.

Following the end of hostilities in Europe Lancasters were put to use in another passive role, being used to repatriate liberated Alled prisoners of war back to England, this task being codenamed Operation Exodus.

After the war a number of Bomber Command units continued to be equipped with the Lancaster until the type was replaced by the Avro Lincoln. The last bomber unit to operate Lancs, 49 Squadron, converted to Lincolns in March 1950.

With the departure of the land-lease Consolidated Lubertons after the wir the Lancaster became the principal land-based maritime recornalisance alroraft used by Coastal Command. The list example of the type to be operated in service by the RS4-most MRI RF325, without was used by the School of Maritime Reconnaissance at RAF St Mawgarin to Cornwall and was refered on 15 October 1966. Saddy, after a tierevell ceremony it was flown away to Winduckino, Withshire, to be scrapped.

The Lancaster also formally served with some other courties post-war. It served on with the Royal Canadian Air Force for some 20 years are seen. The air force of Agentina and Egypt as see sessor. The air force of Agentina and Egypt also used the Lanc, as did the French Naw, The Sowlet Air Force assertibed two examples from those that had force-landed in Russa during the first of the Typez radis, the Royal Australian Air Force seed not lance on its books, and the Swedsh Air Force used a Lancaster were also used in experimental and development trials, and some were put onto the civilian registers of Pittain and Canadian.



The main production variants

BI – Powered by four Rolls-Royce Merlin XXs, 22s or 24s. Most numerous mark built, followed closely by the Mark III. The Mark I and Mark III differed only in respect of the power plants and associated services and controls. The first production example carried out its maiden flight on 31 October 1941.

BI (Special) – Modified to carry loads in excess of 12,000b, notably the huge 20,00b "Grand Slam" bomb, in order to carry such a large and heavy wagon the BI (Special) had to have it slang externally in a doorless 'cutawey' bomb aby area, and had to be fitted with the more powerful Merlin 24s. The first use of the 'Grand Slam' came on 14 March 1945, when the Beleifed Vaduct was attacked. The 'Grand Slam' gained the name Earthquake bomb' due to the effect of such a large explosion. The extra



designation 'Special' was applied to aircraft modified in various ways for specific weapons.

Bil – Built by Armstrong Whitworth and powered by Bristol Hercules VI radial engines, and later the Hercules VVI. This was the first attempt to overcome the problem of Rolls-Royce Merlins not being built fast enough to satisfy an everTOP Lancaster I seen in March 1944 with H2S radar dome visible underneath the rear fuselage. (A&AEE)

ABOVE Lancaster II fitted with Bristol Hercules radial engines. (Air Ministry)



LEFT Fitted with American-built Merlin 28s, this is Lancaster III prototype W4114, photographed in September 1942. (Air Ministry) RIGHT ED817 was a BIII (Special) equipped with gear to hold and rotate an 'Upkeep' mine, more familiarly known as a 'bouncing bomb', for the famous 617 Squadron 'Dam Busters' raid of 16/17 May 1943, (ASAFF)

RIGHT The final evolution of the Lancaster's bombcarrying capability was the BI (Special), which was modified to carry the huge 22,000lb 'Grand Slam' externally, (Alv Ministry)





increasing demand. When powered by the Hercules XIV the Mexil could attain a similar speed to its Merlin-powered brethren, though when fully bombed up it could not reach the same height and had a higher fluid consumption. Of the 300 Merk its built, some served with of 15 Squadron but most were on the strength of 115 Squadron but most were on the strength of 15 Squadron, which operated them from March 1943 unlight JAP 11944.

BELOW One of the few Lancaster VIs, which were fitted with powerful Merlin 85s or 87s and with modified air intakes. (Ministry of Aircraft Production) BIII – Fitted with Packard-built Merlin 28, 38 or 224 engines. After attempting to power Lancasters using Bristol Hercules engines, American-built Merlins were adopted as a better way of keeping pace with the increasing demand for this reliable and powerful engine. The Packard-built Merlin 28 delivered 1,300 hp. and differed from Bristsh-built yearness in a mand differed from Bristsh-built yearness in a number of ways including carburation. The Markin 38 (a)quivant to the British Mark 22) provided 1,390 fbc, and the Packard Merin 224 was the equivalent to the powerful British Mark 24. The Packard engines were first trialled on Luncasters in August 1942 using Mark is R5849 and W4114 – the latter gaining the status of the prototype Mark III. The Mark I and III had almost identical performance, but the new designation areas because there were different servicing procedures. It is reported that the Mark IIII gave better full consumption.

Bill (Special) – Otherwise called Type 464 Provisioning, 23 Lancasters were specially modified to carry 9,250lb 'Upkeep' mines for the 617 Squadron dams raid of 16/17 May 1943. The weapon was carried in a specially





designed structure that could rotate it at the 500rpm required for it to work successfully.

Mark VII - Built by Austin, some of them to 'FE' (Far East) standard for use with the proposed Tiger Force for potential operations in tropical conditions. Included an electricallypowered Martin mid-upper turret. A batch of 150 BVIIs earmarked for Tiger Force were fitted with 1.640hp Merlin 24s, which were particularly suitable for use in the climate of its intended theatre of operations. However, the earlier than anticipated surrender of Japan meant that these hombers saw no action in the Far Fast

Mark X - Canadian-built aircraft manufactured by Victory Aircraft at Malton, Ontario, Fitted with Packard-built Merlins. Later examples had Martin 250/CE Type 23A electric mid-upper turrets fitted further forward on the fuselage and equipped with two 0.5in machine guns rather than Browning 0.303s. All sections were fully interchangeable with British-built parts in case of battle damage.

Some other variants

PRI - For photo reconnaissance. Conversion work included the removal of the turrets. ASRIII - For air-sea rescue duties. Modified to carry the Cunliff-Owen Airborne Lifeboat IIA. MRIII/GRIII - Converted for maritime reconnaissance, to replace Coastal Command's Consolidated Liberators returned to the USA when the Lend-Lease agreement

Mark VI - In order to increase the performance of the Mark III. a small number of Lancasters were fitted with higher-powered Merlin 85s or 87s and designated Mark VIs.



LEFT Lancaster VII NX612 in white 'Tiger Force' paint scheme. (Ministry of Supply)

MIDDLE The RCAF used the five Lancasters converted to 10Ns as navigation trainers, four of which gained names. This is FM211 Zenith. (Nat Def Photograph)

BELOW Nine Lancaster Xs were modified to 10P standard for photo reconnaissance and mapping work. (Nat Def Photograph)



		ark 10 conversion roles
Mark	Duties	Numbers/notes
		Four 10ARs initially modified to 10BR (Interim) standard, then nine BXs converted to 10BR
	Drone carrying	KB848/851
10MR/MP	Maritime reconnaissance/ patrol	Approximately 70
	Navigation trainer	FM206/208/211/KB826/986
	Avro Orenda engine test bed	FM209
	Photographic reconnaissance	FM120/122/199/207/212/214- 218/KB729
	Standard post-war bomber	KB944/781/801/854
	Air-Sea Rescue	FM148/222/KB907/961
	Standard bomber	Unmodified







Chapter Two


Anatomy of the Lancaster

Although the BBMF and Canadian Warplane Heritage operate the only two flying Lancasters in the world there are still many ground-based examples to be seen, some of which are able to run their engines and taxi. Despite being constructed under wartime conditions, these aircraft are a true representation of the 'built to last' mentality. The BBMF is fortunate to have many of the original manuals and drawings. which enable them to maintain their aircraft to a high standard. The following sections should provide readers with a better understanding of the design, maintenance and servicing arrangements of this well-loved aircraft.

Lancaster BI







The fuselage

ecause of its size the fuselage is divided into five sections. These are the nose, front centre section, centre section, rear centre section and rear fuselage. These sections, when boilted together, form the main

fuselage. This is a stressed skin monocoque construction, built up with transverse channel section formers (frames), stiffened by fore and aft stringers that connect to the formers to provide the framework.

RIGHT Inside of the fuselage looking forward from the rear of the bomb bay, showing the frame construction and internal fittings. (Paul Blackah/ Crown Copyright)

FAR RIGHT Closeup view of the frame construction. (Paul Blackah/ Crown Copyright)






This framework is covered with alclad (a light aluminium alloy) sheet, the majority being 22 SWG but in some places 16 SWG. This is riveted to the formers and stringers with dome-head rivets.

The completed fuselage is made up of 51

formers, which are identified by numbers and letters. Formers 1–41 proceed aft from the first complete former in the front centre portion. Formers A–K (excluding letter I, which is not used due to its similarity to the number 1) proceed forward from that point.



LEFT Rigging instructions for the Lancaster. (Crown Copyright) RIGHT Bomb aimer's position, with bomb sight prominent in the centre of this view. (Paul Blackah) Crown Copyright)

FAR RIGHT

Downward pointing F24 camera, mounted in the nose on the port side in front of the bulkhead at former E. (Paul Blackah/ Crown Copyright)

RIGHT View from the front parachute escape hatch looking up towards the pilot's controls. (Paul Blackah/ Crown Copyright)

FAR RIGHT Radio


operator's position. with T.1154 transmitter and R.1155 receiver dominating, The circular display to the left of these is the 'Fishpond' radar, intended to give early warning of nearby enemy fighters. (Jarrod Cotter)














The nose

The nose section houses the front FN5 turret and the bomb aimer's position, and extends back as far as the joint at former E.




The front centre section runs from the joint at former E to the joint at former 6. This houses the pilot's, navigator's and radio operator's stations.



RIGHT Details of canopy construction. (Crown Copyright)






Centre section

This serves as a rest compartment, running from the joint at former 6 to the joint at former 12. The centre section of the fuselage is built on the front and rear spars of the mainplane.

ABOVE Pilot's seat. (Crown Copyright)

ABOVE LEFT
Electrical distribution
panel situated on
the starboard side,
forward of the rear
spar. (Paul Blackah/
Crown Copyright)



LEFT Centre section floor construction. (Crown Copyright) RIGHT Situated behind the front spar are the emergency air blow-down bottles for the flaps and undercarriage. (Paul Blackahl

Crown Copyright)

FAR RIGHT TOP Situated high on the port side of the fuselage behind the front spar is the aircraft's hydraulic tank, filter and automatic cut-out valve ('acov'). (Paul Blackah' Crown Copyright)

RIGHT The rear wing spar joining the centre section of the fuselage. (Paul Blackah/ Crown Copyright)

FAR RIGHT Behind the rear spar is the flap jack, seen here with its end covers fitted. (Paul Blackah/ Crown Copyright)







RIGHT Internal view of the mid-upper turret. (Paul Blackah/Crown Copyright)













FAR LEFT Port side of the rear centre section fuselage, showing the ammo tracking to the right below the mid-upper turnet. (Paul Bleckahl/Crown Copyright)





canisters. (Jarrod Cotter)

FAR LEFT Mid-upper
turret hydraulic tank –
each turret has its own
oil tank and pipework.
(Paul Blackah)

LEFT Reconnaissance flare and photo flash

LEFT Turret system recuperators. These act as a basic accumulator that helps maintain pressure to the system. (Paul Blackah/ Crown Copyright)

Crown Copyright)



Rear centre section

This runs from the joint at former 12 to the joint at former 27 and houses the FN50 midupper turret.

Rear fuselage

The rear fuselage runs from the joint at former 27 to the end of the fuselage (former 41), and houses the tail unit and the rear FN121 turret.



FAR LEFT Rear fuselage joint, showing the attachment bolts. The yellow rail is a handhold. (Paul Blackah/ Crown Copyright)

LEFT Elevator and rudder control rods, running down the rear fuselage. (Paul Blackah/ Crown Copyright) RIGHT Ladder stowage in the rear fuselage. (Paul Blackah/ Crown Copyright)

FAR RIGHT Flare tube at rear of fuselage.











Bomb doors

The two bomb doors run from just aft of the joint at former E to former 22. They are made up of a central spar with nose and main ribs and are covered with a thin alloy skin (24 gauge). Each door has an hydraulic jack attachment at each end.

The tail unit

The tail unit consists of a port and starboard tailpiane to which are attached the firs, rudders and elevators. The two taliplanes are bolted together at the centre of the fuselage at formers \$3\$ and \$3\$. The taliplane is built up of a front and rear spar with 16 rice that are braced with stringers; these are then covered with added skin panels.

The fins

The fins are built up from front, rear, and intermediate fin posts, with vertical stringers, intercostals and ten horizontal ribs. The fin posts are stiffened by steel liners, which are riveted to them. The rear fin posts have

RIGHT View from the internal compartment doors to the rear turnet. (Jarrod Cotter)





FAR LEFT Bomb doors open. (Paul Blackah/ Crown Copyright)

LEFT Rear bomb door operating jacks. (Paul Blackah/ Crown Copyright






FAR LEFT Corrosion on door skin. (Crown Copyright)

LEFT Corroded bomb door reskinned. (Crown Copyright)



LEFT General view of the tail unit, with the elevators seen in the lowered position that would cause the aircraft to adopt a nose-down attitude in flight. (Jarrod Cotter) RIGHT Fin and rudder construction. (Crown Copyright)



additional stiffeners to accommodate the rudder hinge brackets, which are bolted onto the rear face. The whole of the fin structure is covered with an alclad skin.

The rudders

The rudders are of similar construction to the fins, to which three hinge assemblies attach


them. Two mass balance horns – cast iron weights – are supported by tubular arms bolted between ribs 9 and 10. Each rudder has a trim tab fitted to it.

The elevators

Each elevator consists of 16 main ribs, which are welded to the main tubular spar, and light

RIGHT Starboard fin and rudder. The fin is fixed rigid, while the rudder is the movable portion at the rear. Rudders affect the yaw of the aircraft, ie the left and right movement in the horizontal plane. Note also the mass balance horn towards the top of the rudder, and the trim tab at the bottom trailing edge. (Paul Blackah/ Crown Copyright)





LEFT Typical mainplane section. (Crown Copyright)

alloy nose ribs, which are riveted to lugs and then welded onto the main tubular spar. The whole unit is then covered with a light alloy skin, which is riveted in place. The elevators are connected inside the fuselage by means of a steel torque tube; each has a trimming tab and a balance tab. Early production Lancasters had father-covered elevators.

The wings

The Lancaster mainplane runs from the starboard wingsp, through the centre section (including the fuselage), and ends at the port wingsp. Each side is made up of 33 ribs, numbered 5-32 and lettered E-A1. Of these, E-A1 form each wingsp, 5-22 form

BELOW The Lancaster has a 102ft wingspan, evident from this unusual vantage point. (Neil Clegg/ Crown Copyright)







TOP RIGHT Newly completed skin repair to port wingtip. (Crown Copyright)

RIGHT Shackle plate and bolts that hold the outer wing to the centre section. (Crown Copyright)

RIGHT Skin repair work to the underside of a wing. (Crown Copyright)







the outer planes, and 23-32 make up the centre section.

The outer and centre sections have forward, rear, upper and lower main spar booms. The outer section is attached to the centre section by means of a forged shackle that is boited to the spar booms.

For transportation purposes the mainplane is broken down into the following sections: centre plane, both port and starboard trailing edge of the centre plane, port and starboard cuter plane, trailing edge of the port and starboard outer plane, trailing edge of the port and starboard and starboard sized starboard starboard starboard and starboard starboard starboard flaps, and the centre plane hinged leading edge, port and starboard starboard port and starboard starboard starboard port and starboard starboard starboard starboard starboard port and starboard sta

The undercarriage


The undercarriage consists of two restrictable man legs and a fixed tall leg. The man undercarriage is made up of two shock absorber struts, a K-strut and an axis Together these letters are known as the panel assembly. The panel assembly is attached to the airfame by this legs bottle, which attach to the undercarriage support beams mounted on the torict spar.

Attached to the panel assembly are two drag stays. These are also connected to the lower rear spar of the mainplane. Two retraction jacks, attached to the drag stays close to the centre point, enable the undercarriage to retract rearwards and upwards into the nacelle, where they lock into place.

Shock absorber struts are oil and air filled (1,000psi) to provide damping action to the aircraft on landing.








ABOVE Drag stay locking mechanism shown when the main undercarriage leg is locked down. The red tube is the undercarriage ground lock. (Paul Blackah/Crown Copyright)

TOP RIGHT Tailwheel mounting inside the rear fuselage. (Crown Copyright)

RIGHT The outboard undercarriage jack (upper) and drag stay (lower). The orange item is the number 2 fuel tank.

The tail log is non-retractable and is oil and air filled (\$70,00), it is a self-centric juri with the added assistance of an anti-shimmy device filted externally. This stops the tail and from violently shaking on landing and take-off. It is talled into a socket behind the centre joint of the tallplane upper born, where it is also attached by a pin to the lower tailwhelm cuming beam, which is a box section fitted in the rear fuselege, located under the tallplane.





How to remove a Lancaster wheel to replace a worn brake unit





























- Jack adaptor
 access panel
 removed
 Senior Aircraftman
 Barlow fitting the
 jack adaptor in
- jack adaptor in place
 3 25-tonne jack being positioned
 4 Jack in position ready to lift aircraft
 5 The tail-wheel is chocked prior to are lifting the aircraft
- 7 With the aircraft lifted, the wheel chariot is positioned 8 The charlot is lifted, allowing the axle to clear the
- oleos

 9 Senior Aircraftman
 Barlow
 disconnecting the
 brake hoses

 10 The axie boits are
 then removed

 11 Axie boit nearly
 removed
- removed
 12 The wheel is removed, allowing the brake unit to be replaced
 13 With the wheel
- the bolt fits

 14 Lancaster brake pads, retaining plates and springs. (All Paul Blackah/ Crown Copyright)





The Rolls-Royce Merlin engine

The Rolls-Royce Merlin engines fitted to the Lancaster should be the Merlin XX series. However, the BBMF Lancaster operates using Merlin 25, 225 and 500 engines. These are very similar in specification, and for the purpose of this

book we will take a closer look at the Merlin 25. The Merlin 25 is a 12-cylinder, 60°, V12 liquid-cooled engine. It has a compression ratio of 6:1 and its dry weight is 1,430lb.

The two-piece cylinder block is cast from The two-piece cylinder block is cast from the piece cylinder block is cast from several models and from piece the several piece the cylinder block is two of scriper rings. The correcting rods are two of scriper rings. The correcting rods are ricked selet forgings, machined or 4-sections. The one-piece six-frow crankfarft is machine longed from chrome-molyderum steel. The crankcase is cast from alarinium alloy. Two internal rods and rods scriper and rods scriper and rods scriper and rods scriper and scr

Cylinders

The two cylinder assemblises, mainly the rightand life-thand blocks, are known as the A and B blocks respectively. Each comprises six cylinders, the upper camehalt in drive unit and the camehalt and nocker mechanism, which operates he valves incorporated in the cylinders. Each block consists of a separate aloy skirlt, head and skir detachable wet steel liners which, when bothed together, form the cylinder block proper in addition to providing part of the coolart jacket, the head also forms the roots of the six combustion chumbers.

Cylinder liners

Each cylinder liner is shouldered and spigotted at the upper end to enter its respective recess in the bottom of the cylinder head. The cylinder liner is also provided with a sealing ring at its lower end to form a joint with the crankcase, to which it is drawn by the cylinder holding-down studs.

Cylinder block covers

The covers are secured to their respective cylinder blocks by studs and nuts, with a

gasket between the two contacting faces. The main difference between the A and B covers is that the latter incorporates an engine speed indicator drive whilst the former is plain.

Valves

There are two Irlet and enhaust valves per cylinder. Both valves are of the trumpet type and have satellite-ended stems. The valve properties are of the ineit and phosphorbonze for the onlawst. The valves are not interchangeable. Each valve guide is pressed interchangeable. Each valve guide is pressed in the cylinder block until a concial colar near its top end is seated on, and is fault with, here not of the cylinder block.

Camshaft

A single contral camshaft for each cylinder block is mounted in pedestal brackets and operates both intel and exhaust valves through rockers fitted with adjustable tappets. The camshafts, which are similar for both blocks, are driven from the wheel case by inclined shafts ending in bevel prinons, which mesh with bevel wheels at the end of each camshaft.

Camshaft auxiliary drive

The air compressor and hydraulic pumps for the turrets are mounted on the rear ends of the A and B cylinder heads. Both are driven from the spur gear wheels attached to the camshaftdriven bevel wheels.

Pistons

The pistons are attached to the connecting rods by fully floating gudgeon pins. The connecting rods are of the forked and plain type, the forked rod being fitted to the B-side of the engine.

The pistons are machined from light alloy forgings and are fitted with three compression rings above and one grooved scraper ring bellow the gudgeon pin. The gudgeon pins are made from hollow steel and are retained in the piston by spring who cricips. A pair of oil holes are diridled citiguely and upwards towards the centre to meet in the metal above each gudgeon pin bore to assist in conting the piston.

Crankcase

The crankcase consists of two halves bolted together. The upper portion incorporates the

OPPOSITE

Rolls-Royce Merlin 25. (Paul Blackah/Crown Copyright)

- 1 Camshaft cover
- 2 Generator housing,
- generator not fitted 3 Magneto
- 4 Reduction gear
- 5 Ignition harness
- 6 Carburettor 7 Two-speed single
 - stage supercharger
- 8 Coolant pump 9 Magneto
- 10 Oil control valve

Diagram showing all the installation connections for a Rolls-Royce Merlin engine. (Crown Copyright)

1 Coolant outlets

2 De-icing connection to propeller

3 Vacuum pump inlet

4 Vacuum pump return

5 Engine mounting feet 6 Oil pressure gauge connection

7 Oil thermometer gauge connection

8 De-icing inlet connection

9 Coolant inlet to cylinder

10 Dowty pump drain

11 Oil inlet

12 Coolant pump outlet

13 Coolant pump inlet 14 Starter motor terminals

15 Supercharger bearing vent

16 Slow-running cut-off lever

17 Oil outlet

18 Constant-speed propeller governor unit

19 Wheelcase breather vent

20 Magneto earthing connection 21 Magneto booster coil connection

22 Throttle control levers (alternative)

23 Boost gauge connection 24 Cabin heater connection

25 Haywood air compressor outlet

26 I.A.E. pump delivery

27 I.A.E. pump drain

28 I.A.E. pump inlet 29 Fuel priming connection

30 Propeller shaft

31 Crankcase breather

32 Engine starting handle 33 Fire extinguishing system inlet

34 R.A.E. air compressor oil inlet 35 R.A.E. air compressor air inlet

36 R.A.E. air compressor air & oil outlet

37 Engine-speed indicator drive 38 R.A.E. air compressor drain

39 Boost control cut-out lever

40 Two-speed supercharger control 41 Fuel pump drain

42 Fuel pump inlet


43 Fuel priming connection to fuel pump 44 Oil dilution connection

45 Fuel pressure gauge connection 46 Lockheed pump drain


47 Electric generator terminals

48 Electric generator air cooling inlet

49 Electric generator air cooling outlet



REAR VIEW



RIGHT Front of Merlin propeller shaft, reduction gear and constant speed unit (CSU), (Paul Blackah) Crown Copyright)



rear half of the reduction gear housing at its front end, and has a facing and spigot at the rear end to which the wheel case is attached. The lower portion incorporates the scavenge pumps, filters, and the mounting for the hydraulic system pump. This is only fitted to the number 2 and 3 engines.

Reduction gear

The reduction gear is of a single-spur layshaft type and is housed partly in a casing bolted to the front end of the crankcase and partly in the crankcase itself. The casing is located on the crankcase by means of a spigot concentric with the propeller shaft. The driving pinion is concentric with, and is driven by, a short coupling shaft from the crankshaft. All these shafts run in roller bearings, the propeller shaft having, in addition, a thrustable ball bearing, enabling the engine to be used with tractor (pulling) or pusher propeller. A dual-drive unit is fitted to the reduction gear cover for the purpose of driving the propeller constant speed unit (CSU) and vacuum pump unit, which are both bolted to it. The vacuum

pump is used for the operation of certain navigational instruments.

Wheel case assembly

The wheel case is bolted to the rear end of the crankcase and carries the magnetos, coolant pump, generator drive, electric turning gear and fuel pump unit. It houses the spring-drive unit and certain shafts through which the magnetos. camshafts, electric generator, fuel, oil and coolant pumps are driven.

Coolant pump

The coolant pump is of the bottom-fed centrifugal type and serves each cylinder block from a separate outlet.

Fuel pump

The fuel pump unit, mounted on the facing on the port side of the wheel case, consists of two separate pumps operating in parallel. Each pump is capable of operating independently of the other and each is of sufficient capacity to supply more than the maximum amount of fuel required



LEFT Merlin 25 viewed from the rear, showing the supercharger unit and carburettor clearly. (Paul Blackah/ Crown Copyright)

Electrical generator drive

The electrical generator is mounted upon a cast light alloy right-angled bracket that is located on the left-hand side of the crankcase.

Supercharger

The two-speed, single-stage, liquid-cooled supercharger is of the high-speed centrifugal type, embodying a semi-shrouded impellor which is driven from the rear end of the crankshaft through a two-speed gear.

Carburetion

The SU twin-choke up-draught type Merin carburetor fitted to this engine is, with the exception of the separate boost control unit, entirely self-contained and is arranged to be fully automatic in its functioning, with result that the responsibilities of the pilot are reduced to their simplest form and the danger of engine damage resultina from incorrect settina is reduced.

The SU type Merlin AVT40/193, or 214 carburettor, embodies two complete carburettors in one unit. The flow of fuel through the left-hand carburettor main jet is directly controlled by the induction pressurepoperated mixture control, whilst the right-hand potential mixture control, whilst the right-hand jet is directly controlled by the atmospherically poperated mixture control. Both these instrue controls are automatically controlled through inlework by separate amendic capsules incorporated on each side of the carburettor. The upper half of the carburettor casting is mounted on studies on the lower face of the superharger intellike elbow. A large specially shaped gasker is used at the joint faces to provide a gas-strin and fuel-light faces.

Both the vertical intake passage and throttle barrels are coolarit jacketed, these jackets being included in the coolant return from the Boyinder block to the infet side of the coolant pump. A system of oil-heated throttle valves is also included to prevent freezing and to allow for a portion of the scavenje oil being directed through the hollow interior of the throttle valves before it is returned to the oil tank.

Ignition system

The ignition system comprises two magnetos, which are attached to the wheel case, PIGHT Merlin spark plugs – note the twin electrodes. (Paul Blackah/ Crown Copyright)

FAR RIGHT This picture gives an idea of the size of a spark plug from a Merlin - similar to that for a car. (Paul Blackah/ Crown Copyright)



one on the left, and one on the right. Attached to these are the high-tension wing harmesses for the spark plugs, which are metal screened and serve a dust purpose by acting as a collector for the induced field around the high tension were and returning the resulting electrical current to earth, and also preventing radio interference. Each cylinder has two spark plugs—one magneto provides the spark for the inter-side plugs and the other for the exhaust-side plugs. This ensures that if one magneto falls, the engine will still run using the other.





Engine lubrication system

There are four oil circuits in the lubrication system of the engine: the main pressure feed circuit; the low pressure feed circuit; the front sump scavenge circuit; and the rear sump scavenge circuit. The main and lower circuits are served by a single pressure pump and suitable relief valves, while each scavenge circuit is served by a separate scavenge pump.

Engine controls

The control lever for the throttle, airscrew and boost cut-out, together with the engine fuel






cock controls, are mounted on a quadrant below the instrument panel. Chains and tile rods connect the control levers to the engine control boxes behind the engines. The inboard engine boxes are mounted on the front spar and the outboard engine boxes are located on brackets on the front spar. ABOVE Engine and secondary control layout on the mainplane. (Crown Copyright)



LEFT Covers removed to show the engine control workings of the main pedestal in the cockpit. (Paul Blackah/ Crown Copyright)



ABOVE Outboard fuel tank mounting. (Crown Copyright)

RIGHT Each wing has three fuel tanks fitted, which are retained by straps. (Crown Copyright)

FAR RIGHT Fuel tank bay with unit removed. (Crown Copyright)

RIGHT Here the fuel tank has its outer covering removed for maintenance work. (Crown Copyright)

FAR RIGHT Access panel open to the number 1 fuel tank filler cap. (Paul Blackah/ Crown Copyright)









Systems

Fuel system

The fuel system consists of separate port and starboard systems connected by a balance pipe. On each side of the fuselege, mounted in the maniplane, are three metal tanks, each fitted with an electric booster pump. Fuel is drawn by the engine pump or pumped by the booster pump from the tanks through non-return valves to the tank streagh on-return valves to the tank selector cocks. From here a supply is run to each end.

The two inboard fuel tanks – the number 1 fuel tanks – hold 580 gallons each; the intermediate, or number 2 tanks, hold 383 gallons each; and the outboard, or number 3 tanks, holds 114 gallons each. Each tank is filled independently from the top of the wind.

On the BBMF's Lancaster only the number 3 tanks are fully filled and the fuel load never exceeds 1,000 gallons, with the rest of the fuel being evenly distributed throughout the other tanks. This is done to minimise fatigue and stress to the winds.

Cooling system

Each engine has its own independent cooling system. This comprises a header tank mounted behind the front cowling diaphragm, a radiator, attached below the engine, and a thermostat.

The system is operated under pressure, which is controlled by a thermostatic release valve at the top of the header tank. This valve limits he maximum pressure and provides a controlled secape of air, which allows or expansion at different temperatures. The temperature of the coolant is controlled by the temposital, which allows the amount of airlinov through the radiator dependent on the temperature. The coolant consists of 30 per cent glycid (ALS), and 70 per cent diddlilled water.

Oil system

The oil system also has an independent system for each engine. This comprises an oil tank mounted in the engine sub-frame and an oil cooler mounted below the engine. The main BELOW PA474 stripped of its engine cowlings, showing the radiators hanging below each Merlin and the oil tanks behind the engines in the sub-frame.



feed pipe is taken from the filter in the oil tank and passes to the engine oil pump. The oil is returned via the oil cooler to the top of the oil tank. Each oil tank holds 37½ gallons of oil (OMD270)

Propellers

Four Hamilton Standard three-bladed metal propellers drie the aircraft. These are the later wide-blade versions rather than the thinner blades that were mostly used during World Well Two. Each propeller has the capacity to 'feather', which means that if there is an engine problem and the engine has to shut down, the individual blades can turn to 'fully fine' so that no drag is created.

Electrical system

Two generators drive the 28v electrical system on the number 2 and 3 engines. This system operates the lights, internal and external, instruments, radios, intercom and navigation aids. It is backed up by four 24v batteries located behind the front span.

Hydraulic system

Two hydraulic pumps fitted to the inboard engines operate the hydraulic system. Pipework from the two pumps runs to the hydraulic reservoir situated to the rear of the front spar, to an accumulator and an automatic out-out valve which regulates the hydraulic pressure to around 850psi. This system operates the undercarriage, the bomb doors and the flags.

A selector valve on the right-hand side of the plot's seat operates the undercarriage system. This selector is always in either the UP or DOWN position. When a selection is made full is delivered under pressure through the selector to the undercarriage jacks.

The bomb doors are controlled by a similar

selector valve positioned on the left-hand side of the plot's seat. When the lever is pushed down the doors open and when it is pulled up they close. The doors are operated by four hydraulic jacks, one at the front and one at the rear of each door.

A single-cylinder jack, mounted in the fuselage behind the rear spar, operates the flaps. The piston rod of this jack extends outwards through both end covers; these are then connected by universal jointed links to push-pull tubes, sliding in bushes, in the trailing edge of the mainplane. A series of short links then connects the flaps to the push-pull tubes.

A handle to the right of the pilot's seat, and a control valve neutral below the pilot's floor, govern the raising and lowering of the flags. This unit has a neutral position, at which the handle is normally set. When the handle is moved to the doorn position oil is supplied to the downside of the jack so the flags go down. After reaching the required position the handle is returned to neutral, thereby stopping the flow of all.

Pneumatic system

The pneumatic system is operated by two Heyward compressors, which are fitted to the inboard engines. These supply pressure through a pressure-regulating valve, set at 450ps, to an air bottle situated behind the nose turret. This system operates the brakes and the radiator flaps.

A lever on the pilot and co-pilot's control column operates the brakes. This lever is cable-linked to the brake control valve and, when applied, air from the brake control valve inflates the brake bass to 120osi.

Flying controls

The plot and the co-plot operate all the hydro control. These include: allerone, elevators, moderns, naciders, malerone, elevators, nuclders, alleron time, elevator trim, rudder trim and flags. The allerons are operated by a series of cable, chains, tie-rods and control tables. The system runs along the port side of the fuselings and at the rear wing cortres section it enters the port and stathcoard maniplanes, where it connects to the alleron quiet wing bell crank. From there it travels to the alleron input not and onto the alleron, which is a metal framework conversivable flight increase.

The elevator and rudder are operated by control rods that run down the port side of the fuselage to the tailplane where they connect to the controls, which are of metal construction.

All the trim systems are cable-operated (5cwt) to a screw jack, which then connects via an operating rod to the trim tabs.





ABOVE Engine controls. (RAF Coningsby Photographic Section/ Crown Copyright)

- 1 Fuel master cocks
- 2 Throttles 3 Constant speed unit
 - Constant speed unit controls
- 4 Boost cut-out lever
- 5 Pilot's control yoke 6 Co-pilot's control yoke
- 7 Pilot's rudder pedals 8 Co-pilot's rudder
- pedals 9 Rudder control lock in
- place 10 Control column

LEFT Captain's control yoke. Note brake lever on the left-hand side. (RAF Coningsby Photographic Section/ Crown Copyright)



The instrument panel of the Battle of Britain Memorial Flight's Lancaster I PA474. (RAF Coningsby Photographic Section/

(RAF Coningsby Photographic Section/ Crown Copyright) Air speed indicator
 Artificial horizon

3 Rate of climb indicator 4 Altimeter

- 5 Directional indicator
- 6 Turn and slip indicator
- 7 Accelerometer8 Undercarriage indicator
- 9 Compass (P10) 10 Cockpit lights
- 11 Gyro compass remote indicator
- remote indicate

 12 Magneto
 switches



13 Boost indicators 14 RPM indicators 15 Engine start

buttons 16 Boost coil

switch

17 Fire indication test button (guarded) 18 Flap indicator switch

19 Vacuum indicator 20 Flap indicator

21 Vacuum system changeover switch (this works off the number 2/3 engine)

22 Propeller feathering buttons

23 Fire indication lights

24 Extinguisher buttons

25 Air system and brake gauge

26 Identification light Morse switches

27 Engine radiator shutter switches 28 VHF radio

RIGHT Close-up of the left-hand side of the instrument panel. (RAF Coningsby Photographic Section/ Crown Copyright)



RIGHT Centre of the instrument panel. (RAF Coningsby Photographic Section/ Crown Copyright)





RIGHT Right-hand side of the instrument panel. (RAF Coningsby Photographic Section/ Crown Copyright)







FAR LEFT Aileron, rudder and elevator trim wheels. The undercarriage selector lever and safety bolt are in red. The safety bolt prevents accidental operation of the undercarriage. (Paul Blackah/
Crown Copyright)

LEFT Aileron control rod linkage on rear spar. (Paul Blackah/ Crown Copyright)





LEFT Ailerons with fabric removed showing the ribs and trailing edge.



ABOVE Six of the eight Browning 0.303in machine-guns installed in PA474's turrets pointing rearwards. (Jarrod Cotter)

Turrets

The Lancaster was usually fitted with three turnets, atthough some had a fourth or mid-lower turnet, positioned undermatth the aircraft to the near of the bomb doors. This would carry the Drowning 0.3038 upons with 1,000 rounds of ammunition. Each turnet had town hydraulic system, to enable the others to function should one be hit in action; this comprised all hydraulic pump, reservoir and recuperator. The BBMF Lancaster is fitted with fellowing turnets, although the hydraulic systems have been disabled and the turnets can only rotate when manually operated.

Nose turret

The FN5 nose turret was fitted with two Browning 0.303in machine guns, which held 1,000 rounds of ammunition per gun. Once the air gunner was in situ he was able to rotate through 190° by the use of two control handles. The handles also contained the triggers for the firing mechanism.

Mid-upper turret

The FNSD mid-upper turret was also fitted with the Browning 0.350m machine gurs which each held 1,000 rounds of amrunition. To gain access to the turnet a step was stowed on the inside of the fuselege, which swung into position when uncipped. Toos the gunner was inside the turet the harmock-type seat was then clipped into position. The turret could rotate through 360°, in order to protect the fall unit from diarrage during firing there was a failsafe mechanism comprising "taboo arms" that ran on a track fitted to the fairing around the turret. This enabled the air gunner to concentrate on firing without working about shortlong in so on tail off.






ABOVE PA474's nose, with the FN5 front gun turret prominent. (Jarrod Cotter)

LEFT The FN50 midupper turret. Note the 'taboo arms' below the guns. (Jarrod Cotter) RIGHT Rare sight of the mid-upper turret with the glass dome removed. (Jarrod Cotter)



Rear turret


BELOW Rear turret mounting. (Crown Copyright) The FN121 rear turret was fitted with four Browning 0.303in machine guns, which were fed ammunition from stainless steel tracks that ran from two ammunition boxes attached to the floor at formers 20–22. The tracks ran either side of the fuselace and toaether could the stainless of the stainle supply 2,500 rounds for each of the four guns. The turret could rotate through 190° and was operated in the same manner as the other turrets. Once inside the turret the air gunner closed two doors behind him, which prevented him from falling out when the turret was rotated.






LEFT External view of the FN121 rear turret, fitted with four Browning 0.303in machine guns. (Paul Blackah /Crown Copyright)

BELOW Turret hydraulic circuit diagram. (Crown Copyright)





Bomb bay and loads

he Lancaster's bomb bay could hold a variety of bomb loads depending on the operation to be carried out. The BBMF Lancaster has a 4,000lb bomb carrier and several 500lb bomb carriers fitted.

Bomb loading

Before leading bombs, the bomb cell doors were opened by pushing down the lever on the left-hand side of the plots seat. If the inboard engines were running the doors would open automatically, but if they weem'it it was necessary to operate the emergency hand pump on the port wall of the fuselege just aff of spar 4. Safety brackets were then fitted to free for hydraffic jacks to prevent indeventer closure of the doors whilst bomb-loading operations were in progress.

Standard bomb-loading winches were required, two 2,000lb winches being used to host the 4,000lb bomb. The adjustable crutches for the 4,000lb bomb were removed when other bomb loads were to be carried. A step-ladder was necessary in order to remove the bomb carriers, to make final adjustments, and to check that the bombs were in position.

Order of loading

Heavy bombs had to be loaded in the correct sequence. For this purpose each of the bomb gear housings (the arrangement of which depended on the type of bombs being carried) was numbered above and below the floor for ease of identification. Typical load options were:

- 14 x 250lb, 500lb or 1,000lb bombs (other
- than 500lb Marks I, II, III or IV AS bombs)

 6 x mines or heavy bombs, plus smaller
- 6 x 500lb AS bombs (Marks I, II and III only), plus smaller bombs
- 1 x 4,000lb bomb, plus smaller bombs

Note that in options B, C and D several smaller bombs were carried in addition to the main load, eg option D might comprise six 1,000lb and two 250lb bombs in addition to the 4,000lb bomb. The 14 bombs of option A.

however, represent a maximum load, with only the central bomb housing not being used. The 250lb or 500lb bombs or containers could be of the following types:


500lb GP bombs

- 500lb SAP bombs
- 250lb GP bombs
 250lb SAP bombs
- 250lb LC bombs
- 250lb B bombs
- 250lb AS bombs
- Small-bomb containers


Although not important, it was more convenient to load the small bomb containers, the 500lb bombs and the 250lb bombs in that order. If the number of bombs to be fitted was less than 14, the centre housings would be used.

ABOVE Close-up of bomb slip. (Paul Blackah/ Crown Copyright)

OPPOSITE Bomb bay, showing eleven 500lb bomb slips and the red crutches for the 4,000lb 'Cookie' bomb. (Paul Blackah/ Crown Copyright) THIS PAGE AND OPPOSITE
Various Lancaster bomb load configurations.
(Crown Copyright)







8-500 LB. 8 6-250 LB. A.S. (MK. IV ONLY)



6-500 LB & 3-250 LB A.S. (MK.T. II & III) AND 5-250 LB S.A.P.




6-1,000 LB & 3-250 LB G.P.



I-4000 LB. H.C.--6-500 LB. GP. B. 2-250 LB. GP. BOMBS



6-1500 LB. A MINES OR 6-2000 LB. H.C. BOMBS




6-1900 LB. 8. 3-250 LB. GP.

250 LB, SAR 2000 LB, AR 2000 LB, AR



6-2000 LB. A.P. B. 3-250 LB. S.A.P.



500lb and 600lb AS bombs

Fourteen 600lb AS bombs could be carried, but owing to the length of the 500lb AS bomb it was only possible to carry six Mark I, Il or Ill or eight Mark IV bombs of this type. The sequence of loading was in reverse order to the numbering of the housings.

1,000lb bombs

Fourteen bombs of the following types could be carried and would be loaded in reverse order to the numbering of the housings:

- 1.000/b GP (short-tail type) bombs
- 1.000lb USA bombs
- 1,000b MC bombs

However, only six of the long-tail GP type could be carried. The bombs at housings 12, 11, 10, 9, 8 and 7 would be loaded first, in that order.

Loading 250lb, 500lb or 1,000 lb bombs

Lancaster technical manual AP2062A Volume I provides full details of the loading procedure followed during the Second World War:

The following is the sequence of loading operations, using the 500lb standard winch for 250lb or 500lb bombs, and the 2,000lb standard winch for 1,000lb bombs:

(i). Open the bomb doors and fit the safety brackets.

(ii). Remove the cover plates from the bomb gear housings in the floor of the fuselage.



ABOVE Bombing up, as 4,000lb 'Cookies' are taken out to the flight line during World War Two. (RAF Museum) (iii). Using the small crutch handle, wind the front crutch adjustment levers to the maximum up position, i.e. in an anti-clockwise direction. (The crutch handle is stowed in a small pouch on the starboard side of the intermediate centre portion of the fuselage.)

(iv). Remove the bomb carriers from inside the bomb cell by releasing the trip levers in the bomb gear housings. This will need one man inside the fuselage to release the lever, and one man in the bomb bay to remove the carrier.

(v). Fit the bomb carrier to the top of the bomb, which should have been wheeled underneath the bomb cell on the ground, and adjust the bomb crutches evenly only sufficient to steady the bomb while it is being raised,

RIGHT A 'thousandpounder' on each side of a container full of 4lb magnesium incendiaries. (Jarred Cotter)

FAR RIGHT A mix of 1,000lb and 500lb High Explosive GP bombs and an incendiary container in the bomb bay of a Lancaster. (Jarrod Cotter)





otherwise the carrier may distort and prevent its fitting into the housing.

(vi). Adjust the fuse-setting control link from the fusing box on the carrier to the bomb.

(vii). Set the supporting lever in the bomb gear housing in the cocked position.

(viii). Hold the ratchet on the 'quick-windin' side of the bomb winch in the FREE position and pull sufficient length of cable off the drum to pass through the housing.

(ix). Lift the winch reaction pad in the housing so that the winch nose can be fitted after the winch cable has been passed through.

(x). Again hold the ratchet in the FREE position, pull the cable to the ground and carefully fit the ball end to the ball socket on the carrier.

(xi). Take up the free length of the cable on the 'quick-wind-in'.

(xii). After ensuring that the ball end is still engaging the ball socket, proceed to raise the bomb and carrier to the bomb gear housing. The bomb and carrier should be kept in a fore-end-aft position during the lifting operations. (A bomb steadying fork may be used for this purpose.)

used of this papers.

yoli, When the carrier is near the bomb housing, ensure that the guide roters on the carrier engage the guide in the housing, and the supporting pin engages the support hook. This will force the hook upwards and operate the trip lever which will look the supporting hook round the pin on the carrier. (The completion of this operation will be indicated by a loud click as the trip lever operates.) Ensure that the locking pawl is fully engaged.

(xiv). Unwind the cable a few turns to ensure that the carrier is locked in the housing.

(xv). The ball end of the cable should then be disengaged from the socket.

(xvi). Tighten the front carrier crutches by winding the crutch handle in a clockwise direction. Tighten the bomb crutches securely, but take care not to over-crutch or the bomb may be 'fung up'.

(xvii). The electrical connection between the plug on the carrier and the socket at the rear of the bomb gear housing, should




then be made and locked, but first ensure that jettison bars on the selector box are at SAFE.

(xviii). After completion of the bomb loading operations, remove the safety brackets from the bomb door jacks, fit the cover plates to the top of the bomb gear housing, and carry out the usual "light test".

ABOVE A mixed bomb load, just awaiting a 'Cookie'. (Jarrod Cotter)

BELOW To the left of the pilot's seat is the bomb door lever. (Paul Blackah/Crown Copyright)







The owner's view

(•)

Nowadays the chance of anyone becoming the owner of a Lancaster is very unlikely. There are currently only fifteen complete Lancasters on display around the world, with another under restoration and one stored dismantled. All the owners of these aircraft fully appreciate their heritage and rarity, and the phenomenal price tag that would be attached to one probably isn't the biggest hurdle – it's getting one to be offered for sale in the first place!

LEFT AL East Kirkly in Lincolnshine, in the heart of 'Bomber County', Lancaster VII NO811 is keep in finity serviceable taxiable condition at the Lincolnshine Aviation Heritage Gentre, Visitors can regularly see a 'Lanc' running in its natural environment here, and get a taste of night tops' during World War Two. In this scene from November 2007, a poppy wreathy placed in the bomb almer's biller pays a fitting thistute to the lost crews of Bomber Command as Flight Liutenant Mike Leckey runs up the Merlins. (Jamed Cotter)



ABOVE One of East Kirkby's many charms is the sight of a Lancaster operating from a grass runway during its scheduled taxi run days – a sight little seen since World War Two.

(Jarrod Cotter)

Purchasing an airworthy Lancaster is hardly likely!

To see even a static Lancaster offered for sale nowadays would be a minacle, so the prospect of an airworthy example becoming available is remote! The Linconshrine Austion Heritage Centrels NOS11 at East Kirkby represents the most recent instance of anyone coupling a Lancaster in recently airworthy condition, and while nowadays it stays firmly on the ground that signatile even much airworthy.

The museum is a memorial dedicated to all Bomber Command personnel who never returned home from operations, but especially to Piol Officer Christopher Parton. Christopher Real Bight engineer with No 433 Squadron HCAF based at Skipton-on-Swale, Vorkshire, highing the Handley Page Halfac. He was lost on operations over Nuremburg on the night of 3031 March 1944, agod last 19.

Two of Christopher's bothers, Fred Panton MEE and Harold Panton, were young teenagers still at school when their brother died, and as they grew older they became determined to do something to commemorate his memory. What transpired is a fascinating story, the fruits of which can be enjoyed by all today.

We pick up Lancaster Mark VII NX611s story in early November 1962, when numbered WU-15, it made its way to Noumeau, New Caledonia – a French island located about 1,000 mise east of Australia. It was one of three Lancasters employed by the French Nayr for a variety of tasks including air-sea rescue and communication delires across a vide region of the Pacific. After just two years all three French Lancs were witchwarm from sperios.

Around this time the UK-based Historic Aircraft Preservation Society was looking to preserve a Lancaster. The French offered HAPS one of their retiring examples free of charge, and even flew it to Australia for collection. WU-15 arrived at Bantsoum, near Sydney, New South Wales, in August 1964.

Prior to its lengthy flight home the Lancaster would need a thorough overhaul. In order to pay for this and the flight back to the UK a fund-raising campaign was put in hand. Assistance campe from the Hawker Siddeley Group, the Royal Australian Air Force, the RAF, Shell and QANTAS, as well as many aviation enthusiasts.



LEFT Blackpool
'Aeronautical Museum'
auction catalogue
from 1972 which
included Lancaster
VII NX811, with a
reserve of £12,000 that
wasn't reached! An
operational Lancaster
is hardly likely to
appear in an auction
again.

WU-15 was overhauled, fitted with an extra fuel tank and test flown. Then, on 23 Agri 1956, with the Bristin o'll registration GA-SSX, it was moved to Mascot near Sydney, ready for tis much-publiced departure. It look off on the first lag of the 12,000-mile journey home two days later on 25 April. The trip took nine days and totalied around 70 flying hours, with the arrorfst tending and Spain Hill. Kirch on 13 Mey.

Due to the expiry of the permitted hours on one engine and propeller, GASSV was then grounded. Restoration work to return it to the air took around two years and included the overhaul and re-certification of the engines, propellers and various other systems. It was repeated in a right-time camoullege scheme and regarised its original RAF serial number, NGS1.1 It later encewhed the name GDV @Boon at a ceremony attended by the famous bomber pilots father.

On 6 May 1967 NX611 took off for its first sett flight. A second was flown the following day, with a third air test being carried out on 9 May. The fourth test flight took place on 17 May and after the rectification of faults encountered on previous sorties this was completely successful.

NX611's first public appearance was set for the weekend of 1920 May 1967, when the bomber was to travel to RAF Scampton to mark the 24th arriversary of the Dean Busters' in the 18 made several other appearances, but without the required amount of sponsorship funding the expense of operating it, coupled with the fact that the RAF's PA47's was flying again around the same time, was to lead to NX61's being grounded again. Its last sponsored display took locked #181m. Bits st sponsored misses.

HAPS was soon wound up, and Reflectaire Lid fook over its assets. On 30 March 1989 NX611 set off for its new home at Lavenham, Sulfolk. On 7 February 1970 the aircraft was on the move again, this time to Hullavington, Wittshire. NX6115 familie fight took place on 26 June 1970, when it set off for Squires Gatle, Blackpool, Lancashire. Since its armyal back in the UK NX6811 had made a total of 14 flights.

It was planned to establish an aviation museum at Backpool and to keep the Lancaster in airworthy trim as its centrepiece. However, the closest it came to this was during film work in February 1971 which saw NX611 carry out fast taxi runs along the main runway. This was to be the last time it moved under its own power for almost 25 years. Financial difficulties were later experienced and a receiver was called in:

An auction of the museum's exhibits was held on 29 April 1972. The sales catalogue was given the title "The Contents of the Aeronautical Museum". On the header page inside it stated: "Including an Avro Lancaster Bomber "Guy Gibson." The catalogue also mentioned that the Lancaster would taxi during the morning.

It was the last lot, No 63, its description read: 'An Avro Lancaster Bomber with black and beige camouflage, with French Air Force markings; G.L.C. registered NX611; built early 1945, adapted to carry life-boats, later christened Guy Ølsson.

This aircraft few first with the RAF, but not on operations, during the war, was rebuilt in the early 1950s and soid to the French Air Force and few on operations in French Indo-China and was on supply drops at Dien Bien Phu; acquired by the present vendor in 1965, their it was flown back from Australia to this country. It has since flown many times, particularly in relation to 617 Squadron of the RAF – The Dam Busters.

Together with a quantity of spares and parts and the jacks and quistion harness complete.¹ Even though an engine was fixed up in an attempt to impress potential buyers before the auction began at 2:00pm, surpressingly few bidders came forward and the Lanc failed to reach its reserve of £12,000 – within seems incredible nowadays. In the crowd that day was Ferd Panton.

Soon after the auction the Right Honourable Lord Librid purchased the aircraft privately. It was his desire that the Lancaster should remain in Britain. However, though NV611 had found a new owner its future was not assured. A lengthy spell of exposure to sat air and a general tool, or expert maintenance had taken the foll, and during the next winter a rapid deterioration of its overall condition followed, especially to the engines and propellers. Something needed to be done urgently otherwise the bomber could be in dianger of deteriorating severely and subsequently facing the scrape had subsequently subsequently subsequently scrape had subsequently subsequently subsequently scrape had su

Find Partion, who had himself been interested in buying the aircraft, stepped in to persuade the RAF to preserve it. In January the properties of the properties of the properties of the properties of the Lanc and concluded that it would be possible to dismantle the bomber, move it to the Linconshire bease and restore it as a static exhibit, Lord Littord visited Scampton and agreed to offer it on inpresent bane. Dismanfling work began in August, when RAF Scampton sent a team up to Blackpool. It took inite days and six Quien Mary trailer-loads to taken WK811 apart and trainsort it to Scampton it.

Following a thorough and meticulous restoration, NGI 1 was positioned at the main gate on 10 April 1974. Final reassembly began the following day and the difficult task of positioning the Lanc was completed on the 25th, when it was finally lowered onto the constructed for it. On 17 May Lord Lillord unveiled a plaque and officially handed NMGI1 over to RAF Scampton's Station Commander, Croup Captian JB. Fitzpatrick. To round off the ceremony, PAA74 carried out a flypast over the newly installed aget aguard.



BELOW Former BRMF

engineer lan Hickling



As the end of the ten-year loan period agreed by Lord Lillford approached, various parties became interested in buying NX811. Amongst became interested in buying NX811. Amongst them were Fred and Hardic Parton, who had been keen at the time of the Blackpool auction and had also been invoked in the regolations which took it to Scampton. The Lincohshire farming borthers purchased the Lancaster from Lord Lillford on 1 September 1983, its future secure, the Lanc menianed on gate guard duties at Scampton until May 1988, by which time it had soperal imans! I veem them.

The task of dismantling the bomber at RAE Scampton began at around the beginning of April 1988. In order to achieve this it had to be neved onto a newly constructed to praking area opposite the guardroom, in order for there to be a firm hard standing for all the heavy ground equipment, such as trestless, jacks and satilety raisers. The first major components to be removed were the outboard engines and all four propeller assemblies. As things progressed the fusiblesy was sight into three sections for the moved by road to East Kirkby, a distance of about 30 miles.

Following arrival at its new home, the task of putting the Lancaster back together began. This took the team from RAF Abingdon approximately four months to complete. Once reassembled NSG11 received some commetic attention and was given the codes of the former bornber station's two resident Lancaster squadrons, Nos 57 and 630. A 57 Squadron DX-C code was applied on the starboard side and a 630 Squadron LE-C code to port. Fred and Harold's long-held wish to pay tribute to Christopher and all his fellow Bornber

Command aimmen was now a reality. In 1983 they decided that the bomber shouldn't nemain just a static exhalt. Former shouldn't nemain just a static exhalt. Former RAF enginers law Hickling and Rhy Jaman were therefore recruited, and in January 1994 they begain the task of coawing the four ROIL8-Royce Meritis back to life one by one. Within just three months the number 3 engine starboard meny less ready. A first start up was carried out on 20 April — the first time one of the aircrafts engines had been run since the Blackpool auction back in 1972. This was followed by a longer run the next evening, when the site was opened to the public to watch the Lancaster's enable solving a processing of the public to watch the Lancaster's enable solving a processing and pro

It took just another three months to get the number 2 engine (port inner) going. This was ABOVE East Kirkby also boasts a restored World War Two control tower fully fitted out inside, which visitors can look around. (Jarrod Cotter)



ABOVE NX611's port side Just Jane nose art. (Jarrod Cotter)

BELOW Night-time

taxi runs by NX611

November evening


(Jarrod Cotter)

always attract a large

crowd ~ even on a cold

fired up on 28 July, when the opportunity was also taken to start number 3 and see the two inboard engines running together.

The following autumn and writer were spent overhauling various other systems, including the brakes. So delighted was everyone with their progress that thoughts now turned to getting NX611 lift to a condition where it would be abits to tasi under its own power. By the spring of 1995 the bomber was ready to roll. With both inclared surning, on 4 March BBMF Lancaster pict Flight Lieuterant Mike Chatterion sease the throttles forward and



Number 1 engine (port outer) was the next to be got running, on 6 April 1995. To celebrate 1986 it is 60th brinday in fine style, it carried out its first public task run in front of a large and appreciative covered on the 22nd of the same month. Number 4 engine (starboard outer) burst in file just under three months later, and on 13 August the Lancaster's first four-engined task run was carried out, complete with a flypast courtey of PAAT4, which lives just a few miles from East Kricky.

Since then NX611 has carried out regular taxi runs on scheduled days at the museum. Perhaps the most emotive taxi runs are those at night-time events, when the bomber can be seen firing up its engines at a former Bomber Command base in its natural operational environment of darkness.

While such a sight is impressive enough, on 14 February 2002 another milestone occurred when NXS11 performed a tail up fast taid 'takeoff' run on the remainder of East Kirkby's former runway. The wonderful sight of the Lincolnshire Aviation Heritage Centre's Lanc performing these runs was courtesy of a BBC filming contract for a drame entitled Night Flight.

This brought the sight of a Lancaster on East Krichy's runwy for the first time since around 1946, as well as being the first time NKS11's talknheel had been lifted into the air under its own power since the 1971 film work at Blackook. Nowadays the East Krichy museum site has expanded and includes a grass runway. Delight tabl runs now talee the bomber onto this, providing another exocative and rare sight, of a Lanc running on the grass. Occasionally fast taxi tali-lup runs are carried out too.



A part from the BBMF's PA474, the Canadian Warplane Heritage Museum's FM213 is the world's only other airworthy Lancaster. The type has such strong links with Canada that it is most fitting that the country boasts its own airworthy Lanc. It is painted to represent Mark X KB726, in which Pilot Officer Andrew Mynarish RCAF carried out a supremely



brave act that cost him his life to save another, for which he was posthumously awarded the Victoria Cross.

Here we ask Don Schofield, the Lancaster's training captain, what it means to have the bomber flying in the skies of Canada and how they go about it.

Q: Many RCAF crews flew on Lancasters with Bomber Command. In your experience what does it mean to them and their relatives to have FM213 flying in Canada?

A: To have a living, breathing connection with their past that they can see, hear, and touch is a multi-faceted experience for many of the veterans and their families. For many it fosters fond memories of the camaraderie of their youth and intense pricle (and relief) of returning from battles well count.

For others it is a searing reminder of the pain of the loss of comrades, or equally ugly experiences such as wounds and imprisonment. For those, however, who survived at least relatively unscathed, it is a means to explain to generations two and sometimes three their jurior "what Granddad did in the war."

I crock had the experience of meeting Jack-Friday of the original Mynarski crew who was formed to make the man and the man and after we landed we went into the canteen, and while we were having post flight the he took out hall only one the man and the meeter and sign off the relia entry, crossing out the last "mesing" line, and replacing it with "returned", with the date and time etc.

That says it all better than I ever could.

Q: How does flying the Lancaster compare to other types you have flown in your career, especially more modern multi-pistons?

A: The only similarity between the Lanc and the Airbus 330 on which I did my lest flight was that they were both Rolls-Royce powered. I have heard it said that nothing advances technology faster than a war. I was just bucky enough to have started in the pilot business in the late 1950s when we were about to go all jet. I was trained on the Chigmunk and then

Will NX611 ever fly again?

Ever since it was brought back to running order, there has been much debate and speculation about whether or not NNSE1 will one day be made airworthy, Here the Panton family give their thoughts on what it means to them to have the Lancaster at the Linconshirtie Avaidan Heritage Centre, and the latest feelings concerning its future:

latest reeings concerning its future:
"We view our Lancaster NSI-1 Just, Jane as being a living memorial and tribute to Bomber Command and all of the men and women who lost their lives operating them. There is never a day goes by when someone around the world does not talk about a Lancaster, and that shows to us its importance in

a day guest by when another a account on the other and a substant a lancaster, and that shows to us its importance in keeping the memory of the Second World War alive. Both the sight and sound of the Lancaster are enormously evocative and have different effects on different people. For some it enoxies feelings of respect and neverence, for others it symbolises audiness and result loss, and for others it evokes pride and patrioties. But however great you consider to be. If must be understood that it will never be as center as the other standards of the substantial standards.

Many people ask us if our Lancaster will fly again. To this question there is currently no definitive answer. There are three factors; the will to do it; the logistics of operating it; and the finances needed to restore.

From 1994 to 2007 we have been running the engines and from 1996 to 2007 we have been staining, therefore fight is the obvious next step. The aircraft is in excellent condition and it is not beyond the reasins of possibility to be able to fly it, after all, that is what they were made to do. There are quite a few static Lancasters in mueuems that will never be able to fly again so if seems a great wester not to fly a Lancaster that has the ability to be made airvarish; Flying XXXII Just. Airvin has rever been ruled out as a possibility and it has always been considered, but it is not something that has been decided yet. With one Lancaster already flying in Britain, we are in no rush to fly ours.

only ones. There is always ongoing restoration and repairs to Just Janu after the taxing season, throughout the winter period. Janu after the taxing season, throughout the winter period. She is looking in good stape and we hope to keep her that way. We are now trying to build up a good spares store to add the years of operation that we hope to have with the alroralt. As always we are looking for new displays that we can do, such as fall-up text runs. We view the operation of the Lucricaster as any of educating new, women and children about the aircraft and the hardships of the Second World War. We hope to be declaring people for many years to come.



skies of Canada, a flying tribute to the many RCAF personnel who flew with Bomber Command. (Doug Fisher/ www.warbirddepot.com)

ABOVE FM213 in the

BELOW Don Schofield in the cockpit of FM213 – the 'Mynarski Memorial Lancaster'. (Doug Fisher/ www.watbirddepot.com) the Harvard, so talwheel, prop-driven stuff was tour unterfaller. When I got to the T33 at AFS my reaction was "Wow, this is easy!" Other than the basic movement of controls there in or real parity between these generations of aircraft. When we were restoring the Lanc some people commented how it would never get past the modern design criteria. This in no way diminishes the fact that, in its day, the Lanc was 'state of the art.'

Q: Can you give an outline of the procedures you must use to fly the Lancaster around in the restricted airspace of North America, and the principal equipment needed?



A: Procedures and equipment. A very complicated question with an elegantly simple answer - GPS! We have a wonderful GPS on board that allows us to go just about anywhere with ease and precision. We are all active or retired airline types and all very familiar with our operating area, so it is not often a real challenge. One of the more 'different' experiences of late was operating VFR in the New York City area, all of which, by the way, was done with very detailed briefings and blessings of the FAA. Whizzing past, or rather under, the approaches to JFK at 500ft, past the Verazzano Narrows bridge, the Statue of Liberty, and looking down into the hole at Ground Zero was what modern youth would call a 'real mind blowing experience"

Although we do not as a matter of policy by in MC, the GPS I mentioned plus the standard IFR kit of VOR, DME, ADF, LORAN C etc make it pretty hard to get lost. If we are not really familiar we always get detailed briefings, often from ATC or from local pilots whenever we operate in a 'new' venue. We always carry the required flight information publications for both VFR and IFR flight and the ATC types are usually so fascinated by the opportunity to control a real World War Two aircraft that they are unfailingly helpful.

Our GPS is a Garmin 296, which is so clever that in addition to a moving map it has a complete instrument panel presentation that draws all of its information from listening to the constellation of satellites.

We have all of the required kit to operate IFR (as opposed to IMC) because it gives



us the liberty to transit big metropolitan high-density traffic areas (read: marny, marny aeroplanes) with ease and legality. We generally choose not to fly in clouds or rain unless we absolutely have to because, to be frank, she leaks like a sievel One sage said that flying her in heavy rain would probably require the installation of bilge pumps!

Q: When you fly a crew members' sortie, what's it like flying to Toronto around the CN Tower and over Niagara Falls? At Flying around Tronto and Nagara is just a matter of being internately sware of local procedures, it the Clanada Flight Supplement is very specific about flight procedures such as aircraft type, altitudes and speeds, orbit headings, directions of turns, and noise ensitive areas etc. All in the line of good flight safety. The others on board may get to watch the scenery but we are usually quite busy keeping up with variat is nowadays called 'situational awareness'. ABOVE FM213 taxies in after a sortie with Don Schofield in the captain's seat. (Doug Fisher/ www.warbirddepot.com)

Insurance and running costs

In the post-9/11 world, warbird insurance became a huge cost factor and is growing ever more so. People are becoming concerned that this could effectively halt the operation of some large multi-engined warbirds.

warbirds. The cost of insurance for a Lancaster is difficult to determine. The BBMF's example is a military owned and operated aircraft, and as such there is no private insurance company providing a policy. The Claradian Lanc is resured under a policy that provides unlereal siteatity cover for the CMHM's entire, large fleet of airvorthy aircraft. It is not rated separately, and therefore has no policy specifically airclared for it. Besides, to get a quiet for a policy by a policy place of the term to be insured, and the value of an airvorthy Lancaster is something nobody seems sheem to guess att.

he following short list provides some idea of PA474's running osts at the time of writing:

Oil – approximately £11 per gallon (37 gallons x 4 tanks).
Fuel – approximately £1.20 per litre (average 600 gallons, or about 2,730 litres, loaded per trip).

Tyres – £1,300 each; will last for 150 landings.

Brake bags – £2,000; will last for between 10 and 200 landings.

Mid-upper turret fairing – approximately £45,000.
Flame dampers for exhaust shrouds – £32,000.
Bomb aimer's blister – £4,500.
Overhaul of main undercarriage oleo –

approximately £6,500.

Cost of a Major service taking 14,858 man hour £920,528.





Chapter Four

The crew's view

(•)

Where once flying an RAF
Lancaster was a nightly task
required of many, nowadays it is a
privilege experienced by very few.
They do not take this for granted,
being fully aware of exactly why
they are airborne in this flying
memorial. The purpose of this
chapter is to provide you with an
insight into what it is like to fly in
the BBMF's Lancaster, from the
various crew members' points
of view.

LEFT With Flight Lieutenant Ed Straw as captain, this is a rare scene of the crew of PA474 hard at work during a sortie. (Ed Straw)

Pre-flight checks

internal pre-flight checks, as stated in Lancaster technical manual AP2062A-14, are carried out by the engineer, and are as follows:

External pre-flight check

Internal pre-flight check

Carry out a systematic inspection, starting at the entrance door and working clockwise around the aircraft. Check for signs of leaks and damage and check that all panels and hatches are in position and fasteners are secure. Ensure that the airframe is clear of snow, ice and hoper frost. Check:

First aid kit In position
Rear turret Condition
Tailwheel Checked, plug removed
Static vent Checked, plug removed

Pressure head Checked, cover removed
VOR aerial Flag removed
Tyres Checked, condition noted

External power supply In position, ON when required

Ground/flight switch FLIGHT, check voltage. Set to

GROUND when external power available

Intercom switches NORMAL – emergency

Navigator's radio and master RT switch ON
Navigator's instruments Condition, OFF

U/C warning horn TEST
Air intake control COLD AIR (wire locked)

Bomb door selector lever OPEN
Cantain's radio

Captain's radio ON
Navigation lights switch As required
External lights master switch As required

External lights master switch As required

U/C position indicator ON. Day/night screens set DAY.

2 greens. Changeover checked Accelerometer Baset

Flight instruments Checked
Direction indicator Caged

Landing lamps UP

Boost gauges Static readings noted

Flap position indicator Switch ON. Check reading against flap position

Fire warning and feathering button lights Test, Day/night screens set to DAY

Supercharger switch M gear

Master cocks Checked. OFF Boost control cut-out lever OFF

Throttles Full and free movement, set maximum

Pressure available (minimum 250psi)

Handbrake Pressure available (minimum 250psi)

ON, Check pressure at each wheel, handbrake OFF

Co-pilot's VHF radio ON

Radiator shutters AUTOMATIC

Emergency air selector knob In (OFF), tell-tale wire locked

Electrical services switch ON
Engine instruments Checked

Fuel contents Checked, agree with F700

Fuel booster pumps TEST in turn, check ammeter reading (3–5 amps). OFF

Tank selector cocks Checked. Set as required

Introduction

Despite the maintenance and checks carried out by the ground row, it is the responsibility of the aircrew to carry out various final checks before each flight to ensure that their aircraft is airworthy. On the Lancaster the majority of the technical checks are carried out by the flight engineer. However, the other members of the crew are responsible for ensuring that their stations are ready for flight.

Start-up

prior to the starting checks the flight engineer is to ensure that the external power, if available, is ON and the pilot (the captan) is to ensure that the undercarriage locks (4) are removed. In the following checklists P = pilot (left-hand seat):

C = co-pilot (right-hand seat);

N = navigator;

E = flight engineer; G = ground crew. BELOW The flight engineer doing his pre-flight checks. Here Wing Commander Colin Reeves examines the undercarriage. (Paul Blackah) Crown Copyright)



Pre-start checks

E700 Signed

Chacke P/C In position left and right Engineer's pre-flight Satisfactory and complete, POB

checks ('People on Board') Flying controls Full and free movement

P/C ON (P), pressure checked (C) Brakes

(minimum 200nsi)

Undercarriage Down and bolted, 2 greens

Flap selector Neutral

Padine N/C On and chacked

Master cocks

Fuel

Number ... tanks selected

Helmets

Starting checks

Crew intercom ALL Checked Emergency intercom Selected and checked, re-select

G4R inverter ON (cxDG) ('check directional gyro') Static boost Noted

ON Rooster coil master

switch

Half-inch open, friction set Throttles RPM levers Maximum friction set

Start clearance N Obtained

Anti-collision lights ON

Crew chief's start checks G All locks, covers, plug and ladder removed. Fire guard in position. Area

clear for start

Engine start-up drill

The following drill should be followed for each engine. The items in italics are stated unchallenged, but monitored by the checklist reader.

Start number 3 engine Master cock C Number 3 ON

C Number 3 ON lanition cock P/G Clear number 3 Clearance

Turning number 3

Fire warning light OUT Oil pressure Risina

rnm 1 100 Bomb doors N/G Closed

(number 3 only)

Start remaining engines in turn

Start number 4 Start number 2

Start number 1

Lancaster start-up



1 Power to the aircraft is switched on by means of the ground flight switch, aft of the forward main spar



2 The control tower is contacted to confirm that the aircraft is about to start engines, and they are informed of the number of personnel on board



The undercarriage master switch is set to ON



4 At the same time the instrument panel switch is set to ON



5 The boost coil switch is set to ON



6 The fire system light test is carried out to ensure that the system is working



7 The flap indicator switch is set to ON



8 The brake lever is applied, giving 120psi to the main wheels



The lock to the brake lever is put in place; this keeps the brakes on without having to hold the lever



10 The airscrew control is set to FINE



11 The throttle lever on number 3 engine is moved one inch forward



12 The fuel master cock to number 3 engine is set to ON







14 The outer tank fuel pump is set to ON



15 The number 3 engine magneto switch is set to ON



16 The person in the undercarriage bay unscrews the priming pump



17 He then operates the pump 8 to 12 times to prime the engine



18 The switch guard is lifted, the number 3 engine start button is pressed and the engine starts

The other engine follow the same procedure from stage 10 on.

Once all four engines have started and are up to their correct operating temperatures and pressures, the chocks are removed and the pilot then carries out engine power checks to ensure each engine's magnetos are operating correctly. During this check each engine's rpm is allowed to drop a maximum of 50. If it drops any more than this the aircraft is shut down and the fault is rectified. If the engines are within limits the aircraft then taxies to the runway.

Take-off

fter taxiing to the end of the runway. the aircraft lines up for take-off and the following checks are carried out:

Take-off checks

Take-off clearance	N	Obtained
Pressure head heater	E	ON
Radiator shutter	C	Automatic
Windows and hatches	P/C/E	Closed left (P), closed right (C) hatches
IFF	N	secure (E)

After these checks have been successfully completed the pilot will begin the run. When the aircraft reaches 90 knots it will become airborne, the undercarriage will be raised, and the following checks are carried out:

After take-off checks

Brakes

Undercarriage	P/E	UP, lights out
Climb power	C	Set
Engine temps and	E	Checked
pressures		
Flaps	C	UP, indicating selector neutral
Door	E/G	Closed and locked (locked only i leaving the circuit)

Handling pre-display checks Radios

Radios	N/C	Frequency set
Altimeters	P/N	QFE set. Compared
Crew security	ALL	Checked secure
Fuel	E	Checked and set (number tan selected,
		1 and 2 booster numbs ONI

Display brief Complete Anti-collision lights

98

Display flying a Lancaster

BMF Lancaster Captain Flight Lieutenant Ed Straw gives an insight into a typical display sortie:

Taxiing

'The pre-taxi checks are completed and once the oil temperature on each of the Merlins has reached 40° the aircraft is ready to move. As part of these checks I throttle back the two inboard engines and the ground crew remove the chocks from the main wheels. Once taxi clearance has been obtained, and the crew have re-checked everything is clear of the aircraft. I release the brakes using the lever on the left-hand side of my control column.

Once taxi speed is reached I call "thousand inboard" and the co-pilot sets 1,000rpm on both inboard engines. I then retard the outboard engines to idle rpm, thus preventing the aircraft from accelerating too much. Taxiing the Lancaster isn't difficult but takes time and practice to feel totally comfortable.

The pneumatic braking system is basic





LEFT Pre-flight briefing led by Lancaster captain Flight Lieutenant Ed Straw, who will ensure everyone involved with the sortle is fully aware of exactly what's required. (Crown Copyright)

and the technique required to taxi is to use a combination of brakes and bursts of engine power. If the rudder pedals are positioned centrally when the brake lever is applied then equal braking will be applied to both main wheels and the aircraft should decelerate in

a straight line. By applying left rudder pedal and re-applying the brakes, more braking will be applied on the left side and the aircraft will commence a turn to the left. The same principle applies for the right side, which is called differential braking.

BELOW Taxiing out to the runway. (Jarrod Cotter)





ABOVE Flight Lieutenant Les Munro

Les Munro -'Dam Buster' pilot

he following questions were put to Flight Lieutenant Les Murro cizze oso oso oso, who was one of the pilots on the famous 617 Squadron dams raid of 16/17 May 1943. Les continued to fly throughout World War Two and today lives in his native New Zealand.

weight was reduced to provide a safety margin Invariably, however, the long runway was used for most operational take offs

Q: How well could it withstand hits by flak and machine gun fire?

A: Unlike the Wellington, with its geodetic construction and consequent ability to withstand quite all of damage, the Lanc was more vulnerable. It could, however, withstand quite a bit of damage if it was not subjected to a direct hill or did not called fire.

Q: Did you ever return to base with one or more engines hit and shut down, and if so what do you remember of how the Lancaster coped?

At Chinnel coasion I had an engine failure just after telle-off and its lestimony to the power of the Merins that I was able to continue to the tagget at St Elemen with a full born board on three motions, aming shortly affer the next of the separion, and when the attack was aborted returned to base with the born's load still on board. On two other occasions I raid an engine put out of action but was able to return to base without all more high. Q: What was it like to be the captain of your crew and aircraft, and how much did you feel the burden of responsibility for their safety?

At believe that I assumed the responsibility of the captainty of aroutal and crew without any problems. The responsibility for the railety was just part of the observable splicit that I accepted without thinking of it as a major issue. By the same token other one members such as the navigation of the orient and crew on an operation. The navigator by ensuring that we don't stayly over heavily defended areas on the way to and from the target, and the gunness by searching the eight of partificities.

Q: How would you feel physically and mentally after a particularly long-distance sortie, to Berlin for example?

A: On a long trip I had no problems mentally as far as I am awars – check with my crew in the hereafter to confirm that! I think that it was only natural that you would arrive back after, say, an eight- or nine-hour trip feeling somewhat jacked, but I never reached the stage that I had difficulty in maritaining elethness.

BELOW The Lancaster BIII (Special) that dominates this photo was being flown by Les Munro. (Courtesy Les Munro)







ABOVE Wing Commander Guy Penrose Gibson, the most famous Lancaster pilot and leader of 617 Squac on the 'Dam Buster

ABOVE RIGHT The Victoria Cross is Britain's highest award for gallantry and was earned by ten Lancaster aircrew. (Jarrod Cotter)

Wing Commander Guy Gibson VC DSO and Bar DFC and Bar

the most famous Lancaster plot of all was Wing Commander Cuy Phenoso Gibbon, who formed and lad Nike 917 Squadron on the Cam Busters and of 1917 May 1943. After having dropped the bouncing borns' from the Lancaster Edisors A-10; owe the Morine Dam in Germany, Gloson steed at the stepes and accompanies the site two plots during their runs in order to draw the enemy's tie. This advocad the other plots to concentrate on the demanding task of releasing their special weepons auclessfally—at just 60 th above the vater and within they had to be released. He then led the nemander of his squadron to the Eder Dam, where with further deringated for his own salety he repeated his tactics and orios again dreve the enemy's fee to that the attack would succeed. For his advisors that right Gibson wee

awarded the Victoria Cross. He was killed on 17 September the following year while flying a Mosquito, having insisted on staying on operations when his superiors had wanted him not to.

not to.

In all, ten Lancaster alrows were awarded the Victor's Cross during World War Teo. In otherological crieds, the necipients were: Squadron Leader, John Nettleton (17 April 1942; Neg Commander Guy Gibbon (1947) May 1943; Right Leutenart William Reid.

Discernibler 1943; Seggent Norman Jackson. 28 April 1944; Pibt Officer Andrew Mynands (12 Junn 1944); Stragent Norman Leader Leader Leader (14 August 1944); Wing Commander Learnard Chestine (8 September 1944); Staudorn Leader Chestine (8 September 1944); Staudorn Leader Leader (14 August 1945); Wing Commander Learnard Chestine (8 September 1944); Staudorn Leader (15 September 19



'Once the aircraft is turning, opposite brake is required to stop the turn and point the aircraft in the required direction. The aircraft has considerable momentum in the turn, and opposite brake needs to be applied with some anticipation in order to stop the turn at the desired heading. However, once confidence has been gained using the brakes it's helpful to make use of the outboard engines. For example, if you want to turn to the right a burst of number 1 engine will start the aircraft turning, and - with the appropriate anticipation - a burst from number 4 engine will stop the turn. The advantage of using the outboard engines instead of the brakes is that no system brake pressure is expended.

'The Lancaster is taxied using a combination of these techniques. Throughout the taxi, the system brake pressure is continually monitored on the triple pneumatic brake gauge on the right-hand side of the cockpit, to ensure that

the pressure is adequate. Fully charged system pressure is 450psi and the minimum pressure for taxi is 200psi. Small compressors on three of the four engines help replenish the system.'

Take-off

'Having taxied onto the runway I line the aircraft up with the nose pointing to the right of the centreline, so that I'm locking to the left of the nose along the line of the runway. Once all the pre-take-off checks are complete, I call "Zero boost" and the co-plot advances the throttles until zero boost is indicated on the cauces.

"Holding the aircraft on the brakes, with it straining to move, I re-check the engine instruments before looking at each engine. If all is well I release my grip on the brake lever, allowing the aircraft to start moving. I anticipate the swing to the left with right rudder and may even use some right brake to keep the aircraft straid. ABOVE Captain and co-pilot on hold awaiting clearance to move onto the active runway. (Ed Straw)



ABOVE During the take-off run the tailwheel is raised off the ground very quickly to adopt the correct attitude for rotation. (Jarrod Cotter) 'On take-off the Lancaster has a marked wing to port which has to be countered immediately if directional control is to be maritariand. This swing is more pronounced if the surface wind is from the left because, being a tail dragger, the aircraft will want to "weathercock" into wind, if the wind is from the right this heips me to control the swing. Once satisfed that the rolling line is good, and anticipating more swing with power applied, I call for "Plus 7".

The co-pilot advances the throttles evenity and the noise level rises dramatically as the Marins come alive. I counter the further swing to the left with increasing amounts of right nudder, while keeping the control column fully back to keep the tabhwell or the ground. It's not uncommon to use all available right nudder not keep full to the carry stages of the run some right brake may also be required to keep the aircruit attaight.

'As the speed increases the situation quickly improves, as the greater airflow over the rudders means they become more effective. Once I sense the increased rudder authority I push forward on the column to raise the

tail and gain the take-off attitude. As the tail rises the rudders come directly into line with the propeller slipstream, providing even more rudder authority, and the need for right rudder is considerably reduced.

"Throughout the take-off I'm looking straight down the nurway, using the nudders to remain on the centreline, and alleron to keep the wings level. The co-plict, holding her throttles in position, is monitoring the engine boost and pm gauges while the navigator calls the indicated airspeed. At 90 knots [100mph] he calls "Rotated" and I pull back on the control column and select a very shallow climb angle. Once airbornel squeeze the brake lever on to stop the wneets rotating, then of, and call "Gear up." The flight engineer selects the gear lever to the up position and I see the two red lights illuminated to my left side to signify the gears it stavelling.

I maintain the shallow climb angle in order to accelerate the aircraft more quickly and therefore be better placed should we suffer an engine failure. I wait for the two undercarriage lights to go out, signifying the wheels are up, and then re-check the airspeed and altimeter.

Once we have 120 knots [138mph] and 150ft indicated, I call "Raps up". When the co-pilot selects the flap lever to up there's a pronounced nose drop with the Lancaster. I anticipate this by pulling back on the control column to maintain the attitude.

With the airorant now accelerating through 100 knotes (1500mpl) call for "Plas. 4, 24", meaning I want plus 4 boost and 2,400pm — the Lamossier's normal ciril bower setting. Achieving the required setting sint as straightfloward as it may seem, and it takes some getting used to. The throttles are moved first and boungth back to plus 4 boost. Then the pm levers are lowered to reduce the engine.

The co-plot will set the approximate rpm before accurately setting the inboard engines using the rpm pauges. He'll then synchronise each outboard engine by looking through the already set inboard prop. adjusting the outboard proputil if stops moving in relation to the inboard propeller. He then repeats this for the other engine. With the co-plot selecting

climb power, I call for the "After take-off and climb chocks", which the navigator will call out from his checklet. Meanwhile, I have climbed the aircraft at 140 knots [161map] to 500 or perhaps 1,000ft and leveled off. Once 150 knots [172map] singeoed is indicated, I call "Zero 1900" – zero boost and 1,900pm – and the co-plot will repeat the process for this new setting. This power setting results in an indicated airspeed of 150 knots, our normal cruise speed, with a fuel consumption of approximately 150 gallons per hour."

Display

'Displaying the Lancaster is extremely rewarding and in many ways easy. By "easy", I mean that being such an loonic aircraft the Lancaster does all the hard work of impressing the crowd for me. I have no need to perform energetic manosuvres or adopt extreme attitudes, nor would! I ward in.

'We know the public want to see, hear, and feel the magic of the aircraft and we can BELOW The first pass of the Lancaster display is carried out in 'clean' configuration. (Jarrod Cotter)





achieve all that with the gentle manoeuvres we perform throughout the display. We are keenly aware that the Lancaster is a priceless piece of national heritage, and my responsibility as pilot is to display it gently and safely and not subject the airframe to unnecessary fatique.

The classic sight of the BBMF is as a three-ship formation, the Lancaster leading with a Spattife and Hurricane on either wing, Ramingi not he display when I line up and fly the acroralt along the display line in the up and fly the acroralt along the display line, at 300H and approximately 150 knots I SHA*mphl, As we reach the end of the display line, or at an appropriate point, the nesigitors will call "Fighters, break break port, On the word "Cos" the Spatters break away, and once clear I manoseuve the Lancaster to hold position behind the crowd at 500H.

'The first fighter will commence his display, lasting approximately 4 minutes 30 seconds:

ABOVE View over Flight Lieutenant Ed Straw's shoulder as the Lancaster flies over Duxford's runway. (Crown Copyright)



RIGHT Pass with bomb bay doors open. (Jarrod Cotter)

106 LANCASTER MANUAL the second fighter display will be shorter at approximately 3 minutes and 30 seconds. We receive "1 minute" and "30 seconds to go" calls from the fighters and I use these cues to accurately position the bomber for the takeover. The final pass of the second fighter is at 100ft along the display line, pulling up into a victory roll. The Lancaster should be running in to take over as soon as this victory roll is complete.

'When we receive the "1 minute" call I instruct the co-pilot to increase the engine rom to 2,400 and re-confirm that all the pre-display checks are complete. These checks ensure that the aircraft is correctly configured to safely carry out a display. I commence my first run at 100ft and 160 knots for a "clean" pass along the display line, allowing the watching crowd to absorb the magnificent sight and sound of the Lancaster.

The navigator will call display datum and start his stopwatch, calling the time in seconds beyond the datum. At an appropriate time beyond the datum, based on the wind and length of crowd line. I initiate a climbing turn to 500ft and bank the aircraft away from the crowd in order to return the Bomber to "crowd centre". Once the climb is commenced I call "Minus 4" (minus 4 boost) and as soon as the airspeed reduces below 150 knots call "Bomb doors open".

The bomb door lever is by my left side but, because I have both hands on the control column throughout the display, the navigator behind me has to lean forward and operate the doors. I see the amber light illuminate in front of me, signifying the doors are opening, and call "Zero boost" to stabilise the airspeed at approximately 140 knots. I continue turning the aircraft back towards the display datum and

BELOW View out of the cockpit over number 3 engine, with a large crowd on the ground at the Imperial War Museum Duxford - the new 'AirSpace' hangar dominates the site. (Crown Copyright)





ABOVE A wheelsdown pass is another aspect of the bomber's display sequence. (Jarrod Cotter) descend to 300ft and fly in front of the crowd with 30° to 40° angle of bank, allowing them a good view of the bomb bay.

"From "crowd centre" I continue this turn through 360°. Any turn in the Lancaster requires the pilot to "lead" with a good deal of rudder, as well as using alleron, and throughout this turn I often need to make large control inputs, particularly in alleron, to maintain the desired turn. With the bomb doors open I also need to maintain the airspeed below 150 knots.

'Halfway around the 360° turn I have climbed to 400ft and call "Bomb doors closed", and the navigator operates the lever. I continue the turn, checking the bomb door light goes out to

confirm the doors are shut, and complete the turn with a second pass through display datum at 300ft, tracking away at 45° to the display line in a gentle climb. I check again that the airspeed is below 150 knots and call "Below 150 flane 20°.

"The co-pilot will move his left hand from the throttles to the flap lever on his left side and push the lever down whist looking at the flap gauge on his right side. Once the flap indicator gauge shows 20° he returns the flap lever to neutral and both hands go back on the throttles.

'Having re-checked the airspeed I call "Below 150, gear down" and the flight engineer



lowers the undercarriage lever situated between the seats and the undercarriage starts to move. I am made aware of this by the noise of the wheels lowering and by the two red lights appearing on the left-hand side of my instrument panel. I commence a gentle turn back towards the crowd, checking that I have two green lights to indicate that the undercarriage is down, and position the aircraft to fly down the display line at 100th in the "approach" confountion.

'Approaching the display line in a gentle descent at 120 knots I call "2850" and the copilot raises the rpm levers, increasing the engine rpm from 2,400 to 2,850. I continue to monitor the airspeed and call for the appropriate boost setting, normally zero boost, to maintain 120 knots. Now on the display line approaching crowd centre, I squeeze the brake lever on, then off, to stop any wheel rotation, and call "Gear up". The flight engineer moves the undercarriage lever to the "up" position and my two green indicator lights turn of

'Next, just before display datum, I call "Plus 7", the co-pilot pushes the throttles forward and we experience the fantastic noise and surge of the four Rolls-Royce Merlin engines. I bank the aircraft away from the crowd and aim to track out at 45° to the display line, climbing to 500ft. With the surge of engine power the aircraft tries to pitch nose-up, so as well as turning I am pushing forward on the control column. I wait until we accelerate through 120 knots and call "Flaps up", the co-pilot obliging. At this stage the two fighter aircraft are closing in on the bomber to re-join on the wing, so my flying needs to be as smooth as possible as I position the Lancaster for the final pass. I maintain plus 7 boost and 2.850rpm until 140 knots is achieved and call "Plus 4, 24' (plus 4 boost, 2.400rpm).

The airspeed is important here because the fighter on the inside of the turn will be slower than the bomber. For the fighters, particularly in close formation, any airspeed below 140 knots is slow and very uncomfortable, so, as the formation leader, I must ensure our airspeed is in excess of 140 knots and preferably above 150.

"The first jess along the display line is at 500ff in three ship formation. Descending from 500ff in the ship for "Plus 2" or "Zero boost" to maintain airspeed in excess of 150 knots while keeping at 2,400 pm. If the formation intends to land at the venue the final pass will be planned in the direction of the inuse runway, so that at the end of the crowd line the margiagtor and "Fightres, break break go", whereupon they can initiate their break to land.

The Lancaster will continue up-wind to allow sufficient space from the fighters ahead-before turning downwind at 500ft to land. The entire BBMF three-ship display is given a 15-minute slot by display planners, while the Lancaster display alone takes approximately five minutes.

'Finally, it's worth mentioning just how busy the rest of the crew are throughout the entire Lancaster display. The navigator and flight engineer aren't only selecting the services as described, but are helping with lookout. positioning, and clearing turns, as well as fulfilling their individual tasks. The flight engineer monitors his panel, checking the health of each engine and managing the fuel, while the navigator operates the radios, as well as making preparations for the next venue. The co-pilot is kept extremely busy, continuously adjusting the throttle and rom levers and synchronising the engines. Finally, all three have the very important task of monitoring my performance. checking that my actions are correct and safe. and offering support if required. Displaying the Lancaster is a team effort.'

BELOW Heading in towards Duxford's Runway 06. (Crown Copyright)

Circuit and landing

"The Lancaster circuit is flown at 500ft and is most appropriately called a "Bomber Circuit". When on the downwind leg I confirm 2,400rpm and zero boost is set, then check that the airspeed is below 150 knots and cal "Below 150, gear down". The flight engineer lowers the undercarriage lever and I hear the noise of the wheels travelling and see the two red indicator lights illuminated. I wait 20 to 25 seconds for the two lights to go green, indicating the wheels are down, and call "Below 150, flass 20".

The co-pilot lowers the flap lever until the flap gauge shows 20° and then returns the lever to neutral. With flap I have to move the control column forward to maintain the attitude and re-trim in piloth.

"I then request the pre-landing checks, which are challenge and response checks initiated by the navigator. He calls "Undercarriage". I check that the undercarriage lever is down and that the safety both is over the top of the lever, and re-check that I have two greens indicating the wheels are locked down. I respond "Down, botted, two greens".

'Next he calls "Brakes". I check the brake lever is off and call "Off". The co-pilot looks at



the triple brake pressure gauge situated on the right side of the cockpit and checks that there is good system pressure with no pressure at the wheels. He calls "Good pressure, zero at the wheels".

The navigator then calls "Rpm", The copilot checks the rpm is 2,400 and calls "2400". Then the navigator calls "Flag", and the co-pilot checks the flap gauge and lever and calls "Flaps 20, indicator neutral". After this the navigator calls "Pre-landing checks complete".

"I extend the downwind leg of the circuit until the runway threshold is behind the trailing edge of the wing before turning "finals". There's no need to turn early, as the best approach is a long shallow one — a steep approach is not recommended.

"I call "Flap 40". The co-plot lowers the flap lever to 40" while I push the control column forward to maintain attitude and initiate the turn. The navigator then calls "Lancaster finals, gear down", and once established in the turn I call "2850", the co-plot raising all four more levers to increase engine rpm to 2,850. My airspeed is 125 knots.

"At this stage I re-check the boost gauges, as often the boost has dropped off a fitte, and the co-ploif resets zero boost. The navigator calls cut the final approach checks, which confirms that landing clearance has been obtained, the flap is at 40° and yram is 2.850. I am aiming to action eithe arise ped to 90 knots (103mpt) over the threshold and ideally want 105 knots (120mpt) half-way around the turn. On the approach I will call for "Minus 2", "Minus 4", and "Minus 6" to reduce the airpack oboking to be at minus 6 and 90 knots just above the touchdown point.

Due to weather no two days are exactly the same, so the point at which I ask the co-pilot for these power reductions will vary. If ye a shallow approach, working hard to remain exactly on the centreline, and in the final stages use a "wing down" technique to deal with any crosswinds. At approximately 200ft I change from tracking the aircraft down the centreline to pointing the

BELOW The final pass is another 'clean' flypast. (Jarrod Cotter)



PA474 flight test schedule

Current aircraft limitations and restrictions are not to	AFTER START					
be exceeded.	After starting No.3 –					
	Close Bomb Doors satis/unsatis					
GENERAL DATA	At 1,200 RPM No.1 No.2 No.3 No.4					
Pilot	Oil pressure (Min 30psi)					
Co-Pilot.	Oil Temperature (Min 15°c)					
Engineer	Rad Temperature (Min 40°c)					
Navigator	Fuel Pressure Warning Light on/out on/out on/out on/out					
Basic Weight	Magneto Dead Cut yes/no yes/no yes/no yes/n					
Fuel Weight	Generator Charge (1,300rpm)					
Aircrew Weight	Vacuum					
Other Load	Voltage volts					
Take-off AUW						
	TAXIING					
CERTIFICATE OF AIRWORTHINESS	Check operation of:					
Certified that this aircraft has been flight tested in accordance						
with the appropriate Flight Test Schedule and that it is:	Magnetic satis/unsatis					
*a. Airworthy and functionally serviceable to the required	DI satis/unsatis					
standard.	Turn & Slip satis/unsatis					
*b. Airworthy and functionally serviceable subject to minor	Maximum Brake Pressure at each wheel Portps					
rectification as entered in F700 and does not require	Stbps					
further tests.	Function of Brakes, judder and fade,					
*c. To be retested after rectification as entered in the F700.	Captain's Port satis/unsatis Remarks					
	Stb satis/unsatis Remarks					
Signed	Co-Pilot's Port satis/unsatis Remarks					
Name	Stb satis/unsatis Remarks					
Rank						
Date	PRE-TAKEOFF At Zero Boost No.1 No.2 No.3 No.4					
*Delete as applicable.	PRI 1					
	RPM					
AIRCRAFT GENERAL	Oil Pressure (min 30psi)					
Ambient Air Temperature OFE	Oil Temperature (min 15°c)					
	Rad Temperature (min 60°c)					
	Mag Drop Port (max 150)					
Brake Pressure Port	Mag Drop Stbd (max 150)					
Brake Pressure Stb	Supercharger Operation yes/no yes/no yes/no yes/no					
Emergency Air Pressure	Generator Charge amps amps					
(1,100 to 1,200 lb/in)	TAKE-OFF					
Hydraulic Accumulator Pressure						
(220 lb/in)	Start timing at zero boost and brakes off.					
Voltage Fuel Contents No.1 Port	Open throttles to +7 boost. Unstick at knots IAS					
No.2 Port No.3 Port	Climb at 140 kts. With +4 boost and					
	2400 rpm to 7000ft if possible. Time to 3,000ft, min, sec					
No.1 Stb						
No.1 Stb No.2 Stb	Time to 5,000ft min sec					
No.1 Stb						

CRUISING					LANDING/SHU	T DOWN					
At 3,000ft, fly at 150 kts a	nd 2,000m	om.			After landing, at	1,200rpm:	No.1	No.2	No.3	No.4	
In steady conditions	No.1	No.2	No.3	No.4	Oil Pressure						
Boost					Oil Temperature						
Oil Pressure					Rad Temperature	(max 100°)				
Oil Temperature (max 90°c	After shutting down engines 1, 3 and 4.										
Rad Temperature(max 150	ρ°c)				Operate flaps full	y down the	n fully up		Satis/l	J nsatis	
Supercharger Operation	yes/no	yes/no	yes/no	yes/no	Fuel Contents	No.1	port		Galls t	sed	
Generator Charge						No.2	port		Galls u	used	
Voltage				volts		No.3	port		Galls t	used	
Hydraulic Accumulator Pre-	ssure (600-	-1,000ps	0	psi		No.1	stbd.		Galls u	ised	
Trim: Elevator Trim	. Div	Nose (up/down	/neutral		No.2	stbd.		Galls u	used	
Rudder Trim	. Div	Port/S	tarboard	/neutral		No.3	stbd.		Galls	used	
Aileron Trim Div Port/Starboard/neutral				l/neutral	Total flight time .		Total fu	uel used			
					INSTRUMENTS						
STALLING					Check each instr	ument for fu	unction:				
Aircraft clean, Pitch fully fine, Throttle closed					Compass satis/ur				nsatis		
Stalling speed (onset of bu	uffet)		Kts		DI			satis/u	nsatis		
Staling speed (full stall)		1	Kts		AH			satis/u	nsatis		
Wing Drop				Vneutral	T&S		satis/unsatis				
Undercarriage and flaps lowered Kts				Altimeter		satis/unsatis					
Wing Drop				/neutral	RCDI		satis/unsatis				
					ASI			satis/u	nsatis		
OPERATION OF UNDER	CARRIAG	E AND	FLAPS.		RADIO						
At 150kts straight and level time the following:					UHF satis/unsatis						
Undercarriage down			secs		VHF			satis/u	nsatis		
Flaps Down			secs								
Flaps Up											
Undercarriage up					GENERAL REM	ARKS					
Bomb doors open			secs								
Bomb doors shut		5	secs								
ENGINES											
At 2,000ft, 150kts and 2,0	000rpm:										
	No.1	No.2	No.3	No.4							
Boost											
Oil Pressure											
Rad Temperature											
Feathering	yes/no	yes/no	yes/no	yes/no							
Unfeathering	yes/no	yes/no	yes/no	yes/no							
Generators	8	mps	8	amps							
Remarks											
Remarks											

RIGHT Time for the captain to take the Lancaster home to Coningsby.



nose directly at the runway and preventing any drift by banking the aircraft into the wind, hence the term "wing down technique". To prevent the



Lancaster turning, I input opposite rudder to keep it on the centreline.

Coming over the threshold my aim is to descend until the wheels are two to three feet above the runway and level off momentarily. It re-check I have the Bornber absolutely straight before calling "Cut". The co-plot gently relateds the control column while looking straight down the runway. The main wheels should bouch grantly down on the runway, whereupon I call "Flap up" in order to take the lift from the wings and transfer the weight of the aircraft to the wheels. It is very important to keep the aircraft traight at this point and I do this using rudder, while keeping the wings level with alierons.

'Once the aircraft is settled on the main wheels and decelerating I gently pull back on the column to lower the talkheel. If necessary I'll apply some brake and complete the landing run. Once we've decelerated to taxi speed I call for the after landing or becker.

RIGHT Flight Lieutenant Ed Straw signs the aircraft in. (Crown Copyright)



LANCASTER III III & X - Parachute Drill (With Static Line)



Emergency equipment and controls

echnical manual AP2062A Volume I provides the following details regarding the emergency equipment carried aboard a Lancaster during the Second World War:

Fire extinguishers - The automatic fire extinguishers mounted one in each nacelle may also be operated by the pilot from pushbuttons on the right of the instrument panel. Six hand fire extinguishers are provided, of which one for the pilot is mounted on the port cockpit rail.

Parachute and crash exits - Parachute exits may be made from the hatch in the floor of the nose or from the main entrance door. The pilot's parachute is stowed immediately behind his seat on a panel at the end of the navigator's table. The hatch in the nose is released by means of the handle at the centre, lifted inwards and jettisoned through the hole. Three 'push-out' type emergency exits are fitted in the roof of the fuselage, one in the canopy above the pilot, one just forward of the rear spar, and one above the rear end of the main floor. These should not be used as parachute exits.

Dinghy - A Type J dinghy stowed in the starboard [main]plane may be inflated and

released in any of three ways: (i). By pulling the release cord running inside the fuselage along the roof aft of the rear spar.

(ii). From outside by means of the loop on the starboard side adjacent to the leading edge of the tail plane.

(iii). Automatically by an immersion switch. A special emergency pack is supplied with the aircraft; it is carried in the dinghy compartment stowed on top of the dinghy to which it is attached by means of a lanyard. In addition to this pack, standard emergency packs Type 4 and Type 7 are stowed on the starboard side of the fuselage, just aft of the rear spar.





LEFT Entrance to the rear gun turret, showing the gunner's parachute stowage position. (Paul Blackah/ Crown Copyright)

Crash axe and first-aid outfit – These items are stowed on the starboard side aft of the entrance door.


Fuel jettisoning – The contents of both No.1 fuel tanks may be jettisoned by lifting and turning anti-clockwise the hydraulic control handle on the left of the pilot's seat. The flaps should be lowered 15 degrees and speed reduced to 150 mb IAS before lettisoning.





FAR LEFT First-aid outfit, stowed on the starboard side aft of the entrance door and accessed by pulling the handle. (Jarrod Cotter)

LEFT Emergency equipment at the rear spar, including fire-axe and gloves. (Paul Blackah/ Crown Copyright)



(RAF Museum)

If the flaps will not lower by the hydraulic system, do not attempt to lower them by the compressed air system, as this will also cause the undercarriage to lower.

Bomb jettisoning - The complete bomb load (excluding bomb containers) may be jettisoned after the bomb doors have been opened, by means of the jettison handle fitted on the right side of the instrument panel; if bomb containers are carried they should be jettisoned first by the bomb container jettison switch fitted to the left of the bomb jettison handle.





Navigating the Lancaster

BMF Navigation Leader Squadron Leader Jeff Hesketh profiles the role of the 'Nav':

As anvigators know, preparation is all-important in in the custome of a sortie, flypset of display To this end, for each upcoming season the flypset and display bid as eroclated by the previous October, a rough outline plan is then proposed by New Year and fireful up by March. Sorties range from annual features such as Biggin Hill and Dubdord, where we'l find away," to others varying from local to national importance or remembrance.

The Lancaster is only allocated 100 flying hours during the display season, to preserve fatigue on the airfarme. However, 110 hours are actually planned, knowing that some hours will be lost due to inclement weather and also aircraft unserviceability. These hours also have to include plot and newayator training, display work-up and Public Display Authorisation fights. Intial event training is completed by the BBMF Adjutant, who does an outstanding job in beaping table on every detail of administration.

To minimise flight time, the initial triving plan is based on a stright time from Complety to the display/flypast venue flown at 150 knots (deeps the mental maths easy – 2½mm per minute), together with a timing four-minute hold at the IP or "Initials point" – a distinctive feature overtical or hortocrain alorter, og a mast, road junction, forest shape or lake – if it is a "timed" hypast such as a Royal event or graduation revue. More details are put on the plan by the may fact when the strength of the may be presented to the result of the may be supported to the plan by the time of the may be supported to the property of the may be supported to the plan by the may be supported to the major to the plan by the plan by

"These charts are further embellished with the radio frequencies required, thimps, tracks and distances, together with potential diversion antifield details. For a display we always plain to "run in" in the direction we wish to "run out," to achieve minimum flying time to the next event. Quite often two routes are planned whene a transit is required over high ground, one "straight line" for good weather and a bad-weather coffor taking a long for lawling and abd-weather coffor taking a longer lower route "straight line" cover the Pennines to the "straight line" cave with the straight line straight



North of Manchester Control Zone for good weather, while we have a back-up route flying through the Crewe to Wigan corridor in case of bad weather over the hills – and still make the venues on time!

We try to avoid flying through the "chain link fences" of controlled airspace, but many times it's unavoidable and requires co-ordination by the negligator with he ATC unit involved. Almost without exception were allowed into their controlled airspace. We plan to avoid glider sites and light airfields, used predominantly at the weekends and Bark Holddays, not to mention the danger areas, firing ranges and restricted airspace that invessingly over the UK.

If we are in radio contact with airfields as we transit from vanue to versue and the ATC request a fly-through, then proxiding it does to interfere with our thining we are more than happy to oblige — cleared down to 100tt and 300tt. The Lancaster flying on its own is planned to fly at 1,000tt utilising the low-level flying system. This is to avoid the increasingly buy general airchite traffic above. It's quite ABOVE Squadron Leader Jeff Hesketh is the BBMF's Navigation Leader.

(Crown Copyright)

entertaining when a private Cessna tries to fly near the Lancaster, perhaps blissbluly unaware of our "fighter scort" 2,000ft abovel At Nav School we were always taught to avoid large towns, but with this aircraft it's appreciated if we fly over. The Lancaster attracts no noise complaints, only comments such as can we come back again and lower!

'Many of our trips are what we call 'Out and back', where the Lancaster takes off from Coningsby for, typically, fire flypast locations (three passes each) and two display locations (each five minutes), and then returns to base. This example equates to seven events for one aircraft on one day. The flight time for this is typically 70 minutes.

'These types of sortie save our ground engineers time travelling to turn the aircraft and, in addition, should we happen to go u/s it would be at Coningsby. In the 2007 display season more than 700 individual

initially planned 573 events, which comprised some 110 displays and 463 flypasts – not a bad achievement for volunteer alicrew, and a testament to the dedicated maintenance undertaken by our 27 engineers.

'Due to the distinctive sound of the four Merins and our stow speed compand with modern-day jet fighters, many observers on the ground soon become aware of our presence. On many transts, oricket matches are stooped; golfers wave and housewives are seen vaving tea towels deathing into their gardenic; cars stop ahead and their occupants stand and wave. A far cry from World Wei Two.

"Flying down to 250ft, which is our minimum height outside airfields and over England's green and pleasant land, it is a very proud feeling indeed. In the Lancaster, the navigator stands behind the pilot, map and stopwatch in hand, using his "Mx.1 eyeballs" to view over the pilot's shoulder or look out of the blister to the side hank to basiss indeed. To aid us we sometimes.



BELOW Approaching

RAF Wyton for the

sunset ceremony as

described in the text.

with the white water

tower (visible to the

right of the canopy)

used as a reference

point, (Paul Powell/

use a stand-alone Garmin 496 in the Lancaster, to act as secondary aid to map and stopwatch and to give an accurate groundspeed display.

The navigator is responsible for the R/T, using the radio, with callsign "Lancaster", and using the IFF, which is located on the Nav table behind. In summer it can get very hot in the cockpit, with the canopy acting like a greenhouse. Low-level flying requires fix points with vertical extent - masts, chimneys and so on - but above 1,500 feet we can use lakes, forest shapes and towns, so our fiving is a blend of the two. Basically we navigate with a heading and time for that navigation leg. working from big feature to little feature for our tracking, slowly inching or "walking" our fingers over our prepared maps, which have been folded to achieve maximum effect and fit our nav bag - when you see the crew walk out to the Lançaster the navigator is easily identified by his distinctive nav bag.


"We describe the next turning point to help

the plots find it, and this is crosschecked against our timing at the turn as to whether we are early or late. Often it is the nax's hand pointing "over three" that steers the way, but all oreas work together in the bast interests all oreas work together in the bast interests or oreas reasons and lock just in front, but soon you get to find masts minutes ahead so you can settle down to timing checks and maybe admire but view.

The Lancaster is only allowed to fly VFR (visual light rules) and not in the dark—that calls for interesting planning where a sunset coerancy at Shrwerham (near Swindon) is required, so as to return east to Coringsbly and still and before dark. Very strong emotions are fet by the crew at this time, under the Perspox canopy, as the engine exhaust stubs glow red the thought goes through our minds that it would have been this time of night that the actual bombing raids would have taken off in the war—with many crews sagif wor feeturning.

BELOW A final banked pass shows a delighted group of veterans enjoying the sight and sound of the Lancaster.

(Paul Powell/ Crown Copyright)



"Flying the Lancaster in formation with the Solftée and Huricane we use the collective call sign "Memorial Flight". Here planning is slightly different — we don't plan to fit you re large towns, as the fighters have a glicing range of 1.5 miles per 1,000 feet should their angle engine fail. The Lancaster still files alt 1,000 feet both the fighters will be above in the block, anything from 3,000 to 4,000 feet. I'm told by the fighter plots that occasionally the Lancaster can be lost from sight — not only due to their poor downward vaibility, but because the camouflage works as well today as it do in 1945!

A further consideration is that when in formation we have to avoid any precipitation as this could cause the fighters' wooden propellers to delaminate, whereas the Lancaster's are metal. In addition, we have to be aware of diversion airfields, which must have a supply of AVGAS for the fighters.

The Lancaster's speed range in formation is limited, if were early, we can't if you slowly because of the fighters – topically below 130 chots – and if we're late we can't accelerate as fast as they can – max 200 krosts. Often the Lancaster and fighters separate after one event and by independently to delayse and fypasts, then form up at a nominated time and rendezous for a throse-tip formation display at a major venue before making a night stop away from home base.

In 2006 I was privileged to navigate the Lancaster for the Queen's 80th Birthday Flypast in June. This was only one part of the day's events — albeit a major one. Flying from Coningsby with four lighters, our first event was a photo shoot en route to a flypast at Waterbeach, followed by a hold at Fairlop for the flypast at Buckingham Palace.

The Lancaster was to lead the flypast of 49 aircraft of 15 different types, one of the largest formations of aircraft seen over London since World War Two. "Memorial Flight" was our call sign for the Lancaster leading two Spitfires and two Hurricanes, with "Windsor Formation" running in from Clacton at much greater speeds one minute behind.

'The timing was perfect – too early and Her Majesty would not have been on the balcony, and too late and I would have had 44 fast jets coming in close behind me at 280 knots at one minute spacing/ An immediate right turn on top of the palace put the Memorial Fight over Lords Cricket ground. Play was stopped for several minutes – what a sight and sound – leather on whole and eight Piblis Royce Menin regimes passing 800th overhead. Rouring over the RAF Museum to the north clearing Lordon Zone, we then passed south-east over the Queen Estabeth II Bridge to Margate with a Spittle and Hurricane for a formation display, and finally lended at Menaches.

Other flypasts aren't as grand as that often they're menorial cains but of stone, perhaps at the edge of a forest or at a road junction, as a memorial to a downed orew, with just a handful of people in attendence, but nevertheless still as deserving and carried out with the same portessionalem. If the validity is on limits and we are looking out for a group of people accurate newlystin and immig is vital, as we don't want to commence a series of flypast at a nearby car floot self Limits are 3.7km, 700ft doud base for transit, 5km and 1,000ft for displays.

'On the day of a sortie the crew attend a meteorological briefing two hours prior to take-ord, and this can often call for a rapid replant The knock-on effect requires new ETAs for the display organisers, and flypast events to be passed or confirmed. Some rea cancelled due to the weather in some areas being below unlimits. A new pain is then calculated. NOTAMS (Notices to airmen) are checked, inclinating that the fight will be active within a radius of two miles around the venue and up to 2,000th attitude 15 minutes either side of the cliciplay time – professionally we strive to be on time.

"A crew briefing by the captain is given one hour before taken', covering sortic overlew, trimings, weather, fuel, performance, check-in frequencies and "obes plane" in researches and "obes plane" in case one aircraft drops out!. The navigator briefs the route, settly satisface, diversions, Reyal fights, and the all-important time check, together with wind, frequencies to use, times, orientation of the venue and crowd lines at the display or flypsat venue. The display by the Lancaster can involve either a "tall chase" or "back-or" take-over from the fighters – this may very at each deplay during the sortie.



LEFT Target map with the times and run-in route shown in detail. The IP is within the square and the target is marked in red in the triangle. (Media Licence 100043870 Ordnance Survey/Crown Copyright)



ABOVE Navigator's H2S equipment. This was a ground search mapping radar system used as a fixing aid or for blind marking, introduced in 1942. There were severe restrictions on its use in order to reduce transmissions on which enemy nightfighters could home. A fix was given as bearing and distance from an identified ground feature on the plan position indicator (PPI). The operator's skill in reconciling the PPI display with standard topographical maps was the key to accurate marking or flare dropping. (Jarrod Cotter)

"At 35 minutes to go an "out brief" is completed by the captain. With the correct legal authorisation completed, the crew board at 30 minutes before take-off. The engines start at 15 minutes, and run-ups on the mighty. Merin engines are followed by a timed takeoff to make the flypast procisely on time and to preserve fingling hours on the Landstet. It's the culmination of weeks of planning, flaws, telephone calls and e-mails to ensure that the aircraft is exactly where it was planned to be and at precisely the required time.

The map shows a route from RAF Connigsty to RAF Wyton on the occasion of an evening Sypast for the Battle of Britan Reception attended by several veteran in "Pathfinders," RAF Wyton was the home of the Pathfinders, "RAF Wyton was the home of the Pathfinders," RAF Wyton was the home of the Pathfinders, which, "Bard RAF" was the and eleven Mosquido squadrons, located in the vicinity at Wyton, Esangton, Crenely and Warboys. The map shows the latest take-off Warboys. The map shows the latest take-off time – corrected for vind (18:50.1.— the flight always works in local time) to meet the time on tareet (TOT = 1915. Initial air traffic control is with Coningsby departures, within is studied on a pre-set frequency on the radio behind the navigator. Take-off is completed using the Conjapty OFE setting on the altimeter – transit height 500th. Once clear of the military air traffic zone the regional Barresley setting is set, and once clear of Conjagby radio communication is next with information service). Routing is then to the west of Coviland gliders set to a turning point north of Peterboruigh, denoted by a railway line crossing a liste.

"At this turning point a timing check will be made and the spoed adjusted, together with a change of radio frequency to Peterborough Corinjoton, with the navigator asking for any traffic information. Neat leg is onto a track of 159" – corrected for driff to the IP (avoiding Upwood glider sels), to a roundatout to the east of Wartoys. During this leg the regional pressure setting on the attimeter will be changed to the Chatham regional pressure setting.



"Maps are then changed to the more detailed Ordnance Survey (c.123), which shows the run-in track (210" magnetic) and the time the Lancaster has to leave the IP (19:08.30) at a pre-planned still air groundspeed of 150 knots to make the TOT (19:10). During the transit or during the hold the navigator will fine tune the leaving time corrected for local head or tail wirds.

"If the Lancaster is two mixues or more early at the IP, a hold will be carried out. If less than two mixues, then a timing dog-leg will be carried out to make the TOT. Once the aircraft has left he! P a tracking check feature is the wood at just over two miles to run. Looking sheed just to the right of the flypast venue is a large white water tower, and the Lancaster is aligned with his to the right (see photograph p. 120).

'As the aircraft approaches within approximately 1½ miles the individual building is identified and the Lancaster is lined up perfectly by the pilot to overfly the Officers' Mess at precisely 19:10, to coincide with the RAF ensign reaching the bottom of the flag pole

in front of the Officers' Mess. Three passes are completed, then the return to Coningsby via the escape heading shown (329") is to the west of Peterborough and Bourne. (See photo of the Wyton Mess p.121.)

"All five of the BBMF" avalgators are volunteers. Four are from Cranwell – two Cualified Newyation Instructors teaching advanced fast-jet techniques, and two Central Piping School navigator examiners – while in the Standard Evaluation navigator on the E-3D AWACS part of the ISTAR wing at RAF Waddington. The job of a BBMF navigator requires a great deal of commitment, not just from ourselves but from our families as well, as virtually every other weekend between April and October is given up to flying the Flight's Lancaster or Dake Tare.

'The BBMF is kept going by the passion and selfess commitment shown by all the aircrew, ground crew and support orew. It is indeed an honour and privilege to fly this magnificent aircraft built in May 1945, part of our nation's aviation heritage.' ABOVE Navigator's station on board PA474. (Paul Blackahl Crown Copyright)



ABOVE Flight engineer Squadron Leader Ian Morton monitors the various systems on board PA474. (Crown Copyright)

The flight engineer's duties

Squadron Leader Ian Morton gives an overview of the flight engineer's duties on board the Lancaster:

"The fight engineer or FE, more commonly known as "Eng" by the crew in today's Royal Air Force, is probably one of the least known members of acrosw. The majority of fight engineers are sent on-commissioned officers who have completed previous service in the RAF as a technical. The remainder are direct entrants, is they joined the service purely to become an FE.

"There are also a small number of FEs who have been commissioned from the rains to become FE officers, and it is from this small and dwinding branch that the Lancaster FEs are drawn. Very few of them have piston engine experience (the Shackelston retried or 1991) and some have very limited knowledge of propeler theory or practice. With the bare minimum of fultion, each FE selected for the Flight has to study intensively to acquire the technical

knowledge demanded to operate the Lancaster systems safely, using documentation dating back to the 1940s.

To put things in perspective, although anniquated and very different from today's aircraft the Luncaster systems are straightforward to learn. BBMFs Luncaster is dual-controlled so is operated with two plots, which means that some of the tasks that originally life to the FE.—the handling of all engine controls including the throttles and FRM levers, along with the flaps—are now the rents of the co-plot. As a result, after dealing with its routher tasks the FE has plenty of capacity left to devote to the big picture and airmanship. The benefits of having a covernment in this situation during display flying can't be underestimated.

Moreover, the FE has always been devoted to the technicalises of has aircraft, and there have been many occasions in the past where have been many occasions in the past where this has proved his worth. Tike, for example, Flight Sergent Ben Bennett, who flew in the Paration of the Auth, where his howedage of the Lancaster's flying controls along with his browa acts on open one right in September 1943 resulted in the award of the Distinguished Flying Modal. It is the memory of FEs like Ben that makes holding the position of FE on the BBMFs Lancaster so rewarding.

"Today's Lancaster FE wil visit the BBMF prior to the day of its fling dudies to self-brief the sortie. He will ascortain the display venues and read the display files to familiarise himself with the sortie profile and whether the Lancaster is going solor or being accompanied by the Fight's fightes. Having ascertained the total number in the team for the event (the Lancaster will normal) army up to five ground crew in addition to its four flight deck crew), rations are ordered if requires.

The fuel load is chacked, the standard usage being 150 galons per hour, plus 25 galons for each display and a minimum overhead destination fuel of 280 galons. He'll also collect the appropriate aeronautical documentation for the route. If standing away from Coningstry he'll crosscheck the airfeld's facilities, including handling agent and fuel availability (large holdings of AWAAS and a means of dielvering them to the Luncaster are

becoming fewer), and will take a copy of any hotel bookings made.

"On the day of the sortie, the Eng will meet with the rest of the errew in the Met office two hours before take-off for the weather briefing, to see what pleasures or challenges is ahead. Very hot flight 20s days, strong headwinds or particularly poor weather may result in a list minute increase to the fuel load. On arrival at the Flight hell meet the Crew Orleif and sorutinise the Lancaster's technical log ifform 700 to see that all is in order – the Lancaster rarely files with acceptable defects but it's vital the crew knows its technical state."

The Eng will then commence his preflight inspection in accordance with his flight reference cards (FRCs), double-checking that the aircraft is serviceable and all systems are set correctly. Once that's done he'll leave the aircraft "Power and Fuel Off", returning to the Flight to complete his weight and balance calculations, attend a crew briefing and a have "At 30 minutes prior to take-off the crew will walk to the aircraft and commence the Starting Engines checklet. Whilst the navigator reads the checks, the Eng will respond where required and crosscheck the plots and navigator's responses and their actions. The Eng makes checks of the engines' oil pressures and temperatures along with the coolant temperatures under the pressure of the engines' pering up the mighty Medrian, minimum values of these parameters are required.

'Once the engines have been started, the Eng awthces the electrics to flight mode and external power is disconnected. He'll then check the lat flow to ensure a positive flow is available from all tanks under gravity and booster pump supply. During the engine run-up checks oil pressure is monitored and generator outputs checked, and the performance of the magnetos is recorded along with the reference pm, which is the measure of the power culput the health of the engine, Between engine start and talke off many rhecks are completed, the



- 1 Engine oil pressure gauges
- 2 Oil temperature
- gauges
 3 Coolant temperature
- gauges
 4 Fuel tank gauges
 5 Fuel tank selectors
- 6 Fuel pump switches (number 3 tanks have guards fitted; they are last tanks
- 7 Low pressure fuel warning light
- 8 Fuel pump test ammeter 9 Pressure head heater
- switch 10 Dimmer switch and light
- 11 Power switch to panel
- 12 Inspection lamp socket
- 13 Emergency air selector knob



Eng normally being the crew member with the opportunity to ensure all is in order, from crosschecking the brake pressure to ensuring that no puddles of oil or coolant are left behind on the tarmac after the engine runs.

With all the checks complete and takeoft dearance obtained, the Eng monitors the engines both inside the aircraft and outside as istale-off power is applied; 7 inches of boost at 3,000pm is normally all that's required to pull the old gif safely into the air. Once airborne, on the captains command the Eng will select undercarriage UP, monitor it travelling, and ensure that the undercarriage doors close — there's no hydraulic contents or pressure gauge, only an hydraulic accumulator gauge which is situated by the crew rest-bunk, well out of sight.

'Once safely flying the power is reduced and the after take-off checks completed. At cruising height, normally 1,000 to 1,500ft, the Eng checks all systems are functioning correctly inside and visually checks the exterior coolant occurs on hot days, but oil leaks are very rare indeed).

"During the cruise, the plots self the fiving and engine handing between them and the Nav is busy resigning and making radio calls, which leaves the Eng to be Jack-CH-AH-Trades and make sure that all is in order. At some stage half secord a full set of engine readings to be entered into the TOO on leadings, from monitoring engine health. Four pairs of eyes front to mention the ground crewly are essential on fine summer days, when the skies above England are busy with light aircraft, glidner, helicopters and other aeronautical machines, so keeping a cool lookust is part of everyone's routine.

During the flight the Eng will initially feed fuel from the inboard tanks (number 1 tanks), to aid wing relief and thus reduce structural fatgue, changing to the outer tanks (numbers 2 and 3) later in the sortie. Switching from number 1 tank to number 2 tank involves going through the OFF position for both engines on that side, so this action is carried out with the utmost care,



BELOW View from

the rear gun turret as Hurricane II PZ865

follows the Lancaster

during a transit flight. (RAF Coningsby/ When arriving at the venue most eyes are on the lookout, but having descended to low level (100ft is the absolute minimum) the Eng monitors the engines more closely, especially at the higher power settings. Height and speed are every aviator's friend, so both assume an extra significance during the event.

The plots complete the display sequence from memory, however, a rare prompt from "the back" can be velcome. During the display, the Eng will mentally record the engine oil pressure at the higher power settings for entiry into the F700 after landing. When the BBMF's fighters accompany the Lancaster, a valentil, dey is cast in their direction, both for co-ordination and their well-below.

'Once the display is complete the Eng will make an accurate fuel check and pass the captain a bottle of water from the cold box – he's earned it!

'It's rare that the Lancaster flies in marginal weather conditions but if it's necessary the Eng will help obtain updated weather for the destination and diversion on the aircraft's second radio. Approaching the destination, more checks are completed: the Eng ensures the fuel system is set for landing, lowers the undercarriage, and crosschecks the brake pressures and flap positions along with monitoring the engines.

'After landing the engines are "run up" again, to check their serviceability. This can often cause a delay in proceedings at busy airfields whilst the Lancaster finds a spot to turn into wind and be clear well behind, so that the prop wash doesn't cause any damage.

Once the engines have been shut down and the use and electrics switched of, all hat remains is to complete the F700 papework and discuss any technical problems, with the crew chief. Then, more often than not, there? Is be one of the most important aspects of being a crewmenther on the IBMF- ascorting visitors into and carrund the aircraft, accompanying guests around the grand old lady, especially when they're accessive who file without World War Two, makes the flight engineer's position, like the reset of the zerow, something way specially and the properties of the stress contenting way something way something


BELOW Looking aft from the astrodome as PA474 banks to starboard. (Crown Copyright)



'Patching and replacing parts would mean a long toil, and many were the times we worked day and night without a break.'

Stan Wells, groundcrew, 626 Squadron





Chapter Five

The engineer's view



It's a great privilege and a big responsibility to care for one of the only two remaining airworthy Lancasters in the world. Personnel who've never worked on historic aircraft soon learn those rare skills that were second nature to engineers and ground crew working on Lancasters during World War Two.

LEFT Ground crew performing an engine change on Lancastian IW4783 G-for-George of No 460 Squadron, Royal Austrialian Air Force, circa May 1943. The work was obviously a success, as this Lanc went on to complete 90 operations before flying to Austrialia for a War Bond tour. It is now on display in the Australian War Memorial, Canberra, IRFA MUSEUM.



ABOVE PA474 awaits the BBMF engineers to start work. Note the mobile tool chest in the foreground. The raised platform around the number 4 engine is purpose-built for working on the Lancaster.

//arod Cotter/

While articles about flying on operations are, by their very nature, more interesting, if you ask any wartime Lancaster aircrew member about the contribution of their ground crew they'll always say the same thins: "It was critical."

Safety first!

Any aircraft should be treated with respect, especially one that has four propellers! Even when the Lancaster is static you should treat

the propellers as 'live'. Prior to moving a propeller a fellow crew member in the cockpit should confirm to you that the magneto switches are in the OFF position, or the engine could fire.

When starting the aircraft care should be taken to ensure that no unauthorised personnel are close to the aircraft, as a propeller blade can easily remove a head. The height of the Lancaster is a safety issue too, and care must



RIGHT With the spinners removed the propellers take on a different look. (Jarrod Cotter)



be taken when working on the wings, fuselage and tailplane.

Standard safety equipment such as sturdy boots, ear defenders, gloves and overalls are essential to protect against spillage, noise damage, slipping and injury.

When replenishing oils and greases care should be taken to ensure that what you're using is the right product for the job, or mechanical damage can result. Checking is essential, as many containers are similar in appearance.

Finally, before entering the aircraft all your pockets should be emptied, to prevent 'foreign object damage' (FOD).

Tools and working facilities

A good set of BA and BSF spanners and sockats is essential, as is a good general purpose tool kit including screwdrivers, tocking pliers and wire cutters. Spocialist tools, such as box and peg spanners for stripping components and riging boards for setting up flying controls, are also required. These can't be easily acquired, but they can be manufactured from original drawings. The size of hangar required is determined by the size and height of the Lancaster, but remember that adequate space must be available to soft the aircraft if

necessary, to lift out the turrets, or to remove and refit the engines.

A pair of hydraulic rigs is essential to carry out flap and undercarriage functions, wheel chariots to allow easy removal of the aircraft's main wheels, and engine staging to allow work to be carried out whilst the engines are in place.

Jacking and airframe support

To jack the Lancaster you require two 25tonne jacks with jacking adaptors (which fit into special sockets that are bolted to the front spar prior to jacking), a tail trestle, a nose trestle and a pair of wino trestles.

In order to raise the aircraft you firstly lift the rear fusible go wing a crane, which staches to an eyeboth screwed into the top rear fusiblego. The tail treate is then put into place at former 33 and the rear fusiblego is lowered onto it. The jacks are postioned inboard of the number 2 and 3 engines and the aircraft raised high enough to allow the undercarriage to retract. Then the nose treate is postioned at former E. Wing treates are then put into position to steady the aircraft and allow personnel to work on the wings.

A smaller tail trestle can be used for removing the tailwheel. The aircraft must be chocked before raising the tail. ABOVE Supported by jacks, this is the Lancaster undergoing scheduled annual maintenance during the winter. Clarged Cotter)

ABOVE Positions of Lancaster access and inspection panels. (Crown Copyright)

Servicing a Lancaster

The servicing cycle of the BBMF Lancaster is eight years between majors. This is worked out according to the hours flown, the fatigue file of the airframe, components that are fitted, known structural failures and the risks of flying a 60-plus-year-old aircraft. All these factors are considered and a schedule is produced. This schedule not only takes into consideration the aircraft steef but also the parts in it which have their cown specific flespan, either in flying hours, landings or calendar time. For example, a main wheel is life for 100 landings, so this would have to be removed and serviced regardless of whether the aircraft tast a service.

Because of the size of the aircraft the flight servicing is carried out by the individual trades: airframe, engine, and electrics. When servicings have been completed they're signed for on the appropriate document, from F705, in the aircraft flight log form F700. This form is then signed by the pilot to acknowledge he accepts that the aircraft is ready for flight.

Before Flight Servicing

This is carried out within 24 hours of the aircraft's scheduled take-off time. If the aircraft doesn't fly within that period then the service has to be repeated. The following items are checked:

- Internal and external checks to ensure all panels are secure.
- Check of all the flying controls to make sure they're in working order and free of all restrictions.
- 3 Tyre pressures are checked.
- 4 All Plexiglas is checked and cleaned.
 5 Crew harnesses are checked.
- Oil, coolant, pneumatic and hydraulic fluids are checked to ensure they're at the correct level and are replenished if necessary.
- 7 The aircraft is refuelled to the required level.8 The electrical systems are checked, eg the
- navigation lights.

 9 Engine controls are checked for restrictions.

After Flight Servicing

Valid for seven days, this is carried out as soon as possible after landing to ensure that any problems that are identified can be corrected before the aircraft flies again. Such problems may include worn tyres, broken fasteners and oil leaks. The ground crew will:

- 1 Refuel the aircraft.
- 2 Clean the exterior to maintain the aircraft in display condition.
- 3 Tidy the aircrew harnesses.
- 4 Carry out a visual inspection, looking for cracks and damage such as exhaust stubs that have holed and loose screws or panel fasteners.

Turnaround Servicing

This is carried out if the aircraft is scheduled to fly again within a few hours of landing, and involves the following:

- 1 Refuel the aircraft as necessary.
- 2 Clean the windscreen and canony
- 3 A quick visual check of the exterior of the aircraft.

Oils and pressures aren't checked during this



Fuel – Avgas F18 100LL. 2,154 gallons (however, PA474 files with between 600 and 1,000 gallons).
 Oil – OM270-Arosshol 100, 150 gallons.
 Hydraulio fluid – OM15/H515.
 Coolant – AL3.

Lubricating oil - OM150, used for hinges and bearings

Lubricants and fluids



howser in position and the boom extended. refuelling begins. (Paul Blackah) Crown Copyright)

LEFT Corporal Crosby refuelling the number 1 port fuel tank. (Paul Blackah/ Crown Copyright)

RIGHT Wheel retraction sequence. (Jarrod Cotter)









Primary Servicing

This service is carried out at 56 hours' flying time or thereabouts. Requiring about five technicians and taking two to three days, it consists of an inspection of the airframe and engines for general wear and tear:

- 1 Flying controls are inspected and lubricated.
- The undercarriage is inspected and lubricated.
- 3 Engine filters are removed and checked for debris. A soap sample is taken to check for any contaminant in the oil.
- The oil tanks are drained and oil
 - is changed.
- 5 The magneto contact breaker points are checked to ensure that they're set correctly.

Annual Servicing

This is carried out at 112 flying hours or annually, whichever comes first. It usually starts at the end of the display season and takes approximately six months to complete. It includes everything carried out during primary servicing plus the following:

- The internal and external structure of the aircraft is inspected for cracks and corrosion.
- 2 X-rays are taken of the rudders, fins, flaps and mainplanes.
- Wheels are removed and serviced.
 Brake units are inspected and tested.
- 5 Flying control runs are inspected.
 6 Flying controls are inspected, rigged and a
- range of movements carried out.

 7 Undercarriage hydraulic components are inspected and an emergency blow-down
- check is carried out.

 8 Undercarriage and brake functions tests are
- carried out.

 9 The engines are inspected and serviced.
- Oil and coolant are replaced.
 Propellers are inspected.
- 12 Electrical systems and instruments are checked.
- 13 Compass swing is carried out.

At the end of the annual service the aircraft is put through a series of engine ground runs, Once these are completed satisfactorily it is then air tested.



Minor Servicing

This is carried out every four years and is basically an annual service plus:

- 1 The wing joining bolts are removed and inspected.
- 2 Wing plug rivets are removed, holes are inspected and rivets are replaced. (British Aerospace personnel are responsible for this task.)
- 3 Instruments are removed, serviced and refitted.

Major Servicing

Carried out every eight years by an outside agency, who will tender for the contract. This is a much more in-depth service which includes all the work carried out during the Annual and Minor services plus:

- 1 Flying controls are removed and fabric is replaced on the ailerons.
- 2 Undercarriage is removed and overhauled.
- 3 Fuel tanks are removed and overhauled.
- 4 Engines are removed to allow for the engine

bearers to be removed for non-destructive testing and inspection.

- 5 Oil tanks are removed and overhauled. 6 Radiators and oil coolers are removed for overhaul.
- 7 Propellers are removed for inspection.
- 8 All hydraulic and pneumatic components are removed for overhaul. 9 Flying control cables and engine control cables are removed and inspected.

The opportunity is also taken to repaint the aircraft. Depending on the condition of the paintwork when it arrives for its service, the aircraft is either stripped to bare metal or the

paintwork is simply scuffed to accept new paint. Engine ground runs and air testing are carried out once the service is complete.

Common faults

Common faults with the Lancaster include minor oil and coolant leaks, which are generally rectified by tightening jubilee clips on rubber hoses. If this doesn't solve the problem new pipes will be manufactured and fitted.

ABOVE Engineers working on the number 3 engine. (Crown Copyright)

RIGHT Dye penetrant applied to a tube to identify cracking from the taper pin holes. (Crown Copyright)

FAR RIGHT Typical example of loose rivets. The looseness is evident by the damage to the paint around them. (Crown Copyright)

BELOW PA474 received a new type of exhaust stub in 2006. Made from material which was claimed to be more hardwearing. some had been tested the previous season and stood up to the test so well that they were fitted to all the engines the next year. Here, the engines are seen during their winter overhaul, with the shiny new stubs easily identifiable compared to the weathered older ones, (Jarrod Cotter)



Fabric tapes that cover the transportation joints and various seams on the aircraft often peel back and have to be replaced using new tape and dope.

Loose rivets require replacing and regular checks are carried out to locate any areas that require attention.

Brake bags overheat and lose their pressure so require replacement. Although this is not a major job, if the problem should occur when the aircraft is away from base it requires a lorry carrying a 25-tonne jack, a wheel charlot, wing trestles, a crane and additional ground crew

NDT - non-destructive testing

There are four methods of non-destructive testing carried out on the Lancaster: X-rays, ultrasound, magnetic particle and dye penetrant.



The X-ray checks are carried out to examine parts or areas on the Lancaster that can't be easily accessed, such as the fins, flaps and engine bearers. The X-ray check will usually show up any internal corrosion or cracking.

The ultrasound check uses sound waves to detect cracking around the bore of a hole. To do this a probe is inserted into the hole – for example, the wing joint shackle holes – and a meter reading indicates if there is any sign of damage around it.

Magnetic particle checks are used to look for cracks in ferrous metal components. The component is painted with a fluid containing iron filings and an electric current is passed through it. The sample is then examined under ultra-violet light, which will highlight any faults that are present. Afterwards the sample is demagnetised.









FAR LEFT Inside one of the Lancaster's wheel wells. (Crown Coovright)

LEFT Port mainplane with the number 1 fuel tank removed, clearly showing the tank retaining straps. (Crown Coovignt)

Dye penetrant checks are used to look for cracks in both ferrous and non-ferrous components. The component is painted with a fluorescent purple dye, cleaned, and then sprayed with a white developer, which, after approximately 40 minutes, will highlight any cracks. These show up as fine purple lines.

Keeping records

The BBMF Lancaster is operated using a Form 700. This log records the aircraft 8 high plours, landings, and any faults that cocur. The forms that log the aircraft 8 high plours (F724) and faults (F7074) are permanently retained by the BBMF, whilst any other paperwork, such as that for Major or Primary services, is kept for eight veers and then disposed of.

Engines and propellers have their own log cards, which stay with the particular component. These detail dates of fitment, when an item is due for an overhaul, and what repairs have been carried out.





ABOVE Various RAF Form 700s appertaining to PA474. (Paul Blackah/ Crown Copyright)

LEFT RAF Form 707A showing various fault reports and maintenance work entries. (Jarrod Cotter) RIGHT Number 3 engine with all the cowlings removed, revealing various components not normally seen, the most obvious being the radiator. (Jarrod Cotter)



BELOW When all the flying's done, it's down to the engineers to carry out an afterflight inspection and then carefully put the Lancaster away in the safety of the BBMF's hangar. (Jarrod Cotter)

Picking a new colour scheme

Every time PA474 undergoes a Major servicing the BBMF changes its squadron codes to reflect a specific aircraft that flew on operations during World War Two. Once the choice is made research is carried out to find information on that specific aircraft's orew members and

missions, and to collect as many photographs as possible to ensure that the finished markings and codes are accurate.

The BBMF is always grateful for the general public's response when help is requested in achieving this.



Heroes without wings

Amough it is aircrew stories that we read about most, the vital work of the RAFs wartine ground crews should never be overbooked. It is sobering to note that around 8,000 men and women of Bomber Command 8,000 men and women of Bomber Command were killed in the UK while carrying out their various ground-based duties, often under dangerous and thying conditions. Not the least of these was working round the clock in the pean air on exposed affelds, other in the extreme cold and wet of British writers. Many suffered ill health as a result of this constant exposure to the elements, and some became chronically III.

Try and imagine your fingers numb with cold, lumbling with floats nuture and botts, pipe work and engine cowlings, while standing on a raised scalificiding platform at engine height a bitzard of show or sleet sweeps around you. You blow on your hands and stamp your feet, trying hard to get some circulation back into them. You can't just leave the job til later: 'opsi' area no nonicht.'

Through the following extracts we get an insight into the work of a Lancaster's ground crew, and their close relationships with the aircrew – who respected them enormously.

Stan Wells, groundcrew, No 626 Squadron, RAF Wickenby, Lincolnshire

We really loved our own allotted Lanc. She was fussed over like a new car, though we did not always get a brand new machine fresh from the factory. She was as much ours, of course, as the aircrew to whom she was assigned. She was swept and cleaned inside, and woe betide anyone who left a cigarette end around or was sick and said nothing.

'Naturally, the enemy sometimes took a hand. If a kite came back from ops peppered with holes and jagged edges, we would jokingly curse the aircrew for not being more carefull

"It was a proud boast to start the engines first time, regardless of the weather. However, a snag such as a sudden mag drop could not be helped. The Squadron Engineering Officer and "Chiely" were always on hand to help sort out a ticklish problem. Tools were in short supply



but we improvised and some ingenious concoctions resulted.

Patching and replacing parts would mean a long tol, and many were the times we worked day and night without a break, for it was a matter of pride to get ones kite back in the line as quickly as possible. The veether was perhaps our biggest enemy, soaked to the skin or blue with cold, we would be kept going with constant mugs of piping hot tea, brewed on our own strees.

"Relations with the aircraws were excellent. During their tour of ops we got to know a crew very well. Often we would play cricket, football or have a round or two at cards over a brew-up at the hut when take-off was delayed. This was particularly so during the summer and autumn of 1944, when the second front opened and the daylight time beasan in earnest.

In the dark grim days of 1943, with the Sattle of the Ruhr in full swing, and again over the winter of 1943—4 – the Battle of Berlin – Iosses were heavy and few crews got past ten trips. Some were unfucley, oping down on the last five. When a crew did not return there would be glum faces, but within a day or two a new crew would arrive and the whole cycle would be glum faces.

'Once a kite was airborne we would take it in turns to wait up for her, and always there would be some of us to greet the crew when they returned. After each operation we would proudly paint a bomb symbol with a stencil up on the kite's nose, and much friendly competition existed as to who had the kite with the most ose.'

Extract from Lancaster at War by Mike Garbett and Brian Goulding (Ian Allan, 1971)

ABOVE Wartime engineers work hard on numbers 3 and 4 engines to prepare a Lancaster for its next night of operations. (RAF Museum)

Cliff Allan, groundcrew, No 467 Squadron, RAF Bottesford, Leicestershire

'A parade of flight personnel at the MT [motor transport] section followed breakfast, and then it was all aboard for the dispersals in a fog, thickening fast.

'Lancaster "H-Harry" loomed ahead, immobile and inoffensive, as the truck drew near and skidded to a halt. Reluctantly her ground crew dropped on to the crackling dispersal pan, the truck moved off and "H-Harry" was swallowed up by the dark curtain swirling behind. The call "G-George" drifted back from the cab and we knew we had arrived at our charge. "George" stood completely covered in white hoar frost: from each airscrew hung a two-inch wide icicle leading to the ground, and tapes holding engine and turret covers were frozen solid. "Dusty" Coleman, our rigger, found the door into the aircraft welded tight with the frost and disappeared into the fog to report. All the aircraft of No 467 Squadron were enveloped in the deep freeze and, no doubt, so was all 5 Group.

It was a great relief on days like these to complete the Dis (daily inspections) without snags, but this was not always the case. One such day followed a pilot reporting an eincrow that did not respond between coarse and fine pitch. After the Dis, the engine with the fault prop was test run and shut down. Jack, our Aussie corporal, went through all the possible faults but could find nothing amiss, so, by agreement with Laurie Parker (sergeant), made the decision to change the prop.

"It was not a long job to fit a new one, but nonetheless a frustrating task assembling the necessary equipment. Requisitions for replacements were left in our corporal's capable hands, and two of us joined him for a trip back to the maintenance hangar. There he hunted down a new prop whilst we commandered a portable hand-crane.

The sky had been very grey and overcast, and a slight flurry of snow looked ominous. The spinner was removed, the rope sling attached to the old prop, and the large hub loosened to allow the oil to be drained off; then the handcrane was brought into use. Everything was going smoothly when, just as if someone had turned a switch, down came the snow thick and heavy. Unperturbed, we carried on, swinging the prop away and on to the edge of dispersal. By the time the new prop was cranked into the air a bizzard was raging and, though only a few yards from the eigne, we couldn't see it for the binding snow. The quick decision to abandon any further attempts was unanimous and on hurriedly applying covers we retreated to our shack. This was one of the rare occasions when we had to submit to the weather and continue the following day."

Frank Hawkins, armourer, No 9 Squadron, RAF Bardney, Lincolnshire

'Our day would normally commence with daily inspections, when the armourers would visit their designated kites and go through the procedure of checking guns, turrets, bomb gear, etc. These DIs were very thorough as the squadron - indeed Bomber Command in general - had, during the winter of 1943-4 in particular, experienced above average trouble with our stoppages (usually attributed to icing). While icing may well have been a contributory factor, Maquire (Pilot Officer, Squadron Armament Officer) was of the opinion that the answer lay in the fact that the armament staff on many stations were overwhelmed; the monumental task of preparing and handling vast quantities of bombs and incendiaries every day meant that other aspects tended to "go to the wall". It was always maximum effort and a month of continuous operations was a shattering experience; and month followed month with only a quick breather in between.

"All the armanent staff at Barchey were, during the wither of 1943-4, either fully or partially employed in the handing and preparation of bothes; no one was immune – except parhags for the WAAF on the ammunition beliefly section. All emuruers ould expect to be, and often were, diverted from their normal duties to back up the hard-pressed teams in the bomb dump and under the arroraft."

Extracts from Lancaster at War 2 by Mike Garbett and Brian Goulding (lan Allan, 1984)



LEFT The engine cowlings and spinners have been removed. Note the nose section joint fabric tape has also been removed. The aircraft is being prepared for paint stripping. (Bruce Irvine)

From Mickey to the Phantom

uring the winter of 2006/7 the BBMF Lancaster underwent a Major service. The contract for this was awarded by the Nimrod Integrated Project Team, which manages the Battle of Britain Memorial Flight. Bruce Irvine from Classic Aircraft Maintenance Ltd. the Project Manager, tells his side of the story:

'The ad in the EU Journal was simple: "The MoD have a requirement to carry out Major maintenance on BBMF Lancaster PA474 during Winter 2006/07. Interested parties should contact the Nimrod IPT, DLO (now DE&S). RAF Wyton." After a complex competitive tendering process the contract was awarded to Atlantic Airmotive, the engineering section of Air Atlantique's Classic Flight.

'The previous Major was carried out in 1999 at RAF St Athan by RAF personnel, and although the tradesmen of the Classic Flight were experienced on large aircraft such as the Dakota and Shackleton this Major saw a team of entirely civilian contractors carrying out the work to a new maintenance schedule, so there would be no previous experience to fall back on. The condition of the aircraft looked sound.

BELOW The paint removal is complete, leaving the aircraft with a bare metal finish, (Bruce Irvine)





ABOVE The aircraft is jacked and trestled. All the engines, engine bearer frames and undercarriage legs have been removed. (Bruce Irvine) BELOW The rear fuselage is separated from the rest of the aircraft to allow the removal of the rudder and elevator control rod runs. (Bruce Irvine) but as with any project of this size and nature of work, it could not be taken for granted that there wouldn't be any surprises as the paint, panels and various components were removed.

The work identified as "Major Maintenance" is detailed in an AP Publication and is the core tasking. Additional tasking was also identified at the initial tendening stage; what could not be identified, initially, would be the rectification tasks. As these tasks arise they must be identified and scoped and then authorised by the MoD representative before work can commence. This meant constant lisison with the MoD to ensure that the work being carried out was required and was carried out to the highest standards.

It was decided that the best way to tackle this plow sats of dided the workload into two parts. As the Project Manager I would lead the corrigid for the contractor, be responsible for the contract and overall co-ordination and also be the link with the Engineering Authority (DEAS) from RAP Wyton, who had overall responsibility for the aircraft. The physical hands-on aspects, however, would be the responsibility of Allantique's Classic Flight Chief Engineer, Ben Cox.



This would allow Ben to concentrate on the day-to-day tasks and allow me to focus on supporting his activities, whilst working in conjunction with the DE&S engineer (Chief Technician Colin Robertson) to keep the aircraft on course for its output date whilst ensuring that the appropriate level of rectification was being carried out. The Major would then be divided into phases: initial inspection and removals, detailed inspections, repair and rectification, refit, and finally functional testing.

'The initial timeframe to carry out the Major was approximately six months. To make sure this deadline was achieved it was decided that the best way to perform the maintenance was to keep the airframe work in-house but to subcontract the bay maintenance items, for example the hydraulic and pneumatic components.

The contract also required the aircraft to be stripped to bare metal and resprayed. This would also be carried out by a subcontractor. At any one time over 100 tradesmen would be working on the aircraft or its various parts. With so many different subcontractors and precise deadlines, the control of the project was no mean feat in itself.

'The Lancaster arrived at Coventry Airport on 2 October 2006 to a large crowd of both public and media. Somehow the story had leaked out and it appeared that all the surrounding roads leading to or running next to the airport were full of cars waiting for the aircraft. On arrival the bomber flew a circuit, which gave the crowds something for their patience. After taxing to the required slot, where again there was much media in attendance, the crew disembarked and carried out the necessary paperwork. Mickey the Moocher made its last public appearance as it was towed into Air Atlantique's hangar, where it would stay for the next six months or so.

'As the aircraft was to be stripped back to bare metal the decision was taken to carry this out as soon as possible. This would allow the inspections for surface corrosion to be carried out early into the servicing, giving us time to make any repairs if required. However, before stripping could commence the propellers and the engines had to be removed. They could have remained in situ for the strip, but as they



were coming off anyway this was the best time to do it, as it reduced any risk of contaminating the engine bays or paint-stripper damage to the propellers.

'With the spinners removed, access was gained to the hub bolts and the props were removed using a crane. As the props had



ABOVE Work being carried out on the engine bay rear bulkhead. (Bruce Irvine)

LEFT Inspected and repainted, the engine bearers are refitted. The red item behind the bulkhead is the engine oil tank. (Bruce Irvine)



ABOVE Engine refit in progress. (Bruce Irvine)

been overhauled the previous year all that was required for these was a simple inspection.

The RAP policy on Merlin angines is to "file" the engines at 500 hours, site which they're completely overhauled. On this occasion all four were still within life, so only some simple "top end" maintenance was required. This was carried out by BBMF tradesmen. Removal of the engines took several days as many of the ancillary components had to be removed or disconnected before the engines the threshels could be taken off. At this stage it was important to ensure that everything was labelled correctly and the use of digital cameras became second nature to ensure the correct refitting of components.

'All copper pipe work had to be heat treated, as the copper hardens through ageing. Each pipe or pipe assembly had to be removed and labelled in such a way that it would still be identifiable after it had been in a furnace for several hours to anneal the metal.

The next big lob was the bare-metal strp, This was carried outly a specialist arount painting company called Sprayavia, which is based at Norwich Alprot. The aircraft was surrounded by scalfolding to provide a safe working platform. Transparencies were masked with three different layers of protection, then a chemical stripper was applied to the main raises of the aircraft. The stripper and paint were then removed using water, However, in some areas the orty option was to ub down by hand – a long and laborious job. The paint strip took a team of six painters some ten days to complete.

When the aircraft was finally down to bare which and the staging removed from around it. the job of carrying out detailed inspection of all the surfaces began. A little corrosion was found in various locations, but the surfaces were generally in very good condition and ties remedial work, other than that already identified, was required. One area which had previously been identified as "Additional Work" to the core tasking and in need of attention was the starboard wingline.

"During the previous writer maintenance the port whight had been found to be corroded, and although the starboard looked in good condition it was thought that all title time investigating the tip after it had been stripped of its paint would be useful. It proved to be the correct thing to do. The leading edge was corroded and a repair to the upper surface was also showing signs of corrosion. The wrighty was removed to allow ease of access, the upper surface skin was replaced, and the corrosion on the leading edges dressed and repaired.

'Another area that was brought to our attention was that of the rear panel of the port bornb door. A stainless steel skin had replaced the original alloy skin and it was thought that this had been fitted over the old alloy during one of the various trial fits that the aircraft had

undergone in the 1950/60s. The steel skin was removed to reveal what was expected: a badly corroded existing alloy skin. This was removed and the stringers and farmes below it were inspected – fortunately they were found to be in good condition. This was a bonus, as trying to find or remanufacture these stringers and frames could have proved time-consuming.

'As the detailed inspections progressed more and more components were removed from the aircraft for by meinterance or to allow for deep inspection. As the flaps were removed an inspection of the flap operating tubes revealed one of the aspects of the task we had all feared — a major component failure.

The operating tubes on the starboard side ware found to be comded and in one specific area a crack had appeared. The DESS sequired was informed immediately the problem was discovered and, after discussing various options, it was agreed that the only option open to us was to remove and replace the tubes — but we were 99 per cent centain than to spare tubes existed, and even if they did they could be as comoded as the ones fitted. A check of the sparse held at RAF Coningsby confirmed our fears: new corridority between the set of the sparse held at RAF Coningsby confirmed our fears: new corridorit butse would have to

'The tubes were removed and dispatched to Retro Track and Air based in Dursley who took on the task to remanufacture. But there would be a penalty, as this would take time. Tubing

be made.



and there was nowhere in the UK that could provide the diameter, wall thickness and lengths required, so it would have to be sourced outside the UK. The tube also contained inserts that were fixed inside the tube and served as the mounting point for the connecting node; these would also have to be remain/actured. This would all take approximately IC weeks, and in a project such as this time was the one thing that we didn't have.

'The inspections and removals continued with no further great surprises other than finding some cracking on the engine frame welds. The frames were removed and repairs carried out by Skycraft, who did a really creat job returning the

ABOVE Engine systems pipe work and electrical cables are refitted to the engine bearer. (Bruce Irvine)



LEFT The inboard engine is now complete with radiator and oil cooler. (Bruce Irvine) frames well before the engine refit was planned.

'One of the additional requirements during the Major was the removal and replacement of the elevator and rudder flying control rods. These rods run the entire length of the port side and transmit the pilot's operation of the control column to the relevant control surfaces. They had been "snagged" earlier as showing initial signs of wear where they run through bearings housed in the various frames of the fuselage, and would have to be replaced.

'During the manufacturing stage of the aircraft these control rods are normally added as each section is being constructed, so the only way to remove them would be to take the fuselage apart. Through discussion with BAE Systems, the BBMF and DE&S, it was suggested that we might be able to take the nose off and withdraw the rods that way, but after inspecting the control rod run, with various components now removed, we discovered that: (a) the rivets that held the rod male and female end fittings, which linked all the rods together, would not go through the bearings; and (b) there was a slight deviation from a straight line that would not allow the rods to be taken out through the nose section. So that approach wasn't feasible.

each transport joint. This would allow easy access to the control rods for both removal and replacement but would take considerable time. The simplest way was to split the aircraft at

'The alternative was to split the aircraft at

the rear fuselage transport joint, as it had been some four years previously. The bolts would be relatively new, making the split easier, and we had sufficient trestles to support the aircraft.

'Splitting the aircraft at the rear fuselage joint still meant removing the rods through the bearings, which we knew wouldn't work. The rods would still have to have the end fittings taken off inside the aircraft before removal and then refitted after the rod had gone through the bearing. Although a lengthy process this was the best way to proceed, as it provided the least risk to the project. The idea of splitting the aircraft at the rear transport joint was put forward to the DE&S engineer and BAE Systems and, with both in agreement, we were given the green light to go ahead.

'Splitting the aircraft was relatively simple. It was jacked up to its level position using jacks under the mainplanes. An eve-bolt fitted to the tail section was then attached to a crane by a sling and the tail section was raised to the level position. A trestle was then positioned under the aircraft and the tail section rested upon it. Two more trestles were positioned either side of the rear section transport joint and the work of removing the bolts began. They were slowly removed until the final one came out with no more than a slight tap. The rear section was then simply pushed away from the main fuselage, giving us ample access to remove the control rods.

'This proved to be the easy part, as it then took nearly three weeks to remove and replace the existing rods, with each one having to have the end pieces removed in situ. The old rod was then removed from the aircraft by sliding it through numerous bearings, a new rod was cut to the exact length, the old bearings were replaced, the rod was slid back in and the end pieces were fitted.

'The wear characteristics of the rudder and elevator control rods also made us question the possibility of wear in the alleron control rods, as these are of the same construction, and upon further detailed examination we found similar wear characteristics just beginning. Our findings were put to the DE&S engineer, who agreed that the rods should be replaced. Luckily, at this point the flap and trailing edge of the wing had been removed, allowing easier access, so replacing the rods was an easy option to take.

BELOW A view of the port inner engine fitted to the bearer assembly. (Bruce Irvine)





With the Lancaster now on jacks the undercarriage could be removed for bay maintenance. The removal itself proved simple enough, but when the legs were taken to the bay and stripped down some internal damage was discovered. No spare parts were available to replace the unserviceable components and the only option open to us to meet the timescale was to use the serviceable components from each panel to make up one serviceable leg. Fortunately a spare panel assembly (one complete leg unit) was available from the BMFF, but as this had been in storage for some time it was agreed that it should be inspected prior to fitting. Luckily everything was found to be serviceable, and between the removed legs and the spare we were able to provide a complete undercarriage.

'As late autumn gave way to whiter the work in the hangar changed from inspection and removal to rectification. Loose rivets, worn anchor nuts, minor corrosion and cosmetic skin replacements were the order of the day, with the sound of air drills whizzing in the background replaced by the prappt of a rivet gun and block.

'Other than the ones mentioned above, no major rectification tasks were required. It was good to see the aircraft in such a good condition – a real testament to the tradesmen and women at the BBMF who regularly service the aircraft and to those who'd carried out Major maintenance in the past. It gave us the confidence that the maintenance schedules used for the past 60 years really worked, and with the aircraft in such a good condition, with some 5,000 flying hours on the clock, it should be good for at least the same again.

'By January 2007 many of the components that had been sent for bay maintenance were beginning to return and could start to be refitted. Cocklich instruments, Pydraulic components and undercarriage legs at had a new lease of life, and internally the aircraft was taking shape too. The extra control rods for the aircrons had arrived and had been fitted as for as possible. The fuselege had gone back together as easily as it had come apart and the new control rods for the nudder and elevator were in place and felt smooth and precises. The

ABOVE The aircraft is off its jacks. Fabric tapes have been applied to all the transportation joints before the aircraft is primed. (Bruce Irvine)

BELOW After the primer has been applied the aircraft is masked ready for application of the camouflage paintwork. (Bruce Irvine)



flap-operating tubes remained the one thing outside our control, outside anyone's control really, as the tubes had to be specially milled and it just took time. The tube inserts were ready and we just had to wait.

'There was still plenty to do on the fuel tanks. engine bearers had to be fitted and then the engines themselves had to be installed with all their accessories and ancillaries. The idea of going into repaint at this stage was debated. but some sections of the aircraft could not be painted, as the trailing edge was still off, awaiting the flap tubes. Although it would have been very unlikely, painting the aircraft at this stage could have resulted in a slight colour distortion and no one wanted anything but a nerfect finish, as the first event the Lancaster was scheduled for was a commemoration ceremony at RAF Coningsby for the two units the new paint scheme would represent - 100 and 550 Squadrons

"Finally the call came that the tubes were reshall and could be picked up, which was done as soon as possible, and just four hours later they were being readed to be fitted. With the tubes in place the wing trailing edge could then be fitted and the vital repairs commenced.

The repaint took a team of ten painters two weeks to complete, turning what was a rather strange looking aircraft back into one of the most distinctive in UK skies today. The black, or night, underside, with camoullage green and dark earth upper surfaces, have remained constant throughout the Lancasters.

If e with the BBMF. However, with each Mejor maintenance the nose-art changes. In this case it changed from an affable Mickey the Mocoche to the Phantom of the Puhr, a distinct change to a far more sinister scheme. Nonetheliess, the nose-art is fantastic and I must thank Sprayavia for their considerable input and patience in achieving the final result.

With the paintwork complete we were able to get back to work on completing the installation of the engines and the final few components. Although no final output date had been given, a bunch for the BOMP's 50th enmissay was planned for late April and we realised what an important point in the Fighth shelory this was. Not to have the Lancaster there in its new squadron colours would be unforwished.

"As the date for the ceremony grew closer and closer we reasised that the tempo in the hangar would have to be increased if we were long to get the aircraft out on time. At this stage 12-hour days and seven-day weeks were not uncommon. Although the MoD doth'n push us, and safety was paramount, professionalism and a pride of being part of something great forced us to put in the hours to get the aircraft out on time.

'Slowly it was coming back together. The paints sheme was complete, including the nose-art, all instruments were refitted and the hydraulic components were in place. The undercarriage units had been refitted, as had the engines and propellers, so hydraulically and electrically the aircraft was sound; but the proof to the proof to the proof of the proof of the sound; but the proof of proof proof of proof of proof proof



RIGHT When the camouflage has been applied the markings are added. Here the roundel is going through this process. (Bruce Irvine)

of the pudding was in the eating, "Electrics going on" - no sparks, no bangs, nothing. a good sign. "Hydraulics going on" - again nothing, another good sign.

'As the various hydraulic system function tests were completed the aircraft could be lowered off lacks and back onto the ground, a position it hadn't been in for over six months. As the flying controls range of movement checks were completed the next moment of truth came upon us; engine ground runs.

'The RAF is quite stringent as to who can run the engines on their aircraft. This is not just for commercial contractors but for all tradesmen, including their own, and a great amount of time, effort, training and care is taken before someone is authorised for ground runs. Doubly so with the Lancaster. There are very few people in the country, if not the world, who can safely fire up all four Merlin engines with confidence, so it was the tradesmen of the BBMF who carried out the ground runs.

The engines were primed and finally the aircraft was towed out of the hangar into a beautiful sunny April morning. The Coventry Airport fire service had been informed and a fire tender had been dispatched to be in attendance should anything go wrong. A crowd slowly gathered. Although we hadn't realised, it was about lunchtime, so many airport workers were in a position to watch the aircraft as it began the final phase of the journey that would bring it back life.

"Number 1 contact, contact," Slowly the propeller turned and after few rotations the Merlin roared into life, accelerated, and then steadled. Contact number 2, the same process. and so on up to number 4. Then all four Merlins were roaring outside the hangar, much to the joy of the onlookers and to us. This initial low power run had to be right otherwise we could be looking at an engine change and delaying the output date. Low power runs completed, high power runs were required. This meant the aircraft would have to go to the other side of the airport. During the high power runs a slight "mag drop" problem occurred, but by the following day this had been rectified and ground runs carried out again successfully. The Lancaster was now ready for its final test - the air test



'Disaster! The following morning, as we entered the hangar to prep the aircraft for its test. a drop of fuel landed on the head of one of the maintenance team as he walked under the wing. Removing the panel below the fuel tank revealed what we had thought - a leak. The tank was removed to investigate further in the hope that it might be a union or fitting that was leaking. But that was not the case. It was the tank itself.

'The DE&S engineer was informed immediately, as this could have a serious impact on the output of the aircraft and the ability to carry out the air test. There were two options available: not to refit the tank, and get it repaired; or refit it, raise the appropriate paperwork to inform the aircrew and the ground crew, and carry on with the air test. Much discussion took place over the merits of both options between the contractor, the DE&S engineer, the BBMF ground crew and us. In the end the decision lay with the MoD, and the decision was to refit the tank. This was done. and by the time the aircrew arrived the panel was back on and the paperwork sorted.

'The aircraft was towed out into the daylight and again a large crowd had assembled both inside the airport site and outside the perimeter fence to see it fly. The engines were started up without any problems and the aircraft taxied off to the end of the runway after further engine checks.

'From where we stood we could see the aircraft start making its, what seemed painfully slow, run along the runway. Slowly the tail

ABOVE The nose ort is hand painted using an enlarged copy of an original photo. (Bruce Irvine)

lifted into the air and a minute or so later the main wheels cleared the runway. As the aircraft started the climb we saw the undercarriage retract and the doors close. The Lancaster then banked to the right and headed off to carry out the air test.

"If it's back in five minutes it's felled," was one comment, but five minutes led to ten, then to 20 and 30, and after about 40 minutes we were informed that PA474 was making its approach. As the bomber roland overhead we realised that everything must have gone well, though these might be some minor range to sort. As we watched the undercarriage come down and the aircraft slowly descend through the sky I held my breath, waiting for touchdown and for the brakes to operate. As the aircraft taxied back into the slot it had left some 45 minutes earlier Lieu cat a great slot or frelief.

The engines stopped and the crew emerged. As we suspected, there were a couple of minor snags that were quick fixes, and a minor oil leak that was also soon sorted. Some hydraulic fluid had been seen very slowly leaking from one of the main oloos, and at first we thought this was merely the aircraft settling jobs we could carry out were completed and some other enags were addressed, but the aircrew were happy to take the aircraft back to RAF Coningsby. So as the evening started to draw to a close PA474 took off from Coventry Airport once again, this time not to return. After a magnificent flypast the aircraft banked to the rioth and flew home.

'After landing the leak from the cleo didn't stop, so the leg was removed and repaired. The leaking fuel tank was also replaced, and at the time of writing PA474 has flown over 100 hours during the 2007 flying season.

"My tranks go out to all those involved in this project. If there to list everyone it be into another page, but special tranks go to Ben. Bob, Dan, Jehn A, John and Paul — without your dedication this couldn't have been done. The tradesmen and women at the BBMF arraweard my questions on the plane are arswered my questions on the plane are again. Thanks to to Colin Robertson, whose open mindedness helped no end in getting over the problems we encountered, and to at the subcontractors I used to get the job finished with 36 hours to gaze. Good project finished with 36 hours to gaze. Good project

BELOW PA474's repaint is finished and the major servicing is nearing completion. Engine ground runs are required and then the remaining cowlings and spinners can be refitted. (Bruce Irvine)



Part numbers

For ease of identification, each area of the Lancaster is designated a letter followed by the actual part number:

B - data and rigging

C - cockpit deck and fairings

D - fuselage structure

E – cowlings and fireproof bulkheads E – wing structure

G - tailplane and elevators

H – fin and rudders K – undercarriage, main and tall N - furnishings

O – power plant P – fuel and oil

Q – piping services, hydraulic and

B = flying and trim controls

S – instrument and panels

T – radio and radar

U – ancillary equipment V – electrical systems

W – bomb gear X – gun gear 7 – sundries The undercarriage legs and hydraulic components were all manufactured by Dowy, the wheels, brakes and pneumatic components by Dunlop, and the turest by Praser Nash, Each company operated its own numbering system. The Meriin engine has its own flour of the-part number system own flour of the-part number system prefixed by the letter D. A Packard Meriin is prefixed by the letters PD.

Dimensions and weights

All dimensions are with the Lancaster tail up:

Wingspan – 102ft Length – 69ft 6in Height – 20ft 6in Tailplane span – 33ft Maximum take-off weight (wartime) – 61,500lb BBMF Lancaster – 48,000lb Fuel – 2,154 gallons (the BBMF do not fill above 1,000 gallons maximum) Oil tanks – 150 gallons Main hydraulic system – 19½ gallons

PA474 avionics

Successive modifications have totally superseded the original avionics. The current equipment is as follows: V/UHF – a PTR 1751 V/UHF radio. VHF – an AD 120 VHF radio. Intercom – an ARI 5388 intercom. IFF – an ARI 23373/1 IFF system. DME – DME, ARI 23414, installed under SRIM 4147 Part A. VOR – a VOR system, installed under SRIM 4147 Part B.

PA474 general limitations

Weight limitations

The all-up take-off and landing weights are limited to a maximum of 48,000lb.

Centre of gravity limitations

The position of the centre of gravity is not to fall outside the following limits:

Aft: 60.6in aft of the datum.

Forward: 41in aft of the datum.

Speed limitations

The maximum speeds for operating the aircraft are to be as follows:

Diving - not to exceed 200 knots.

Undercarriage down – not to exceed 150 knots.
Flaps selected – not to exceed 150 knots.
Operation of bomb doors – not to exceed 150 knots.

All flying – not to exceed 200 knots.

Maximum permitted normal accelerations

Manoeuvres involving negative normal accelerations are not permitted. The following accelerometer readings, which include accelerations due to turbulence, are not to be exceeded:

Normal operation and displays - 1.5g.

Never exceed - 1.8g.

Stalling

Intentional stalling in accelerated flight is prohibited. The limitations regarding stalling laid down in the Aircrew Manual are to be observed.

Crosswind limitation

The maximum permissible crosswind component for take-off and landing is 15 knots.

PA474 engine limitations

The following engine limitations are never to be exceeded:

	rpm	Boost	Temperature °C	
		lb/sq in	Coolant	Oil
Max take-off to 1,000ft	3,000	+18*	135	105
Max climbing 1 hour limit	2,850	+9	125	90
Max continuous	2,650	+7	105	90
'Combat' 5 minutes limit	3,000	+18*	135	105
"+18 lb/sq in boost must	not be u	sed below	2,850rpm	1.

Under normal operating conditions, the following engine limitations are not to be exceeded:

	rpm	Boost lb/sq in	Temperature °C	
			Coolant	Oil
Take-off (max)	3,000	+9	135	105
Take-off (normal)	3,000	+7	135	105
Max continuous	2,650	+7	105	90
Normal climb	2,400	+4	105	90
Cruise	1,900	+4	105	90
Descend at 150 knots 500ft/min rate of desc		b/sq in bo	ost to atta	in

Maximum overspeed

The maximum permissible overspeed is 3,150rpm for 20 seconds.

Oil pressure

The oil pressure under normal conditions should remain between 60 and 80lb/sq in. The minimum permissible oil pressure is 30lb/sq in.

Minimum temperatures

The engines are not to be run at above 1,200rpm until the following minimum temperatures have been achieved: Oit: +15°C.

Coolant: +40°C.

Surviving Lancasters

Listed here are the 15 extant Lancasters which are currently on public display, Additionally Lancaster VIN NOSE MUL-21 is undergoing a comprehensive netsoriant at Le Burgel in Preiss. Arother Lancaster is stored discernated in the USA and various cockpil sections (both original and modic-upil also remain, including the imperial Wier Museum Lambeth's Mark I DA/372 OLF Preis, which has been on public disclaim visions to sait after the end of World Wier You.

	Mk	No	Location	Status
1	Mark I	R5868 S-Sugar	RAF Museum, London, Hendon, UK	Museum display
2	Mark I	W4783 G-for-George	Australian War Memorial, Canberra, ACT, Australia	Museum display
3	Mark X	FM104	Toronto Aerospace Museum, Ontario, Canada	Museum display
4	Mark X	FM136	Aero Space Museum, Calgary, Alberta, Canada	Museum display
5	Mark X	FM159	Nanton Lancaster Society and Air Museum, Nanton, Alberta, Canada	Museum display, engines being brought to running order
6	Mark X	FM212	Windsor, Ontario, Canada	Under restoration
7	Mark X	FM213 (C-GVRA)	Canadian Warplane Heritage Museum, Hamilton, Ontario, Canada	Fully airworthy
В	Mark X	KB839	Greenwood Military Aviation Museum, Nova Scotia, Canada	Museum display
9	Mark X	KB882	St Jacques Airport, Edmundston, New Brunswick, Canada.	Displayed
10	Mark X	KB889	Imperial War Museum, Duxford, Cambridgeshire, UK	Museum display
11	Mark X	KB944	Canada Aviation Museum, Ottawa, Ontario, Canada	Museum display
12	Mark VII	NX611 Just Jane	Lincolnshire Aviation Heritage Centre, East Kirkby, Lincolnshire, UK	Taxilable
13	Mark VII	NX622	RAAF Association Aviation Heritage Museum, Bull Creek, Perth, Western Australia	Museum display
14	Mark VII	NX665	Museum of Transport and Technology, Austin, Auckland, New Zealand	Museum display
15	Mark I	PA474 Phantom of the Ruhr	Battle of Britain Memorial Flight, RAF Coningsby, Lincolnshire, UK	Fully airworthy

Glossary and abbreviations

ADF - Automatic direction finder, a radio receiver that points

to a selected transmitter.

AP - Armour-piercing bomb.

AS - Anti-submarine bomb.

RAe - British Aerospace

BBMF - Battle of Britain Memorial Flight.

Boost – The pressure of the fuel/air mixture in the induction manifold of the engine. Measured in pounds per square inch on the boost gauge in the cockoit, this indicates the power

level delivered by the engine.

CRS - Central Plying School.

SSU - Constants pead unit. This unit, fitted to the engine, automatically controls the engine rpm and the propeller pitch mechanism so that they operate at high efficiency over a wide range of flight conditions. The plict sets the required engine rpm using his control lever, and a governor automatically controls the othor the propeller blades. Thus

the aircraft flies at the most efficient value for the engine power selected and the speed of the aircraft.

DME - Distance measuring equipment; gives the distance to the transmitter.

F700 - Form 700 aircraft logbook.

FE - Far East (as in FE Standard).

GP – General purpose.
 GPS – Global positioning system.

HC - High capacity bomb.

HE - High explosive bomb.

IFR - Instrument flight rules.

IMC - Instrument meteorological conditions.

IP - Initial point.

LC - Low capacity bomb.

LORAN C - Long-range aid to navigation level C.

Mass balance horn - A weight on the flying control surface

that assists in its movement. MC - Medium capacity bomb.

NOTAM - Notice to airmen. Advisory notice giving

information on the establishment, condition or change in any aeronautical facility, service, procedure or hazard.

OC - Officer Commanding.

QFE - Airfield atmospheric pressure reading.

rpm - Revolutions per minute. SAP - Semi-armour-piercing bomb.

SBC - Small bomb container.

SWG - Standard wire gauge.

Taboo arms – Exterior arms on the mid-upper turret, running around a track, that prevent the gunner from shooting off the tailplane.

THUM - Temperature and Humidity Flight.

TOT - Time on target.

Trim tab - A small control surface that, when set, enables the aircraft to fly straight and level without any forces on the

control column. U/C – Undercarriage.

USA bomb - A bomb manufactured in the USA.

VFR - Visual flight rules.

VMC - Visual meteorological conditions.

VOR – Very high frequency omni-directional radio range; a navigation aid.

Useful addresses

Airframe Assemblies

Hangar 6S

Isle of Wight Airport Sandown

Isle of Wight PO36 0JP Tel 01983 408661/404462

Produces replacement airframe and wing components.

Anglia Radiators

Unit 4

Stanley Road Cambridge CB5 8LB

Tel 01223 314444

Builds replacement radiators and oil coolers.

ARCo

Duxford Airfield Cambridgeshire CB2 4QR

Tel 01223 835313 Maintenance on historic aircraft

Classic Aircraft Maintenance Ltd

90 Conduit Rd Stamford

Stamford Lincolnshire PE9 10L

Maintenance on historic aircraft.

Dunlop Tyres

40 Fort Parkway Erdington Birmingham

West Midlands R24 9HI

Hanley Smith 7 South Rd

Templefields Harlow

Essex CM20 2AP

Tel 01279 414446

Overhauls undercarriage legs.

Lincolnshire's Lancaster Association

Lincolnshire's Lancaster Association PO Box 474

Lincoln

LN5 8ZW

Registered charity, supporting the Battle of Britain Memorial Flight.

Ormonde Aircraft I td

Hangar 2 Nottingham Airport

Tollerton Lane

Nottingham NG12 4GA

Produces replacement airframe and wing

components.

Retro Track and Air Unthorne Iron Works

Upthorpe Iron W Upthorpe Lane

Dursley

Gloucestershire GL11 5HP

Tel 01453 545360 Overhauls engines.

Supermarine Aero Engineering Ltd

Mitchell Works Steventon Place

Burslem

Stoke-on-Trent

Staffordshire ST6 4AS Tel 01782 811344

Machine components.

Vintage Fabrics Ltd Boones Farm

Boones Farm Helstead Road

High Garret Braintree

Essex CM7 5PB

Tel 01376 550553 Fabric for the flying controls, rudder

and elevators.

Index

Accelerometer – 66 Aero Space Museum, Calgary, Canada – 155 After take off checks – 98 Alierons – 69 Air Atlantique Classic Flight – 143 Air Historical Branch – 20 Air Ministry specification P.13/36 – 25 Air speed indicator – 66

Air system and brake

gauge - 67

'AirSpace' – 119
Allan, Cilf – 141
Allimeter – 66
Ammo tracking – 45
AP2062A-14 – 92
Armstrong Whitworth
– 18, 33
Artificial horizon – 66
Astrodome – 129
Augsburg raid – 22
Automatic out-out valve
(acov) – 44

Australian Wer Memorial, Canberra, ACT – 131, 155 Awro 683 – 27 Awro Lincoln – 32 Awro Manchester – 27 A. V. Roe & Company Limited – 27

BAE Systems – 147,148
Battle of Berlin – 141
Battle of Berlin – 141
Battle of Britani
Flight – 13
Battle of Britani
Flight – 13
Battle of Britani
Flight – 13
Battle of Britani
Battle of Britan

position – 42 Bomber Command – 8, 20 'Bomber County' (LincoInshire) – 15 Bomb doors – 46, 47 Bomb jettisoning – 118 Bomb loading – 75, 78
Bomb loads – 75, 76, 77
Boost – 31
Boost coil switch – 67
Boost cut-out lever – 65
Boost indicators – 67
Bristol Hercules VI – 33
British Aerospace

Bristol Hercules XVI – 33 British Aerospace (BAe) – 23 Browning 0.303 machinegun – 70, 72, 73 Buckingham Palace – 122

Camshaft – 55 Camshaft auxiliary drive – 55 Canada Aviation Museum, Ottawa, Canada – 155 Canadian Warplane Heritage Museum, Hamiton,

Hamilton,
Canada – 86, 155
Carburettor – 59
Centre of Gravity – 154
Centre section – 43
Chadwick, Roy – 27
Chatterton, Fit Lt,
Mike – 86

Mike – 86 Cheshire, Wg Cdr, Leonard – 102 City of Lincoln – 23 'Clapper' aircraft – 32 Classic Aircraft Maintenance Ltd – 142

College of Aeronautics – 18 Common faults – 137 Compass (P10) – 66 Constant speed unit (CSU) – 58 Constant speed unit

constant speed unit controls – 65 Control column – 65 'Cookie' bornb – 75 Coolant (AL3) – 135 Coolant pump – 58 Cooling system – 63 Co-pilot – 64 Co-pilot's control yoke – 65

yoke – 65 Co-pilot's rudder pedals – 65 Coventry Airport – 144 Cox, Ben – 144 Cranfield, Beds – 18 Crash axe – 117 Crosswind limitation – 154 Cylinder blocks – 55 Cylinder liners – 55

Dam Busters raid – 22 D'Arcy, Wg Cdr, M. A. – 20 Dimensions and weights – 153 Dis (daily)

Dls (daily inspections) – 142 Dinghy – 115 Directional indicator – 66 Display (Lancaster, flying) – 98, 99, 105 Drag stay locking mechanism – 51 Dye penetrant – 138

East Kirkby, Lincs – 81, 82 Edentrical distribution panel – 43 Electrical generator drive – 59 Electrical system – 64 Elevator and rudder control rods – 69 Elevators – 48, 49

Elevators – 48, 49
Elsan tollet – 46
Emergency air blow down
bottles – 44
Engine control
workings – 60, 61
Engine controls – 60, 65
Engine cowlings – 63
Engine kbrication
system – 60
Engine radiator shutter
switches – 67

buttons – 67, 97
Engine start-up drill – 94
Eurofighter Typhoon – 17
Exhaust valves – 55
Extinguisher buttons – 67

F24 camera – 42
'FE' (Far East)
standard – 18
Fins – 46
Fire extinguishers – 115

Fire indication lights – 67 Fire indication test button – 17 First-aid outfit – 117

First-aid outfit – 117
'Fishpond' warning
device – 42
Flaps – 64
Flap indicator – 67
Flap indicator
switch – 67
Flap lank – 44

Flap jack – 44 Flare tube – 46 Flight Engineer – 126 Flight reference card – 127 Flight Refuelling Ltd – 18 Flying controls – 64 Foreign object damage

Foreign object damage (FOD) = 133 Form 700 = 127, 129, 139 F724 = 139 F707A = 139

Fuel (Avgas F18 100LL) = 135 Fuel jettisoning = 117 Fuel master cocks ~ 65 Fuel system = 63 Fuel tanks = 62 Fuselane = 40

Garbett, Mike – 141, 142 Generator housing – 55 Gibson, Wg Cdr, Guy – 102 Glycol – 63 Goulding, Brian – 141, 142

'Grand Slam' – 33 Greenwood Military Aviation Museum, Canada – 155 Griffiths, Gp Capt, Arthur – 13 Group, – 5 31, 142 Gyro compass remote

indicator - 66

H2S equipment – 124 H2S radar dome – 33 Hamilton Standard threebladed metal propellers – 64 Handley Page Halifax – 82 Arthur – 6 Hawarden, North Wales – 18 Hawkins, Frank – 142 Height – 153 Hesketh, Sqn Ldr, Jeff – 119 Hicking, Ian – 84, 85 Historic Aircraft Flight – 10, 13

Harris, ACM, Sir

Historic Aircraft
Flight – 10, 13
Historic Aircraft
Preservation
Society – 82
Hullavington, Wilts – 83
Hydraulic fluid (OM15 –
H515) – 135
Hydraulic system – 64
Hydraulic tank, mid-upper
turnet – 45

identification light Morse switches – 67 Ignition harmess – 55 Ignition system – 59 Imperial War Museum, Dudford – 155 Imperial War Museum, Lambeth, London – 155 Instrument panel – 66, 67, 68 Intercom – 92

Jacking – 133
Jackson, Sgt,
Norman – 102
Jarman, Roy – 85
Johnson, Gp Capt, J. E.
'Johnnie' – 13
Just Jane – 86

Irvine, Bruce - 142

Kaafjord, Norway - 30

Ladder stowage – 46
Lancaster at War – 141
Lancasters
Prototype BT308 27
Second prototype
DG595 – 27
First production
machine
L7527 – 27

MR.3 RF325 - 31 Morton, San Ldr. Propeller reduction Rankin, Gp Capt. Temperature and Mk.X KB726 - 86 lan - 126 gear - 59 James - 13 Humidity Flight - 12 (Preserved examples) Munro, Les - 100 Propellers - 64 Rate of climb Thompson, Fit Sat. Mk.I R5868 Museum of Transport and Public Display indicator - 66 George - 102 S-Sugar - 155 Technology, Auckland, Authorisation Rear turret - 46 Thompson, Wa Cdr. Mk.I W4783 New Zealand - 155 flights - 119 Reconnaissance flare Peter - 10 G-for-George - 155 Mynarski Memorial canister - 45 'Thousand Bomber' Mk.I DV372 Lancaster - 88 R.1155 receiver - 42 Reduction gear - 58 raid - 28 RAAF Association Mynarski, Pit Off, Reeves, Wg Cdr. Throttles - 65 Mk.I PA474 Andrew - 86, 102 Aviation Heritage Colin - 93 'Tiger Force' - 18, 35 Phantom of the Museum, Western Reid, Fit Lt, William - 102 Tirpitz - 29, 30, 31, 32 Nanton Lancaster Society Australia - 155 Robertson, Chief Tech. Tonsberg, Norway - 32 Mk.VII NX611 and Air Museum. Radiator - 63 Colin - 144 Toronto Aerospace .lust .lane - 155 Canada - 155 Radio operator's Rolls-Royce Merlin - 27 Museum, Canada - 55 Mk.VII NX622 - 155 Navigator - 119 station - 42 Merlin 25 - 55, 56, 57 Trim - 64 RAF (Royal Air Mk VII NX665 - 155 Navigator's station - 125 225 - 55Tromsø - 30 Mk.VII NX664 - 155 NDT (non-destructive Force) - 8 500 - 55 Turn and slip Mk.X FM104 - 155 testing) - 138 RAF Museum London, indicator - 66 Mk.X FM136 - 155 Nettleton, San Ldr. Hendon - 155 Vulture - 27 Turret system Mk.X FM159 - 155 J. D. - 102 RAF stations Royal Canadian Air recurerator - 45 Mk.X FM212 - 155 New Zealand - 100 Bardney, Lincs - 142 Force - 10 Turrets - 70 MKX FM213 Nimrod Integrated Project Benson, Oxfon - 18 Boyal Tournament - 13 FN5 nose - 70, 71 (C-GVRA) - 155 Team - 142 Biggin Hill, RPM indicators - 67 FN50 mid-upper Mk.X KB839 - 155 NOTAM (notices to Kent - 10, 83 Budder - 48, 69 -70.71 Mk.X KB882 - 155 airmen) - 122 Bottesford, Lincs - 141 FN121 rear - 72, 73 Mk.X KB889 - 155 Coltishall, Norfolk - 14 Schofield, Don - 87, 88 Martin 250CF 23A Mk.X KB944 - 155 Oil (OM270 - Aeroshell School of Maritime Coningsby. mid-upper Lancaster types 100) - 64, 135 Lincs - 15, 149 Reconnaissance - 32 turret - 35 ASR III (air-sea Oil control valve - 55 Dipdord Cambs - 13 Servicing - 134 Type 484 rescue) - 35 Oil system - 63 Henlow, Beds - 20 Annual - 136 Provisionina - 34 B.I - 33 Operation 'Chastise' - 29 Horsham St Faith Minor - 137 B.I (Special) - 33 Operation Norfolk - 14 Major - 137 Undercarriage - 50 'Catechism' - 31 Lossiemouth. Shackle plate - 50 Undercarriage Operation 'Exodus' - 32 Scotland - 30 Skin repair - 50 indicator - 66 B.III (Special) - 34 Operation 'Manna' - 32 Martlesham Heath. Sorpe Dam - 29 'Unkeen' - 29, 34 Mk.VI - 35 Operation 'Obviate' - 31 Suffolk - 14 Sowden, San Ldr. Mk.VII - 35 Operation North Weeld. E. H. - 13 Vacuum indicator - 67 Mk.X - 35 'Paravane' - 30 Fesex - 14 Spark plugs - 60 Vacuum system Mk.X conversion Scampton, Lines - 83 Sprayavia - 145 changeover roles - 35 Packard Merlin - 34 St Athan, Wales - 143 Squires Gate, Blackpool, MR.III/GR.III Palmer, Son Ldr. St Mawgan. Lancs - 83 VFR (visual flight (maritime Robert - 102 Comwall - 31 St. Jacques Airport. nules) - 121 reconnaissance) - 35 Panton, Pit Off, Waddington, Lincs Edmundston. VHF radio - 67 PR.I (photo Christopher - 82 - 15, 20, 21 Canada - 155 Vickers-Stalling - 154 Armstrong - 15, 18 Lavenham, Suffolk - 83 Panton, Harold - 82 Norfolk - 14 Starting Victoria Cross - 22, 87 Leckey, Flt Lt. Mike - 81 Parachute escape Wickenby, Lincs - 141 checks - 93 94 Length - 153 hatch - 42 Woodvale, Lancs - 12 Straw, Flt Lt. Ed - 98-9. Wallis, Sir Barnes - 29 Lifford, Rt Hon, Lord - 84 Phantom of the Wyton, Cambs Wells, Stan - 141 Lincolnshire Aviation Ruhr - 126 RAF Squadrons Supercharger - 59 Westminster Abbey - 13 Heritage Centre - 155 Photo flash canisters - 45 9 - 29 30 31 Swales Cant. Lubricating oil Pilot - 64 44 (Rhodesia) - 20, 28 Edwin - 102 assembly - 58 (OM150) - 135 Pilot's control yoke - 65 49 - 32 Swedish Air Force - 32 Windsor, Ontario, Canada Pilot's rudder pedals - 65 Magneto - 55 Pilot's seat - 43 82 - 18, 20 T.1154 transmitter - 42 Wing span - 153 Magneto switches - 66 100 - 149Taboo arms - 71 Wing spar, rear - 44 Mainplane - 49, 50 Pneumatic system - 64 433 (RCAF) - 82 Tail unit - 46, 47 Wings - 49 Mass balance horns - 48 Pre-display 460 (RAAF) - 131 Tail wheel - 51 World War Two - 7 Melrose, Flt Lt. J. D. - 30 checks - 98 467 (RAAF) - 141 Tailplanes - 46 Mickey the Moocher - 145 Pre-flight checks - 92 550 - 149Take-off checks - 98 X-ray - 13 Mid-upper turret - 70 Pre-start checks - 94 617 - 28, 29, 30, 31 'Tallboy' - 29, 31, 32 Möhne Dam. Propeller feathering 626 - 141 Tarrant Rushton Yagodnik, Soviet Germany - 29, 102 630 - 85 Union - 30



Jarrod Cotter)

This book has hopefully given the reader an insight into the maintenance and flying of the sole remaining RAF Lancaster. But we must remember that all you have seen and read about is a commemoration of the more than 55,000 Bomber Command aircrew who never came home from operations. This is reflected on a plaque positioned just aft of PA474's main entrance. Each time the crew enter and leave the aircraft they pass the Bomber Command crest and the simple but extremely meaningful words:

AVRO LANCASTER



OFFICIAL PRODUCT

1941 onwards (all marks)







T believe that the Lancaster was the greatest single factor in winning the war, said Air Chief Marshal Sr Arthur Harris, wartime commander of RAF Bomber Command. During the Second World War, RAF Lancaster bombers

During the Second World War, RAF Lancaster bombers took the war into the very heart of Hitler's Third Reich, pounding its cities and industrial centres with more than 600,000 tons of bombs.

Lancissters flew some of the most daring bomber operations of the war including the intredict daylight statick on the MAN diesel engine factory in Bavaria in 1942; the legendary dams raid in 1943, and the attacks on the German battleship Tripotz-in 1944.

Surprisingly, of the 7,377 Lancasters built only two survive today in an airworthy condition – one in Britain, the other in Canada.

Produced with the full cooperation of the RAFs Battle of Britain Memorial Flight, the Haynes Arro Lancaster Manual gives a rare and fascinating insight into how the Lancaster is constructed, how it is flown and operated, and the all-important details of how it is serviced and maintained to keep it airvorthy.

Jarrod Cotter is one of the lucky few to have flown in both of the envority Luciacetes. Before his apportment as Deputy Editor of FyPast magazine, Jarrod served for rine years in the PAF. He saw service in the Lik and with PAF Cemmary as an NCO, working on Jaguars and Harriers. He is the author of Ling Lancesters (2005) and Battle of Britain Memorial Flight: 50 Years of FyIng (2007).

Paul Blackah is one of the smalt band of experts who keep the RPS Lancaset hing. He joined He RPI in 1978 and was posted to the Battis of Britan Memorial Flight in 1960 where he remained until his retrievant from the litter service in 2002 as a Chef Technician. Paul's specialised knowledge of virtage aircraft saw him en engaged as an RPI reservist. working as an affairm sepocialist in the RBM. Paul is co-author with Afferd Phora of Supermariae Spiffer Memorial (2007).

UPC CODE



Haynes Publishing
Sparkford, Yeovil, Somerset BA22 7JJ, UK
Tel: 01963 442030 • Fax: 01963 444001
Int. tel: +44 1963 442030 • Int. fax: +44 1963 440001
E-mail: sales@haynes.co.uk • Website: www.haynes.co.uk